

# Kit Installation Instructions

XOG SPAR Team

Product(s):	EX 550/560	Date:	2/2012
Title:	1.1sp1 Installation Instructions	Page:	1 of 1

## Purpose

This software kit provides an EX550/560 software update in response to an EX550/560 SPAR. Refer to the included customer letter for more information.

In the event of an EX550/560 system reinstall this software patch should be reapplied.

## Kit Contents

Qty.	Description
1	Kit Installation Instructions
1	Customer Letter
1	SP1.exe

## Prerequisites

- Previous working knowledge with the EX550/560
- 1.1

## Installation Instructions

**NOTE:** This software may be installed by the customer.

### Install the EX550/560 sp1.exe patch:

- \_\_ 1. Install the **sp1** patch
  - \_\_ a. Double click on sp1.exe file
  - \_\_ b. At the Fiery Patch Download window, click [Next]
  - \_\_ c. At the License Agreement window, click [Accept]
  - \_\_ d. At the Fiery Logon window, type the Fiery administrator login password in the Password field
 

**NOTE:** Do NOT change the User field; that value must be admin.
  - \_\_ e. In the Hostname field, type in the IP address or hostname of the EX550/560 and select [Connect]
  - \_\_ f. At the Server Information window, select [Download]. The patch will be downloaded and installed
  - \_\_ g. At the Processing window, select [Next], wait for approximately one (1) minute
  - \_\_ h. On the final window, select [Reboot], then select [Finish]

**NOTE:** The patch will not be installed until the EX550-560 is rebooted.

- \_\_ 2. Verify that the patch is installed and wrap-up
  - \_\_ a. Once the Fiery status says "Idle," select [Server: Print Pages] from the CWS menu and print a configuration page.
  - \_\_ b. On the "System Update Log" sheet of the configuration pages, ensure that the patch sp1 is listed

**NOTE:** When executing **sp1.exe**, if you choose **Restart later** when prompted by the Fiery Patch Downloader, please make sure you manually reboot the server for changes to take effect.

**NOTE:** There is a uninstaller for sp1. Just double click on the uninstall\_sp.exe and follow the instruction to remove sp1.