

Fiery Patch Release Notes

General information

Defect ID number	Service Pack Uninstaller
Product name	Fiery Controller for Xerox Color 550/560 v1.1
Release date	3 February 2012

Files included in this release

File name	File size
uninstall_sp.exe	1.10 MB

Issue(s) addressed with this release

- Service Pack Uninstaller

Steps to reproduce the Issue(s)

1. None

Before installing uninstall_sp.exe



- 1 If this patch is exclusive, it must be installed by itself, and the server must be rebooted or restarted once. After that, other patches can be applied to the server.
- 2 If any prerequisites listed below, they must be installed in the order specified before applying the **uninstall_sp.exe** patch:
 - **SP1**
- 3 If any known issues listed below, read before installing **uninstall_sp.exe** patch:
 - This patch will only uninstall the Service Pack. If there are any SPAR release patches installed after Service Pack 1, the uninstaller patch will not uninstall Service Pack 1.

Patch installation instruction

- 1 Make sure the Fiery is idle.
- 2 Execute **uninstall_sp.exe** and follow the instructions in the Fiery Patch Downloader.
- 3 Notes about the Fiery Patch Downloader



- a. Login must be admin. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password.
 - c. Hostname can be either the IP address or the Fiery server name.
- 4 After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot.
 - 5 Wait until the Fiery comes to Idle and print the configuration page.
 - 6 Verify that the System Update Log **does not** contain the patch number **SP1**.