

Release Note

General information	
Issue ID Number	1-OV7CE
Product Name	Fiery EXP250 v1.01 & 1.1 English
Issue Date	August 25, 2006

Files included in this release	
File name	File size
hf_2.1.0.40.zip	89.1 MB
1-OV7CE_relnotes.doc	

Issue(s) addressed with this release

When downloading files via Hot Folders, the job are intermittently corrupted

Steps to reproduce

Application: Hotfolder 2.1.0.30

- 1) Configure Hotfolders properties as follows:
 - a) Select Filter Settings and choose TIFF/IT to Postscript (Exclusive) filter
 - b) Select Job settings and choose
 - i) Page Size = A3 SEF
 - j) Combine Separations = On
- 2) Copy customer files to HotFolder
- 3) Go to Command Workstation and perform a Process and Hold on the download jobs
- 4) Repeat step 3 several times

Result: The downloaded job will move to the Printed Queue with a PS-error when the previous jobs did not get the same error

Prerequisite(s)

None

Installation instructions

- 1) Click on Start button
- 2) Select Settings->Control Panel
- 3) Select Add/Remove Programs
- 4) Select EFI Hotfolder and click "remove"
- 5) Reboot client
- 6) Install Hot Folders 2.1.0.40 by double clicking on Setup.exe.

Known Issues

None