

***Imported Files Print Uncollated  
XP12 1.1 SP1***

**Problems Addressed:**

When downloading a pdf file, the output is not longer collated. (Xerox SPAR # 034894875 & # 610075142, EFI Bug # 1-B4AZH)

**Solution:**

Download the enclosed 1-B4AZH.ps to the Fiery.

This update consists of the following file:

| File Name  | File Size |
|------------|-----------|
| 1-B4AZH.ps | 106 KB    |

**Important Note:**

This patch requires and was tested with composite patch 1-8C6Z7 pre-installed.

**Installation Instructions:**

1. Download 1-B4AZH.ps file via the Fiery Downloader or Web Downloader to the Direct Connection.  
Note: Downloading via Command WorkStation, refer to the Job Management Guide, Page 4-26  
Downloading via Fiery Downloader, refer to the Printing Guide, Chapter 5  
Setting up Fiery WebTools to use Fiery WebDownloader, refer to the Getting Started Guide, Page 83.  
Using Fiery WebDownloader, refer to Printing Guide, Page 1-10 (for PC) and Page 2-6 (for Mac OS)
2. After the system returns to "Idle", wait 60 seconds.
3. Reboot the Fiery server from the Fiery Control Panel.
4. After the server has restarted, please wait until it goes to idle and print a Configuration Page to verify that the file has been received. The Update Information should contain the patch number 1-B4AZH.ps.