

Release Note

General information	
Issue ID Number	1-JZGN9
Product Name	Fiery EX12 Color Server PS 2.0SP2
Issue Date	22 September 2005

Files included in this release	
File name	File size
1-JZGN9.ps	303 Kilobytes
1-JZGN9_relnotes.doc	

Issue(s) addressed with this release

SPAR 931477420 / Job does not stop printing when stacker is full. Job will continue to print to the Top Tray.

Steps to reproduce

1. Attach finisher to DC12.
2. Import customer file "Finance V2 en course.pdf" to Hold Queue.
3. Check for job properties: Duplex Top-Top, Finishing destination Stacker, Grayscale, 8 copies.
4. Observe that when stacker is full, the DC12 doesn't stop printing and will continue to print in the top tray.

Installation instructions

1. Download/Import the patch file "1-JZGN9.ps" with Command Workstation to the "Direct" queue.
2. You must wait at least 60 seconds after the patch file downloaded/imported before rebooting the system. This will ensure the patch file is completely processed.
3. The system must be rebooted twice for the patch to be effective.
4. Please select "Shut Down" and then "Reboot System" on the Fiery LCD. When the Fiery has come to "Idle", repeat the steps to reboot the system.
5. Please wait until the Fiery has come to idle after the second reboot to print out the configuration page.

Verify the **Update Info** section. It should contain the patch number "1-JZGN9".

Prerequisite(s)

None.

Known Issues

None.