

***Application Define and Combine Separations w/ Newsprint
EX12 2.0***

Problems Addressed:

1. When printing an image with Application Defined in the Halftone selection will cause corrupted output. (Xerox SPAR # 836705683, EFI Bug # 1-8IY9I).
2. Selecting Newsprint in Halftone selection and Combine Separations at the same time will crash the EX12. (EFI Bug #1-7E21J).

Solution:

Download the enclosed 1-7E21J.ps to the Fiery.

This update consists of the following file:

File Name	File Size
1-7E21J.ps	10.4 MB

Installation Instructions:

1. Download 1-7E21J.ps file via the Fiery Downloader or Web Downloader to the Print queue or if using the import function of CWS 4.x, import to the Hold queue, then print.
2. In Command Workstation/Spooler (web), verify that 1-7E21J.ps is in the printed queue.
3. Wait 60 seconds.
4. Reboot the Fiery server from the Fiery Control Panel.
5. After the server has restarted, please wait until it goes to idle and print a Configuration Page to verify that the file has been received. The Update Information should contain the patch number 1-7E21J.ps.

Important Note:

This patch requires and was tested with composite patch 1-7QU5B pre-installed.