

***Freeform, Yellow Printing, Duplexing, & Pantone Gradients
XP12 1.1 SP1***

Problems Addressed:

1. After upgrading to XP12 1.1 SP1, FreeForm functionality on Non-FACI systems was lost. (Xerox SPAR # 751816204, EFI Bug # 1-7Z98D)
2. After a large number of prints, the XP12 abruptly starts printing all jobs as a single yellow separation. (EFI Bug # 1-7SN1D)
3. While server defaults are Face Up, Reverse order printing:
 - a. When printing a 2 page duplex job to the Fiery EX12, will receive page 2 on both sides
 - b. When printing a 4-page duplex job, the Fiery EX12 will toggle between Idle & Printing, which results in the Fiery server hanging. (Xerox SPAR # 420864405 & 580231590, EFI Bug # 1-8C0L5)
4. Blends of certain Pantone colors in Quark Xpress print black only. (Xerox SPAR # 254331786 & 808985764, EFI Bug # 1-8C0LD)

Solution:

Download the enclosed 1-8C6Z7.ps file to the Fiery Server.

This update consists of the following file:

File Name	File Size
1-8C6Z7.ps	40.6 MB

Installation Instructions:

1. Download 1-8C6Z7.ps file via the Fiery Downloader, Web Downloader to the Print Queue or use the import function of CWS 4.x to import to the Hold queue, then print it.
2. In Command Workstation/Spooler (web), verify that 1-8C6Z7.ps is in the printed queue.
3. Wait 60 seconds.
4. Select Reboot from the Fiery Control Panel.
5. After the server has restarted, please wait until it goes to idle and print a Configuration Page to verify that the file has been received. The Update Information should contain the patch number 1-8C6Z7.ps.