

***Windows 2000 Drivers
Fiery XJ+325 3.2***

Problem:

Unable to print to the Fiery XJ+325 Print Server on the Windows 2000 operating system with currently supplied drivers.

Solution:

Install the printer using the included driver files listed below.

These drivers are considered final release. This means that these drivers have been released as is. Validation was performed and all issues found are listed below. Further testing will not be conducted nor supported.

This update consists of the following (2) files for each language:

File Name	File Size
Efxjx203.ppd	41.6 KB
Efxjx303.ppd	41.5 KB
Efxjx503.ppd	71.8 KB
Efxjx703.ppd	44.8 KB
Oemsetup.inf	3.7 KB

Installation Instructions:

1. Go to **Start/Settings/Printers** and double-click on **Add Printer**
2. Follow the On-screen instructions

Note: When installing the printer driver, you will be asked for additional files. These files will be found on the Windows 2000 CD.

Known Issues:

1. Job Notes are not supported.
2. Custom Paper sizes are not supported

Fiery Utilities are not supported on the Windows 2000 operating system.