

# Kit Installation Instructions

XOG SPAR Team

Product(s):	CX250_v1.1_SP2 for DocuColor 240/250	Date:	06/13/08
Title:	Patch_Custom2Booklet Installation instructions	Page:	1 of 1

## Purpose

This software kit provides a CX250\_v1.1\_SP2 software update in response to a CX250 SPAR. Refer to the included customer letter for more information.

In the event of a CX250 system reinstall this software should be reapplied.

## Kit Contents

Qty.	Description
1	Kit Installation Instructions
1	Customer Letter
1	Patch_Custom2Booklet.zip

## Prerequisites

- Previous working knowledge with CX250\_v1.1\_SP2.
- The CX250 must be at version **1.1\_SP2** prior to performing this install. This software is supplemental to the version **1.1\_SP2** launch software.

## Installation Instructions

**NOTE:** This software may be installed by the customer.

- \_\_\_ 1. Exit the Spire application.
- \_\_\_ 2. Extract **Patch\_Custom2Booklet.zip** to the CX250 Windows desktop.
- \_\_\_ 3. Open the **Patch\_Custom2Booklet** folder.
- \_\_\_ 4. Double-click on the **Install.exe** file. Follow the onscreen instructions. Click **Finish** to exit the installation wizard.
- \_\_\_ 5. Restart the system by clicking **Start > Shutdown > Restart**.
- \_\_\_ 6. After the system restarts, the Spire CX260 software will launch automatically.
- \_\_\_ 7. To verify that the patch was successfully installed, go to the **Help** menu, select **About**, and confirm that **Custom2Booklet** is listed next to **Updates**.

## Uninstallation Instructions

- \_\_\_ 1. Exit the Spire application.
- \_\_\_ 2. Extract **Patch\_Custom2Booklet.zip** to the CX250 Windows desktop.
- \_\_\_ 3. Open the **Patch\_Custom2Booklet** folder.
- \_\_\_ 4. Double-click on the **Uninstall.exe** file. Follow the onscreen instructions.
- \_\_\_ 5. Launch the Spire application and open **Help > About** to confirm that the patch was uninstalled successfully.