

## Patch Installation Instructions

L3 Support Team

Product(s):	Xerox EX 180 Print Server Powered by Fiery	Date:	July 2020
Title:	FIT102104247.exe Installation Instructions	Page:	1 of 2

### Purpose

This Fiery EX 180 software patch is being provided to enable the Fiery print server to use the optional Xerox Adaptive CMYK Plus features.

- For Color managed Preview, please use latest Command WorkStation 6.4 from EFI download center.

Only customers who have the Xerox Adaptive CMYK Plus kit should install this patch.

### Kit Contents

Qty.	Description
1	Patch Installation Instructions
1	Customer User Addendum
1	FIT102104247.exe patch
1	uninstall_win_v1.exe

### Prerequisites

- Previous working knowledge of the Fiery EX 180 system.
- The Fiery EX 180 software must have **version 1.2** installed prior to installing this patch.
- The following prerequisite (s) must be installed before installing this patch. Prerequisite patches are obtained via EFI Auto Updates, System Updates, or by contacting our Xerox L2 Support teams.

- FIT102105428

### Important Information for FIT102104247

- Image viewer shows separation name as Cyan, Magenta, Yellow, and Black while Vivid\_kit/Fluo\_Kit workflow is in use.
- If you observe blank output when processing few files with Vivid\_kit preset and APPE enabled, please enable 'Separate RGB/Lab to CMYK source' from Job Properties/Color Tab/Color Settings.
- Printing of files with CMYK Plus colors is supported only through Command WorkStation and not through Fiery drivers.

### Installation Instructions

**Note:** The customer or a member of the Xerox Service Team may install this software.

**Note:** This patch is exclusive, it must be installed by itself, and the server must be rebooted or restarted once. After that, other patches may be installed on the server.

- \_\_\_ 1. The Fiery controller must be **Idle**.
- \_\_\_ 2. Execute the file FIT102104247.exe and follow the instructions in the Fiery Patch Downloader.
- \_\_\_ 3. Notes about the Fiery Patch Downloader
  - \_\_\_ a. Logon must be admin. This is fixed and cannot be modified.
  - \_\_\_ b. Password is the Fiery administrator login password.
  - \_\_\_ c. Hostname can be the IP address or the Fiery server name.
- \_\_\_ 4. After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot.
- \_\_\_ 5. Wait until the Fiery has come to Idle and print out the Configuration page.
- \_\_\_ 6. Verify the **Update Info** section of the Configuration page. It should contain the patch number FIT102104247.

### Uninstall Instructions

**Note:** The Uninstall patch will only uninstall FIT102104247.

- \_\_\_ 1. The Fiery controller must be **Idle**.
- \_\_\_ 2. Execute the uninstall\_win\_v1.exe file and follow the instructions in the Fiery Patch Downloader.
- \_\_\_ 3. Notes about the Fiery Patch Downloader

	Date: July 2020	Page: 2 of 2
--	--------------------	-----------------

- \_\_\_ a. Logon must be admin. This is fixed and cannot be modified.
- \_\_\_ b. Password is the Fiery administrator login password.
- \_\_\_ c. Hostname can be the IP address or the Fiery server name.
- \_\_\_ 4. After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot.
- \_\_\_ 5. Wait until the Fiery has come to Idle and print out the Configuration page.
- \_\_\_ 6. Verify that FIT102104247 is no longer on the Configuration page.