

JULY 2021

Xerox® AltaLink®  
C8100 & Xerox®  
AltaLink® B8100  
Series  
Multifunction  
Printers Release  
Version  
113.xxx.011.17810

General Release Notes



## General Release Notes

This version is based on the content and features that were present in version 111.xxx.000.27020, which was released in January 2021. [Pre-Patch v539237v6](#) is required before upgrading to this release.

## Software Release Version

| XEROX® PRODUCT               | SOFTWARE VERSION  | LINK TO SOFTWARE ZIP FILES            |
|------------------------------|-------------------|---------------------------------------|
| Xerox® AltaLink® C8130/C8135 | 113.009.011.17810 | <a href="#">Altalink® C8130/C8135</a> |
| Xerox® AltaLink® C8145/C8155 | 113.010.011.17810 | <a href="#">Altalink® C8145/C8155</a> |
| Xerox® AltaLink® C8170       | 113.011.011.17810 | <a href="#">Altalink® C8170</a>       |
| Xerox® AltaLink® B8145/B8155 | 113.013.011.17810 | <a href="#">Altalink® B8145/B8155</a> |
| Xerox® AltaLink® B8170       | 113.014.011.17810 | <a href="#">Altalink® B8170</a>       |

**Note:** Find your Xerox® Device in the left column. Devices that are enabled for remote software downloads to receive the latest security and software enhancements will upgrade automatically to the latest software release. These software updates will be done automatically at 9:00 PM local time by default. If you have questions about your Xerox® Device software version, contact Xerox Technical Customer Support.

This firmware release contains the following improvements to previous software version:

- Adaptive learning.
- Add support for TLS 1.3 for improved security with an option to select TLS 1.3 Only.

Note: Not all applications support TLS 1.3 yet. To avoid problems, such as failure to login, it is advised that you verify all your applications support TLS 1.3 before selecting the TLS 1.3 Only option.

- Enabled Configurable Disk Overwrite for HDD for improved security.
- New screen saver.
- Ability to enable/Disable offset in finishers.
- Touch screen screenshots.
- XMPie APP is now pre-installed on all AltaLink® MFPs
- Remote SNMP v3 Credential Management.
- Cloud based Remote management.
- Ability to disable Service Representative/Diagnostic User account for improved security.
- Customize the supported Smart cards list .
- Support for Single sign-on for One Drive and O365 App Gallery App.

- Regional time zone fix for Mexico City.
- Improved Image quality when using touchless copy app.
- Provide support for SMBv1 when using Win 2003 server.
- Scan to email fix for gmail.com relay server.
- Fix for "XSA login failure" error message when using Equitrac 5.6.
- With proximity sensor enabled, system settings will now reset correctly when the user walks away from the device.
- IPSEC password length changed from 1 character to 14 characters'.

**Note:** Reference System Administrator Guide for more information.