

Product Readme Xerox B215/B205/B210 General Release

Release Date: August 15, 2019
Updated May 13, 2020

dc19rn3877

Device Software Release Details

Products	System Software	Main Controller Board (MCB)	Image Output Terminal (IOT)	Network Controller
B215	88.000.60.000	3.50.01.60_20190916	1.00.32_190308	4.00.50
B205	85.000.58.000	3.50.01.58_20190718	1.00.32_190308	4.00.50
B210	80.000.58.000	3.50.01.58_20190718	1.00.32_190308	4.00.50

I. Fixes/Features new in this release

- **B215 only: Fixed intermittent device reboot at power up or wake up from deep sleep.**
- Changed default Banner page to OFF
- Device no longer rebooted after receiving a print job via PS driver
- Fixed 2up/4up Copy Job Scan Motor when scanning pages

II. Installation Notes

Standard Installation instructions are associated with the firmware download location.