

# Product Readme Document

## Xerox B215/B205/B210 General Release

### 88.000.64.000 & xx.000.60.000

Release Date: October 23, 2020

dc20rn3979

## Device Software Release Details

Products	System Software	Main Controller Board (MCB)	Image Output Terminal (IOT)	Network Controller
<a href="#">B215</a>	88.000.64.000	3.50.01.64_20200715	1.00.32_190308	4.00.50
<a href="#">B205</a>	85.000.60.000	3.50.01.60_20200715	1.00.32_190308	4.00.50
<a href="#">B210</a>	80.000.60.000	3.50.01.60_20200715	1.00.32_190308	4.00.50

## I. Fixes/Features new in this release

- In this release, association Response buffer size was increased to accommodate ipTime routers and others. Prior to this fix attempts to connect wirelessly to these routers would fail.

## II. Installation Notes

Standard Installation instructions are located within the firmware zip file.

**Note: Once the above firmware is loaded into the device, you cannot downgrade the device to previous firmware versions. This is per design.**