

EFI Fiery™ for the Xerox® EX-i C60/C70 Color Server

PostScript patch release note



Overview

This checklist will help you prepare for the installation of **FIT101661010.ps**.

General Information	
○ Current Version	2.0_SP2
○ Defect ID	FIT101661010.ps
○ Release Date	19-May-2017
○ Files included	FIT101661010.ps
○ File size	61142848 bytes
○ Checksum	

Issue(s) addressed with this release

- Apache version is upgraded to 2.2.31
- PHP version is upgraded to 5.6.27
- OpenSSL version is upgraded to 1.0.2J
- Samba version is upgraded to 4.4.6
- Samba client version is upgraded to 4.1.15

IMPORTANT

Before installing FIT101661010.ps

- Known issues listed below, read before installing FIT101661010.ps patch:
 - None.
- The following prerequisite(s) must be installed in the order specified before applying the **FIT101661010.ps** patch:
 - SP1
 - SP2_FIT101687996
 - FIT101692002
- Do NOT install any of the following patch(es) after installing the **FIT101661010.ps** patch. If you must install any of the patch(es) below, do so before installing the **FIT101661010.ps** patch:
 - None.
- This patch is exclusive, it must be installed by itself, and the server must be rebooted or restarted once. After that, other patches can be applied to the server.

Disclaimer

This hardware, software/patches, or technology may contain cryptographic functions as defined in Article 8 (ix) (h) because the cryptographic capability is not user-accessible, and are designed to have only one or more of the following cryptographic functionality(ies):

1. Functionality to execute copy-protected programs
2. Functionality to access to digital contents stored on copy-protected read-only media
3. Functionality to access to encrypted and memorized digital contents on a medium that will be sold to the public with the same content
4. Functionality for copying control of copyright protected audio/video data
5. Functionality to encrypt and/or decrypt to protect libraries, design attributes, or associated data for the design of semiconductor devices or integrated circuits

EFI Fiery™ for the Xerox® EX-i C60/C70 Color Server

PostScript patch release note



Patch installation instructions

1. Make sure that the Fiery controller has reached Idle.
2. Import the patch file **FIT101661010.ps** using Command WorkStation to the Direct connection.
3. You must wait until the file finishes processing and Command WorkStation or the LCD show Idle.
4. From Command WorkStation, choose Server, Reboot Server, or from the Fiery LCD, select Shut down, Reboot System.
5. Wait until the Fiery controller reaches Idle and print the configuration page.
6. Verify that the Update Info section contains the patch number **FIT101661010**.

Disclaimer

This hardware, software/patches, or technology may contain cryptographic functions as defined in Article 8 (ix) (h) because the cryptographic capability is not user-accessible, and are designed to have only one or more of the following cryptographic functionality(ies):

1. Functionality to execute copy-protected programs
2. Functionality to access to digital contents stored on copy-protected read-only media
3. Functionality to access to encrypted and memorized digital contents on a medium that will be sold to the public with the same content
4. Functionality for copying control of copyright protected audio/video data
5. Functionality to encrypt and/or decrypt to protect libraries, design attributes, or associated data for the design of semiconductor devices or integrated circuits