

March 2013

Dear Xerox DocuColor 242/252/260 Integrated Fiery Color Server customer:

Your DocuColor 242/252/260 Integrated Fiery Color Server can now be upgraded with the 1-1J9XON software patch.

**NOTE:** *Your system must be at version 2.0 prior to installing this software.*

We tested this software patch specifically for the System Problem Action Requests (SPARs) noted below. If your SPAR number is not listed, we are providing you this software either because you reported a problem that resembles one of the listed fixes or because our testing has shown that this software should resolve your problem. If this software does not resolve your problem, please contact the hotline and provide a detailed job scenario and sample job(s) for further investigation, testing, and resolution.

This software patch contains fixes for the following SPARs:

SPAR #	Description
1. 821280273	Network SMB scanning to windows 2012 server generates o byte files.
2. 339268797	Scan to SMB will not work on Mac os 10.7 and 10.8 server client

**Prerequisites:**

- PRODID
- 1-U8E58
- 1-18SMZM
- 1-1E21N4
- 1-13LK3J
- 1-19AZVM
- 1-1CNL1W
- 1-1H1YIQ
- 1-1FLFQA
- 1-1IJ6ZK