

# Product Enhancement Document

## PrimeLink C9065/9070 Firmware v85.6.11

Release Date: August 09,2021

dc21rn4036

### Software Release Details

System Software	Version
System	85.6.11
Controller ROM	1.1.12
IOT ROM	4.91.0
C Finisher	6.4.0
UI Panel Software	10.18.4
Link to Software	<a href="#">C9065/C9070</a>

### Contents

#### Firmware 85.6.11 (August 2021)

- New scanner CCD/CIS has been added to support new hardware

#### Firmware 85.6.3 (December 2020)

- Improvements to reduce DADF Feed Jam 005-141 when scanning larger number of originals. If excessive jamming still occurs after installing this release, contact Xerox Technical Support.

#### Firmware 85.5.93 (October 2020)

- Scan to Home is now successful when scanning to a Microsoft DFS and using Smartcard Authentication

#### Firmware 85.5.83 (September 2020)

- Scan to Home is now successful when scanning to a NetApp Filer/Appliance and using CAC/PIV/Smartcard Authentication  
Caveat: Scan to Home to Microsoft DFS fails with Smartcard Authentication

#### Firmware 85.5.53 (August 2020)

- EIP SNMP Web Service Improvement:  
Enabling only SNMP v3 on the device no longer impacts the use of the EIP SNMP Web Service  
Caveat: When using the EIP SNMP Client to write data, the SNMP v1/2 SNMP Set Community Strings must be the same on the printer and within the EIP SNMP Client otherwise an SNMP Timeout error will occur.

#### Firmware 85.5.41(October 2020)

- This firmware includes the addition of supporting new Finishing modules that are compliant with the IEC 63628 regulations. These regulations go into effect in 2021.

(The new Software is also backward compatible with the current Finishing equipment.)

- Added support for eWire & Tape Binder finishing.
- CMYK+ Enhancements for Adaptive CMYK+ Vivid Process Process Controls

## Firmware 85.5.31 (July 2020)

- By default, when a scan to email job is sent from PrimeLink C9065/C9070, the recipients email address gets cleared out. In the event the customer workflow would benefit by having the email address retained, the following SFR key should be applied.

Product	Enablement Key	Disablement Key
PrimeLink C9065/C9070	*1035149891	*1035149890

- Fixed an issue that allows the device to connect to the remote services when an expired certificate and a valid certificate is present.
- The Printer is displaying the correct login site when connected to Xerox App Gallery
- 19209 IOT needs to communicate Community Names and IP address to the DFE to fix 127-210 faults issues
- Added Image Orientation for Server Fax
- Modernized CAC Card Support with CAC/PIV Rollover
- This release provides the ability to search through all certificates on the card and attempt authentication with each valid certificate that supports smartcard login before communicating failure to the end-user.
- The plugin provides support for new Common Access Cards with reduced / realigned certificate profiles including:
  - a. A single certificate for each major PKI function: PIV-Auth for authentication, Signature for email and document signing, and Encryption for encryption.
- Addition of an asymmetric card authentication certificate (aCAK) for physical security.
- Elimination of the Identity certificate present on previous versions of the CAC card.

The following cards/tokens are now supported:

- Giesecke + Devrient Mobile Security FIPS201 SmartCafe Expert 7.0 with HID Global ActivID Applet v2.7.5  
ATR: 3b f9 18 00 00 00 53 43 45 37 20 03 00 20 46
- Gemalto TOP DL V2.1 128K with HID Global ActivID Applet v2.7.4  
ATR: 3B 7D 96 00 00 80 31 80 65 B0 75 49 17 0F 83 00 90 00

## Installation Instructions

This file contains machine firmware and installation instructions. Unzip then download before attempting to install the firmware.

- [Link to Third Party Disclosure file](#)

© 2021 Xerox Corporation. All rights reserved. Xerox®, and PrimeLink® are trademarks of Xerox Corporation in the United States and/or other countries. BR22773 Other company trademarks are also acknowledged. Document Version: 1.0 (January 2021).