

Product Enhancement Document

PrimeLink C9265/C9275/C9281 SPAR

Firmware v86.03.53

Release Date: March 12th, 2025

dc25rn1118

Software Release Details

Software	Version
System	86.03.53
Controller ROM	1.0.100
IOT	80.9.0
PF2.0 HCF	13.1.0
PF3.1 HCF	50.17.0
PF3.2 HCF	24.136.0
Finisher GC	3.5.0
Finisher D	16.62.0
ADF	1.45.0
FAX	3.0.0
Panel	1.1.4
CDM	6.31.0
Booklet	2.0.0
Folder	2.0.0
TCBM	1.25.0
IP	0.26.0
Punch	2.0.0
Finisher-D Enh	31.0.0
TCBM2	2.10.0
Link to Software	C9265/C9275/C9281

Plug-in Release Detail

C9265/C9275/C9281 Plug-ins v1	Version
Xerox USB Card Reader	1.0.0
Modernized CAC Smartcard Service Plugin	3.0.0
Active Tag Plugin	2.0.0
CCID Terminal Plugin	1.2.2
TWN4 Card Reader Service	2.0.0

Contents

Firmware 86.03.53 (March 2025)

- Fixed the issue where EFI Connected devices cannot get into the Device Web page. This version allows EFI to connect to the device independent of CSRF enablement setting.
- Addition of Heavyweight 4a: 257 - 300 GSM to Default Media list.

Firmware 86.03.20 (December 2024)

- Launch Release of C9265/C9275/C9281 products

© 2025 Xerox Corporation. All rights reserved. Xerox®, and PrimeLink® are trademarks of Xerox Corporation in the United States and/or other countries. BRXXXXX Other company trademarks are also acknowledged. Document Version: 1.0 (January 2025).