Product Enhancements Document for WorkCentre 3335/3345 Firmware 60.006.03.000

Release Date: October 16, 2019

dc19rn3874

Software Release Details

Component	Version
System	60.006.03.000
MCB	V2.50.06.03
Engine (IOT)	V0.00.39_V1.00
Network	4.00.50.77
Link to Software	<u>WC3335 / WC3345</u>

I. Fixes/Features new in this release

- Fixed Open VMS PCL jobs from shifting up and to the right on 8.5 X 11 Labels.
- Libtiff Invalid Address Dereference Vulnerability (CVE-2019-7663.
- 2020 California Password law SB-327 update. This software release supports the California password law SB-327 effective January 1, 2020. Upgrading existing devices to this release will have no impact on the system administrator account password, administrator privileges, SNMP or device behavior. The changes incorporated in this release to support SB-327 327 will be transparent unless a factory reset routine is performed on the device.

II. Installation Notes

Install instructions are included in the zip file containing firmware. Unzip and download before attempting to install the firmware

© 2019 Xerox Corporation. All rights reserved. Xerox®, Xerox and Design®, and WorkCentre® are trademarks of Xerox Corporation in the United States and/or other countries. BR22773

Other company trademarks are also acknowledged. Document Version: 1.0 (January 2019).