

Patch Installation Instructions

A3 DFE SPAR Team

Product(s):	Xerox EX-i Print Server for the Xerox Color C60/C70 Printer	Date:	04/2017
Title:	SP2 Installation Instructions	Page:	1 of 1

Purpose

This software patch provides a 2.0SP1 software update in response to a XC C60/C70 EXi Integrated Fiery Color Server SPAR. Refer to the included customer letter for more information.

In the event of a system reinstall this software should be reapplied.

- ___ 5. Verify the **Update Info** section. It should contain the patch number SP2.ps.

Kit Contents

Qty.	Description
1	Patch Installation Instructions
1	Customer Letter
1	SP2.ps
1	Uninstall_SP.ps
1	Uninstaller Release Notes

Prerequisites

- Previous working knowledge with the XC C60/C70 EXi Integrated Fiery Color Server.
- The EXi Integrated Fiery Color Server must be at version 2.0SP1 prior to performing this install. This software is supplemental to the 2.0 launch software.
- Ensure the following patches are installed in the order they are listed here before installing this patch.
- SP1

Installation Instructions

NOTE: The customer or a member of the Xerox Service Team may install this software.

SP2.ps:

Before upgrading the software, ensure there are no other jobs processing.

- ___ 1. Import the patch file SP2.ps with Command Workstation to the **Direct** queue.
- ___ 2. You must wait at least 1 minute after importing the patch file before rebooting the system. This will ensure the patch file is completely processed.
- ___ 3. From Command Workstation, select **Server > Reboot Server**. The Fiery will reboot.
- ___ 4. Wait until the Fiery has come to idle and print out the configuration page.