

RELEASE NOTES

General information	
Issue ID Number	1-GSXYL
Product Name	Fiery EX2000D v. 3.0
Issue Date	November 12, 2004

Files included in this release	
File name	File size
1-GSXYL.ps	488 Kilobytes
relnotes.pdf	

Issue description
EX2000D does not work with CW2000.

Steps to reproduce
Once the 1-G6VTP patch is installed, user cannot select the HCS Bypass tray from an imported job. There is no way to force the job to print. When printed through the application, the HCS Bypass is selectable as an output destination, however, the job never gets to the CW2000. The job instead goes to the HCS Top Tray.

Resolution type:	Closed - Patch
-------------------------	-----------------------

Resolution

1-GSXYL.ps

Important notes

To install this patch, download this file to the Direct Queue using Fiery Downloader or use the import function of CWS 4.x to import it. After the file has finished processing, please wait at least 60 seconds, then reboot the server from the Fiery LCD. When the Fiery has come to idle, print out the configuration page to confirm that the patch file has been received. The Update Info section should reflect the patch number: "1-GSXYL."

NOTE: This patch replaces and supercedes 1-G6VTP.