

RELEASE NOTES

General information	
Issue ID Number	1-ANC11
Product Name	S-Series, Q-Series, X5, Z5, Z9, Z18 Series and X3e with languages EFIGSBPD Print Controllers with NT SP6a
Issue Date	08/15/2003

Files included in this release	
File name	File size
1-ANC11.ps	10,718,681 bytes

Issue description	
Microsoft Security Bulletin MS03-026 / Microsoft Hot-fix Q823980	
Steps to reproduce	
Please see Microsoft's Website for more details: http://www.microsoft.com/security/security_bulletins/ms03-026.asp http://www.microsoft.com/security/incident/blast.asp http://support.microsoft.com/?kbid=823980	
Resolution type:	Closed - Patch

Resolution
1-ANC11

Important notes
<p>This patch resolves the issues outlined in Microsoft's Security Bulletin MS03-026. This patch will install the Q823980 Hot-fix.</p> <p>Installation instructions:</p> <ol style="list-style-type: none">1) Download patch 1-ANC11.ps using CWS or Downloader to Direct connection of Fiery.2) After returns to "Idle", wait 60 seconds3) Reboot Print Controller .4) Fiery will boot up and then reboot itself.5) Let Fiery come to idle.6) Print the configuration page and make sure the correct information appears (Update Info section should appear with 1-ANC11).7) Installation is complete