

# Kit Installation Instructions

PSG SPAR Team

Product(s):	DocuColor 3535 v1.1/1.1P bustled Fiery color server	Date:	09/10/08
Title:	Patch 1-VG2ZB Installation instructions	Page:	1 of 1

## Purpose

This software kit provides a version 1.1/1.1P software update in response to a DocuColor 3535 bustled Fiery color server SPAR. Refer to the included customer letter for more information.

In the event of a version 1.1/1.1P system reinstall this software should be reapplied.

## Kit Contents

Qty.	Description
1	Kit Installation Instructions
1	Customer Letter
1	Patch 1-VG2ZB.ps

## Prerequisites

- Previous working knowledge with the DocuColor 3535 bustled Fiery color server.
- The DocuColor 3535 bustled Fiery color server must be at version 1.1 or 1.1P prior to performing this install. This software is supplemental to the version 1.1/1.1P launch software.

## Installation Instructions

**Note:** This patch is not Exclusive which means that it can be applied to the server along with other patches concurrently and only one server reboot/restart is sufficient for all patches to take effect on the system.

- \_\_\_ 1. Import the patch file **1-VG2ZB.ps** with Command Workstation to the **Direct** queue.
- \_\_\_ 2. You must wait at least 60 seconds after importing the patch file before rebooting the system. This will ensure the patch file is completely processed.
- \_\_\_ 3. Power off your DC3535.
- \_\_\_ 4. Power on your DC3535.
- \_\_\_ 5. Wait until the Fiery has come to idle and print out the configuration page.
- \_\_\_ 6. Verify the **System Update Log**. It should contain the patch number **1-VG2ZB**.