

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 1 of 89

# Suivi des versions logicielles iPrint & iPress

---

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 2 of 89

## Table des matières

VERSION: 2.12.6.0 .....	7
NEW FEATURE /IMPROVEMENT .....	7
BUG .....	7
VERSION: 2.12.5.0 .....	10
NEW FEATURE /IMPROVEMENT .....	10
BUG .....	10
VERSION: 2.12.4.0 .....	12
NEW FEATURE /IMPROVEMENT .....	12
BUG .....	12
VERSION: 2.12.2.0 .....	14
NEW FEATURE /IMPROVEMENT .....	14
BUG .....	14
VERSION: 2.12.1.0 .....	16
NEW FEATURE /IMPROVEMENT .....	16
BUG .....	16
VERSION: 2.12.0.0 .....	18
NEW FEATURE /IMPROVEMENT .....	18
BUG .....	18
VERSION: 2.10.1.0 .....	20
NEW FEATURE /IMPROVEMENT .....	20
BUG .....	20
VERSION: 2.10.0.0 .....	22
NEW FEATURE /IMPROVEMENT .....	22
BUG .....	22
VERSION: 2.9.8.0 .....	24
NEW FEATURE /IMPROVEMENT .....	24
BUG .....	24
VERSION: 2.9.7.0 .....	26
BUG .....	26
VERSION: 2.9.6.0 .....	28
BUG .....	28
VERSION: 2.9.5.0 .....	30
BUG .....	30
VERSION: 2.9.4.0 .....	31

	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	<b>Version :</b> 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	<b>Page</b> 3 of 89

BUG .....	31
VERSION: 2.9.3.0 .....	33
NEW FEATURE /IMPROVEMENT .....	33
BUG .....	33
VERSION: 2.9.2.0 .....	35
NEW FEATURE /IMPROVEMENT .....	35
BUG .....	35
VERSION: 2.9.1.0 .....	37
NEW FEATURE /IMPROVEMENT .....	37
BUG .....	37
VERSION: 2.8.7.0 .....	39
BUG .....	39
VERSION: 2.8.7.0 .....	40
BUG .....	40
VERSION: 2.8.6.0 .....	41
BUG .....	41
VERSION: 2.8.5.0 .....	42
BUG .....	42
VERSION: 2.8.4.0 .....	44
BUG .....	44
VERSION: 2.8.3.0 .....	46
BUG .....	46
VERSION: 2.8.2.0 .....	48
BUG .....	48
VERSION: 2.8.1.0 .....	50
NEW FEATURE /IMPROVEMENT .....	50
BUG .....	50
VERSION: 2.7.0.0 .....	52
NEW FEATURE/ IMPROVEMENT .....	52
BUG .....	52
VERSION: 2.5.3.0 .....	55
BUG .....	55
NEW FEATURE.....	55
TASK.....	55
VERSION: 2.4.3.0 .....	57

	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	<b>Version :</b> 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	<b>Page</b> 4 of 89

NEW FEATURE.....	57
VERSION: 2.4.2.0.....	58
BUG .....	58
VERSION: 2.4.1.0.....	59
BUG .....	59
IMPROVEMENT.....	59
NEW FEATURE.....	59
VERSION: 2.4.0.0.....	61
BUG .....	61
IMPROVEMENT.....	61
NEW FEATURE.....	61
TASK.....	62
KNOWN BUG .....	62
VERSION: 2.3.0.12.....	64
BUG .....	64
IMPROVEMENT.....	64
VERSION: 2.3.1.11.....	65
IMPROVEMENT.....	65
VERSION: 2.3.0.11.....	66
BUG .....	66
IMPROVEMENT.....	66
VERSION 2.3.0.10.....	68
BOGUE .....	68
VERSION 2.3.0.9.....	69
BOGUE .....	69
VERSION 2.3.0.8.....	70
BOGUE .....	70
AMELIORATION .....	70
VERSION 2.3.0.7.....	72
BOGUE .....	72
AMELIORATION .....	72
NOUVELLE FONCTIONNALITE .....	72
TACHE .....	72
VERSION 2.3.4.6.....	74
BOGUE .....	74
VERSION 2.3.0.6.....	76

 <b>imPIKA</b> A Xerox Company	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	<b>Version :</b> 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	<b>Page</b> 5 of 89

BOGUE .....	76
<b>VERSION 2.3.0.5 .....</b>	<b>78</b>
BOGUE .....	78
AMELIORATION .....	78
TACHE .....	78
<b>VERSION 2.3.0.4 .....</b>	<b>80</b>
BOGUE .....	80
NOUVELLE FONCTIONNALITE .....	80
TACHE .....	80
<b>VERSION 2.3.0.3 .....</b>	<b>81</b>
BOGUE .....	81
AMELIORATION .....	81
NOUVELLE FONCTIONNALITE .....	81
TACHE .....	81
<b>VERSION 2.2.0.17 .....</b>	<b>83</b>
BOGUE .....	83
AMELIORATION .....	83
<b>VERSION 2.1.0.43 .....</b>	<b>84</b>
TACHE .....	84
<b>VERSION 2.1.0.42 .....</b>	<b>85</b>
BOGUE .....	85
<b>VERSION 2.1.0.41 .....</b>	<b>86</b>
BOGUE .....	86
AMELIORATION .....	86
<b>VERSION 2.1.0.40 .....</b>	<b>87</b>
BOGUE .....	87
<b>VERSION 2.1.0.39 .....</b>	<b>87</b>
BOGUE .....	87
<b>VERSION 2.1.0.38 .....</b>	<b>87</b>
BOGUE .....	87
AMELIORATION .....	87
NOUVELLE FONCTIONNALITE .....	87
<b>VERSION 2.1.0.37 .....</b>	<b>87</b>
BOGUE .....	87
<b>VERSION 2.1.0.36 .....</b>	<b>88</b>
BOGUE .....	88

	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 6 of 89

<b>VERSION 2.1.0.35 .....</b>	<b>88</b>
BOGUE .....	88
<b>VERSION 2.1.0.34 .....</b>	<b>88</b>
BOGUE .....	88
AMELIORATION .....	88
NOUVELLE FONCTIONNALITE .....	88
<b>VERSION 2.1.0.33 .....</b>	<b>89</b>
BOGUE .....	89
<b>VERSION 2.1.0.32 .....</b>	<b>89</b>
BOGUE .....	89
AMELIORATION .....	89
<b>VERSION 2.1.0.31 .....</b>	<b>89</b>
BOGUE .....	89
AMELIORATION .....	89
<b>VERSION 2.1.0.30 .....</b>	<b>89</b>
AMELIORATION .....	89

	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 7 of 89

## VERSION: 2.12.6.0

Release date: 05 Novembre 2018

### NEW FEATURE /IMPROVEMENT

- [\[IPRINT-1940\]](#) - Operator rights restriction when cover open

### BUG

- [\[IPRINT-1170\]](#) - Unable to activate refill on tank through the MMI
- [\[IPRINT-1085\]](#) - [Initialized ValidTypeInk to true
- [\[IPRINT-1410\]](#) - [IN VHQ small drop and big drop are inverted on the back on machine 11-11 TRIVOR

Main files versions (file modified from the previous version in bold)		
File	Version	Date
<b>i600mmi.exe</b>	<b>2.12.6.5837</b>	<b>11-05-2018</b>
<b>pbx661controller.exe</b>	<b>3.8.5.1333</b>	<b>08-28-2018</b>
cddjobfile.dll	3.0.3.0	04-18-2016
CDD_iController.dll	1.0.0.0	04-18-2016
printdatapvider_icontroller.dll	1.5.1.0	22-03-2016
printdatapvider_jobfile.dll	4.7.1.0	15-02-2015

Secondary files version (file modified from the previous version in bold)		
File	Version	Date
configupdate.exe	1.2.2.0	08-24-2016
lpkBackup.exe	1.0.5.0	08-24-2016
i-dtpnetlibrary.dll	1.1.7.0	02-15-2016
impikafiberboard.dll	4.0.0.0	04-18-2016
cpnetlibrary.dll	5.1.0.0	02-15-2016
virtualkeyboard.dll	1.0.0.5	02-15-2016
virtualkeypad.dll	1.0.0.3	02-15-2016
vst_matti.dll	1.1.0.0	08-24-2016
serialportcom.dll	1.0.9.0	02-15-2016
iLog	1.0.1.0	08-24-2016
i600configuration.dll	1.5.2.0	08-24-2016
signaturetools.exe	1.0.0.4	08-24-2016
skinx.dll	1.0.0.7	02-15-2016
languageresource.dll	1.0.0.0	02-15-2016
mfcguiext.dll	1.0.0.2	02-15-2016
sqlite3.dll	-	05-26-2014
pcan_usb.dll	2.0.4.0	04-18-2016

	<h1>Technical Note</h1>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 8 of 89

adsapi32.dll	1.5.16.1	02-15-2016
dbghelp.dll	6.12.2.633	02-15-2016
mxio.dll	2.7.0.0	02-15-2016
paexec.exe	1.25.0.0	02-15-2016
xcmd.exe	1.0.0.1	08-24-2016
xcrashhandler.dll	1.0.0.1	02-15-2016
xcrashreport.exe	1.0.0.2	02-15-2016
ipkwidgit.dll	2.1.0.0	08-24-2016
qtcore4.dll	4.8.1.0	01-11-2016
qtgui4.dll	4.8.1.0	01-11-2016
qtxml4.dll	4.8.1.0	01-11-2016
iControllerConfigNameLookup.exe	0.9.0.0	03-22-2016
Secondary files version (file modified from the previous version in bold)		

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
DMDB Firmware	5.10.000 6.4 5.6	24-03-2016

TDB = To Be Done

Subassembly	Minimum required versions		
	Compact	Reference* (Single or Twin)	eVolution (Single or Twin)
Process PLC SW	1.0.02.9 (SSR)	1.0.02.1 (SSR)	1.0.02.0 (SSR)
Motors Drives	1.0.02.9 (SSR)	1.0.01.3 (SSR)	1.0.01.3 (SSR)
Stepper motor interfaces version (lift)	1.0.00.9.ccp 1.0.00.5.ccx	1.1.00.1.ccp 1.0.00.5.ccx	1.1.00.1.ccp 1.0.00.5.ccx
Stepper motors interfaces version (CWS drawer)	1.0.00.0 ccp 1.0.00.0 ccx	1.0.00.0 ccp 1.0.00.0 ccx	1.0.00.0 ccp 1.0.00.0 ccx
EPSIB Board	Xerox PN : 146N00150 (Rev B)	Xerox PN : 146N00150 (Rev B)	Xerox PN : 146N00150 (Rev B)
EPSIB Firmware (UC / NIOS / FPGA)	UC: NA / NIOS: 2.1.4 / FPGA: 31	UC: NA / NIOS: 2.1.4 / FPGA: 31	UC: NA / NIOS: 2.1.4 / FPGA: 31
DMDB (NIOS / FPGA 1 COM / FPGA 2 TIR)	5.01.000 / 6.4 / 5.6	5.01.000 / 6.4 / 5.6	5.01.000 / 6.4 / 5.6
MTPB (ISC IMC)	16.1.010	16.1.10	16.1.10

Subassembly	Minimum required versions		
	Reference MICR		
	Tower #1		Tower#2
Process PLC SW	1.0.02.1 (SSR)		
Motors Drives	1.0.01.3 (SSR)		
Stepper motor interfaces version (lift)	Lift 1 1.1.00.1.ccp 1.0.00.5.ccx	Lift 2 (MICR) 1.1.00.2.ccp 1.0.00.5.ccx	1.1.00.1.ccp 1.0.00.5.ccx
Stepper motors interfaces version (CWS drawer)	1.0.00.0 ccp 1.0.00.0 ccx		1.0.00.0 ccp 1.0.00.0 ccx
EPSIB Board	Xerox PN : 140N63812 (Rev F)		Xerox PN : 146N00150 (Rev B)
EPSIB Firmware (UC / NIOS / FPGA)	UC: 1.1.1 or later NIOS: 2.2.0 or later FPGA: 55 or later		UC: NA / NIOS: 2.1.4 / FPGA: 31
DMDB (NIOS / FPGA 1 COM / FPGA 2 TIR)	5.01.000 / 6.4 / 5.6		5.01.000 / 6.4 / 5.6
MTPB (ISC IMC)	16.1.10		16.1.10



	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 9 of 89

**Stepper motor interface identification**

<b>Stepper-motor Interface N°</b>	12U0	12U5	13U0	14U0	14U5
<b>Corresponding motor</b>	CWS Drawer #1	CWS Drawer #2	CWS Drawer #3 (if installed)	Lift #1	Lift #2 (if installed)

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 10 of 89

## VERSION: 2.12.5.0

**Warning: this version requires a DMDB firmware Update ! [v5.10.000 6.4 5.6]**

**Warning: this version requires a Matti firmware Update to manage SlowSpeedRequest ONLY FOR eVolution printers (see below inside the firmware version table) – SlowSpeedRequest Reference and Compact Printers are not available yet !**

Release date: 24 August 2016

### NEW FEATURE /IMPROVEMENT

- [\[IPRINT-996\]](#) - Allow only one temperature sensor (instead of 8) to be mounted on PrintHead
- [\[IPRINT-1010\]](#) - Change Module Distance parameter access from Setup operator to Maintenance operator

### BUG

- [\[IPRINT-1002\]](#) - [TN20160241] "Show / hide MICR" button is not blue
- [\[IPRINT-1003\]](#) - [TN20160165] Missing translation in the 2.12.4 versions
- [\[IPRINT-1004\]](#) - [TN20160214] I600MMI Application Crash
- [\[IPRINT-999\]](#) - Incorrect ink consumption in dual color
- [\[IPRINT-1043\]](#) - ConfigUpdate add an open xml tag <GetFileVersionFAILED> who is never closed
- [\[IPRINT-1044\]](#) - Change the value of use temperature compensation to false in MD and in all associated snapshots
- [\[IPRINT-1064\]](#) - [TN20160262 20160266] Snapshot list takes long time to show up

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
i600mmi.exe	<b>2.12.5.3607</b>	<b>08-24-2016</b>
pbx661controller.exe	<b>3.8.4.879</b>	<b>08-24-2016</b>
cddjobfile.dll	3.0.3.0	04-18-2016
CDD_iController.dll	1.0.0.0	04-18-2016
printdatapvider_icontroller.dll	1.5.1.0	22-03-2016
printdatapvider_jobfile.dll	4.7.1.0	15-02-2015

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
configupdate.exe	<b>1.2.2.0</b>	<b>08-24-2016</b>
lpkBackup.exe	1.0.5.0	08-24-2016
i-dtpnetlibrary.dll	1.1.7.0	02-15-2016
impikafiberboard.dll	4.0.0.0	04-18-2016

	<h1>Technical Note</h1>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 11 of 89

cpnetlibrary.dll	5.1.0.0	02-15-2016
virtualkeyboard.dll	1.0.0.5	02-15-2016
virtualkeypad.dll	1.0.0.3	02-15-2016
vst_matti.dll	1.1.0.0	08-24-2016
serialportcom.dll	1.0.9.0	02-15-2016
iLog	1.0.1.0	08-24-2016
i600configuration.dll	1.5.2.0	08-24-2016
signaturetools.exe	1.0.0.4	08-24-2016
skinx.dll	1.0.0.7	02-15-2016
languageresource.dll	1.0.0.0	02-15-2016
mfcguiext.dll	1.0.0.2	02-15-2016
sqlite3.dll	-	05-26-2014
pcan_usb.dll	2.0.4.0	04-18-2016
adsapi32.dll	1.5.16.1	02-15-2016
dbghelp.dll	6.12.2.633	02-15-2016
mxio.dll	2.7.0.0	02-15-2016
paexec.exe	1.25.0.0	02-15-2016
xcmd.exe	1.0.0.1	08-24-2016
xcrashhandler.dll	1.0.0.1	02-15-2016
xcrashreport.exe	1.0.0.2	02-15-2016
ipkwidget.dll	2.1.0.0	08-24-2016
qtcore4.dll	4.8.1.0	01-11-2016
qtgui4.dll	4.8.1.0	01-11-2016
qtxml4.dll	4.8.1.0	01-11-2016
iControllerConfigNameLookup.exe	0.9.0.0	03-22-2016

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
<b>DMDB Firmware</b>	<b>5.10.000 6.4 5.6</b>	<b>24-03-2016</b>
Reference		
PLC Firmware	TBD	
Drives	TBD	
Compact		
PLC Firmware	TBD	
Drives	TBD	
eVolution		
PLC Firmware	1.0.01.9	
Drives	1.0.01.3	

• TDB = To Be Done

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 12 of 89

## VERSION: 2.12.4.0

**Warning: this version requires a DMDB firmware Update ! [v5.10.000 6.4 5.6]**

**Warning: this version requires a Matti firmware Update to manage SlowSpeedRequest ONLY FOR eVolution printers (see below inside the firmware version table) – SlowSpeedRequest Reference and Compact Printers are not available yet !**

Release date: 08 July 2016

### NEW FEATURE /IMPROVEMENT

- [\[IPRINT-959\]](#) - Update configUpdate to allow 7 marks per side
- [\[IPRINT-868\]](#) - TraceManager: Use 'ProductionLog.db' file path set and used by the current I600MMI application instead of the default one
- [\[IPRINT-869\]](#) - TraceManager: Use the current I600MMI application's path as the MMI path instead of the 'default' hard coded one in the trace gathering operations
- [\[IPRINT-870\]](#) - TraceManager: Detect currently running I600PBX executable's path and use those instead of the default path in the trace gathering operations
- [\[IPRINT-942\]](#) – Remove required license for the feature KVM compatibility
- [\[IPRINT-958\]](#) - [TN20160161] Change the minimum size of additional cue marks to 0.1mm

### BUG

- [\[IPRINT-944\]](#) – Forbid application exit during log/trace creation process
- [\[IPRINT-952\]](#) – Wrong Speed limit generated by ConfigGenerator
- [\[IPRINT-953\]](#) - The control bits sent by the SetLightBar commands are incorrect
- [\[IPRINT-956\]](#) – Display two MICR tank for MICR configurations
- [\[IPRINT-960\]](#) - Undo on modified snapshot leads to erroneous max speed
- [\[IPRINT-971\]](#) - [TN20160179;20160177;20160147] Bit "Slave 4 Stop" is returned by the VST

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
i600mmi.exe	<b>2.12.4.3375</b>	<b>08-07-2016</b>
pbx661controller.exe	<b>3.8.3.820</b>	<b>04-07-2016</b>
cddjobfile.dll	3.0.3.0	01-21-2015
CDD_iController.dll	1.0.0.0	17-03-2016
printdataprovider_icontroller.dll	1.5.1.0	22-03-2016
printdataprovider_jobfile.dll	4.7.1.0	09-01-2015

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date

	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 13 of 89

<b>configupdate.exe</b>	<b>1.2.1.0</b>	<b>05-07-2016</b>
lpkBackup.exe	1.0.5.0	01-06-2016
i-dtpnetlibrary.dll	1.1.7.0	11-12-2014
impikafiberboard.dll	4.0.0.0	01-21-2015
cpnetlibrary.dll	5.1.0.0	01-21-2015
virtualkeyboard.dll	1.0.0.5	06-09-2014
virtualkeypad.dll	1.0.0.3	05-28-2015
vst_matti.dll	1.1.0.0	24-03-2016
serialportcom.dll	1.0.9.0	11-12-2014
iLog	1.0.0.0	03-26-2015
<b>i600configuration.dll</b>	<b>1.5.2.0</b>	<b>05-07-2016</b>
<b>signaturetools.exe</b>	<b>1.0.0.4</b>	<b>05-07-2016</b>
skinx.dll	1.0.0.7	02-05-2015
languageresource.dll	1.0.0.0	11-12-2014
mfcguiext.dll	1.0.0.2	11-12-2014
sqlite3.dll	-	11-12-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	11-12-2014
dbghelp.dll	6.12.2.633	11-12-2014
mxio.dll	2.7.0.0	11-12-2014
paexec.exe	1.25.0.0	11-12-2014
xcmd.exe	1.0.0.1	11-12-2014
xcrashhandler.dll	1.0.0.1	11-12-2014
xcrashreport.exe	1.0.0.2	11-12-2014
ipkwidgit.dll	2.1.0.0	24-03-2016
qtcore4.dll	4.8.1.0	07-04-2014
qtgui4.dll	4.8.1.0	07-04-2014
qtxml4.dll	4.8.1.0	07-04-2014
iControllerConfigNameLookup.exe	0.9.0.0	10-03-2016

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
<b>DMDB Firmware</b>	<b>5.10.000 6.4 5.6</b>	<b>24-03-2016</b>
Reference		
PLC Firmware	TBD	
Drives	TBD	
Compact		
PLC Firmware	TBD	
Drives	TBD	
eVolution		
PLC Firmware	1.0.01.9	
Drives	1.0.01.3	

TDB = To Be Done

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 14 of 89

## VERSION: 2.12.2.0

**Warning: this version requires a DMDB firmware Update ! [v5.10.000 6.3 5.6]**

**Warning: this version requires a Matti firmware Update to manage SlowSpeedRequest ONLY FOR eVolution printers (see below inside the firmware version table) – SlowSpeedRequest Reference and Compact Printers are not available yet !**

Release date: 31 May 2016

### NEW FEATURE /IMPROVEMENT

- [\[IPRINT-871\]](#) - TraceManager: Trace Extra Information on each Start of Printing
- [\[IPRINT-897\]](#) - Data Provider Interface: Allocated spot color with channel ID value 6 to MICR
- [\[IPRINT-900\]](#) - TraceManager: Trace License Status and list of the License Features as part of traced Extra Information
- [\[IPRINT-923\]](#) - Print Data Provider Interface: ResChannelX and ResChannelY parameters usage, with iController specific exception

### BUG

- [\[IPRINT-898\]](#) - Light Cyan and Light Magenta channel IDs were not handled correctly in LocalJob file name generation
- [\[IPRINT-902\]](#) - Print Data Provider Interface: Speeds reported in E\_PID\_SupportedResolutionsAndSpeeds parameter are not changed when the 40kHz license is enabled

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
i600mmi.exe	<b>2.12.1.3149</b>	<b>25-05-2016</b>
pbx661controller.exe	<b>3.8.2.778</b>	<b>25-05-2016</b>
cddjobfile.dll	3.0.3.0	01-21-2015
CDD_iController.dll	1.0.0.0	17-03-2016
printdataprovider_icontroller.dll	1.5.1.0	22-03-2016
printdataprovider_jobfile.dll	4.7.1.0	09-01-2015

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
configupdate.exe	1.2.0.0	24-03-2016
lpkBackup.exe	1.0.5.0	01-06-2016
i-dtpnetlibrary.dll	1.1.7.0	11-12-2014
impikafiberboard.dll	4.0.0.0	01-21-2015
cpnetlibrary.dll	5.1.0.0	01-21-2015

	<h1>Technical Note</h1>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 15 of 89

virtualkeyboard.dll	1.0.0.5	06-09-2014
virtualkeypad.dll	1.0.0.3	05-28-2015
vst_matti.dll	1.1.0.0	24-03-2016
serialportcom.dll	1.0.9.0	11-12-2014
iLog	1.0.0.0	03-26-2015
i600configuration.dll	1.5.1.0	22-04-2016
signaturetools.exe	1.0.0.3	03-26-2015
skinx.dll	1.0.0.7	02-05-2015
languageresource.dll	1.0.0.0	11-12-2014
mfcguiext.dll	1.0.0.2	11-12-2014
sqlite3.dll	-	11-12-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	11-12-2014
dbghelp.dll	6.12.2.633	11-12-2014
mxio.dll	2.7.0.0	11-12-2014
paexec.exe	1.25.0.0	11-12-2014
xcmd.exe	1.0.0.1	11-12-2014
xcrashhandler.dll	1.0.0.1	11-12-2014
xcrashreport.exe	1.0.0.2	11-12-2014
ipkwidget.dll	2.1.0.0	24-03-2016
qtcore4.dll	4.8.1.0	07-04-2014
qtgui4.dll	4.8.1.0	07-04-2014
qtxml4.dll	4.8.1.0	07-04-2014
iControllerConfigNameLookup.exe	0.9.0.0	10-03-2016

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
DMDB Firmware	5.10.000 6.3 5.6	24-03-2016
Reference		
PLC Firmware	TBD	
Drives	TBD	
Compact		
PLC Firmware	TBD	
Drives	TBD	
eVolution		
PLC Firmware	1.0.01.9	
Drives	1.0.01.3	

TDB = To Be Done

	<b>Technical Note</b>	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 16 of 89

## VERSION: 2.12.1.0

**Warning: this version requires a DMDB firmware Update ! [v5.10.000 6.3 5.6]**

**Warning: this version requires a Matti firmware Update to manage SlowSpeedRequest ONLY FOR eVolution printers (see below inside the firmware version table) – SlowSpeedRequest Reference and Compact Printers are not available yet !**

Release date: 08 July 2016

### NEW FEATURE /IMPROVEMENT

- [\[IPRINT-830\]](#) - Enable Background spray only for HD2
- [\[IPRINT-842\]](#) - Set Realistic Maximum Stacked/Fixed/Eject Distances
- [\[IPRINT-845\]](#) - Remove iController Data Provider configuration specific code from Tracing/Logging
- [\[IPRINT-890\]](#) - SlowSpeedRequest feature enabled only on eVolution printer

### BUG

- [\[IPRINT-860\]](#) - Press InFeed / OutFeed is not updated on mechanical screen when the state change
- [\[IPRINT-861\]](#) - In Tach&Cue screen Back configuration is visible on printer with only front printhead
- [\[IPRINT-862\]](#) - The DMDB synchronization checks are broken (Extreme)
- [\[IPRINT-863\]](#) - On flushlines when drawMICR is unchecked the flushline is still drawn

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
i600mmi.exe	<b>2.12.1.3046</b>	<b>04-05-2016</b>
pbx661controller.exe	<b>3.8.1.749</b>	<b>02-05-2016</b>
cddjobfile.dll	3.0.3.0	01-21-2015
CDD_iController.dll	1.0.0.0	17-03-2016
printdataprovider_icontroller.dll	1.5.1.0	22-03-2016
printdataprovider_jobfile.dll	4.7.1.0	09-01-2015

Secondary files version (file modified from the previous version **in bold**)

File	Version	Date
configupdate.exe	1.2.0.0	24-03-2016
lpkBackup.exe	1.0.5.0	01-06-2016
i-dtpnetlibrary.dll	1.1.7.0	11-12-2014
impikafiberboard.dll	4.0.0.0	01-21-2015
cpnetlibrary.dll	5.1.0.0	01-21-2015



	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 17 of 89

virtualkeyboard.dll	1.0.0.5	06-09-2014
virtualkeypad.dll	1.0.0.3	05-28-2015
vst_matti.dll	1.1.0.0	24-03-2016
serialportcom.dll	1.0.9.0	11-12-2014
iLog	1.0.0.0	03-26-2015
<b>i600configuration.dll</b>	<b>1.5.1.0</b>	<b>22-04-2016</b>
signaturetools.exe	1.0.0.3	03-26-2015
skinx.dll	1.0.0.7	02-05-2015
languageresource.dll	1.0.0.0	11-12-2014
mfcguiext.dll	1.0.0.2	11-12-2014
sqlite3.dll	-	11-12-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	11-12-2014
dbghelp.dll	6.12.2.633	11-12-2014
mxio.dll	2.7.0.0	11-12-2014
paexec.exe	1.25.0.0	11-12-2014
xcmd.exe	1.0.0.1	11-12-2014
xcrashhandler.dll	1.0.0.1	11-12-2014
xcrashreport.exe	1.0.0.2	11-12-2014
ipkwidget.dll	2.1.0.0	24-03-2016
qtcore4.dll	4.8.1.0	07-04-2014
qtgui4.dll	4.8.1.0	07-04-2014
qtxml4.dll	4.8.1.0	07-04-2014
iControllerConfigNameLookup.exe	0.9.0.0	10-03-2016

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
<b>DMDB Firmware</b>	<b>5.10.000 6.4 5.6</b>	24-03-2016
Reference		
PLC Firmware	TBD	
Drives	TBD	
Compact		
PLC Firmware	TBD	
Drives	TBD	
eVolution		
PLC Firmware	1.0.01.9	
Drives	1.0.01.3	

TDB = To Be Done

 A Xerox Company	<h1>Technical Note</h1>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<h2>Suivi de version iPrint &amp; iPress</h2>	<b>Version :</b> 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	<b>Page</b> 18 of 89

### VERSION: 2.12.0.0

**Warning: this version requires a DMDB firmware Update ! [v5.10.000 6.3 5.6]**

**Warning: this version requires a Matti firmware Update !**

Release date: 24 March 2016

### NEW FEATURE /IMPROVEMENT

- Compatibility with Tagg Automatic installer
- [\[IPRINT-736\]](#) - Add software version at the beginning of languages files.
- [\[IPRINT-775\]](#) - Display CMR param in setup for MICR
- [\[IPRINT-784\]](#) - [TN2016001] Add Billing Meters for pages with MICR Only
- [\[IPRINT-799\]](#) - Redo the WebGuide screen
- [\[IPRINT-565\]](#) - [TN20140278] Chose the system unit displayed (International or US Standards Units)
- [\[IPRINT-734\]](#) - Slow speed request signal management
- [\[IPRINT-735\]](#) - Clear Pixel Technologie: Background Spray
- [\[IPRINT-792\]](#) - MICR with different resolution
- [\[IPRINT-795\]](#) - Print PDF with MICR
- [\[IPRINT-797\]](#) - UI for PDFExtraColor
- [\[IPRINT-800\]](#) - Add auto check for media size and media offset entered by operator
- [\[IPRINT-803\]](#) - Add black border on MMI if the configuration screen is 16/9

### BUG

- [\[IPRINT-759\]](#) - On machine 11, the trc files appears on the mmi only if the 4 file CMYK are present in the folder TRC profile
- [\[IPRINT-771\]](#) - [TN20150494] PrintDataProvider\_iController: E\_PT\_PressCancel parameter's value is sent with reverse logic
- [\[IPRINT-777\]](#) - CueMark parameter MarkInsideTheJob disable editable parameters for all CueMark
- [\[IPRINT-779\]](#) - [TN20150548] Config generator does not populate TRCPath parameter in machine definition
- [\[IPRINT-787\]](#) - [TN20160004] French translation replace by german sentence
- [\[IPRINT-788\]](#) - Error when reading counters from byte array
- [\[IPRINT-806\]](#) - Button "Enter CS in Maintenance Mode" doesn't work on NTB
- [\[IPRINT-810\]](#) - PBX crash in when the configuration is received
- [\[IPRINT-818\]](#) - Ink Coverage File Absolut Path is incorrectly used and not sent to the PDPs
- [\[IPRINT-819\]](#) - SpeedLimitation is wrong with MICR
- [\[IPRINT-821\]](#) - [TN20160042] MarksInsideJob parameter should be only used by syncro mark
- [\[IPRINT-825\]](#) - ConfigUpdate mess with JobsEnumerationAbsolutePath
- [\[IPRINT-827\]](#) - I600MMI crash when the VST connection failed

	<h1>Technical Note</h1>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<h2>Suivi de version iPrint &amp; iPress</h2>	<b>Version :</b> 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	<b>Page</b> 19 of 89

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
<b>i600mmi.exe</b>	<b>2.12.0.0</b>	<b>24-03-2016</b>
pbx661controller.exe	3.8.0.0	07-01-2016
cddjobfile.dll	3.0.3.0	01-21-2015
<b>CDD_iController.dll</b>	<b>1.0.0.0</b>	<b>17-03-2016</b>
<b>printdatapvider_icontroller.dll</b>	<b>1.5.1.0</b>	<b>22-03-2016</b>
printdatapvider_jobfile.dll	4.7.1.0	09-01-2015

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
<b>configupdate.exe</b>	<b>1.2.0.0</b>	<b>24-03-2016</b>
lpkBackup.exe	1.0.5.0	01-06-2016
i-dtpnetlibrary.dll	1.1.7.0	11-12-2014
impikafiberopticboard.dll	4.0.0.0	01-21-2015
cpnetlibrary.dll	5.1.0.0	01-21-2015
virtualkeyboard.dll	1.0.0.5	06-09-2014
virtualkeypad.dll	1.0.0.3	05-28-2015
<b>vst_matti.dll</b>	<b>1.1.0.0</b>	<b>24-03-2016</b>
serialportcom.dll	1.0.9.0	11-12-2014
iLog	1.0.0.0	03-26-2015
<b>i600configuration.dll</b>	<b>1.5.0.0</b>	<b>24-03-2016</b>
signaturetools.exe	1.0.0.3	03-26-2015
skinx.dll	1.0.0.7	02-05-2015
languageresource.dll	1.0.0.0	11-12-2014
mfcguiext.dll	1.0.0.2	11-12-2014
sqlite3.dll	-	11-12-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	11-12-2014
dbghelp.dll	6.12.2.633	11-12-2014
mxio.dll	2.7.0.0	11-12-2014
paexec.exe	1.25.0.0	11-12-2014
xcmd.exe	1.0.0.1	11-12-2014
xcrashhandler.dll	1.0.0.1	11-12-2014
xcrashreport.exe	1.0.0.2	11-12-2014
<b>ipkwidget.dll</b>	<b>2.1.0.0</b>	<b>24-03-2016</b>
qtcore4.dll	4.8.1.0	07-04-2014
qtgui4.dll	4.8.1.0	07-04-2014
qtxml4.dll	4.8.1.0	07-04-2014
<b>iControllerConfigNameLookup.exe</b>	<b>0.9.0.0</b>	<b>10-03-2016</b>

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
<b>DMDB Firmware</b>	<b>5.10.000 6.3 5.6</b>	<b>24-03-2016</b>

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 20 of 89

## VERSION: 2.10.1.0

**Warning: this version requires a DMDB firmware Update ! [v5.00.100 6.3 5.4]**

Release date: 07 January 2016

### NEW FEATURE /IMPROVEMENT

- [\[IPRINT-554\]](#) - Prohibit user to do the electric shutdown of the machine if printheads are not parked.
- [\[IPRINT-568\]](#) - New Operator Safety Management : Automatically adjust time out of printhead movement to add the 3 seconds taken by the buzzer
- [\[IPRINT-754\]](#) - New Operator Safety Management : Colored Messages on ToDo Info Panel

### BUG

- [\[IPRINT-747\]](#) - Multiple messageBox when the linearisation file are invalid
- [\[IPRINT-750\]](#) - It possible to change the printing mode when machine is printing
- [\[IPRINT-751\]](#) - [TN20150484] Error in DFE after switching VHQ to HS
- [\[IPRINT-761\]](#) - PBX Controller crashes if CDD's Configuration string is longer then 260 character
- [\[IPRINT-771\]](#) - [TN20150494] PrintDataProvider\_iController: E\_PT\_PressCancel parameter's value is sent with reverse logic
- [\[IPRINT-777\]](#) - CueMark parameter MarkInsideTheJob disable editable parameters for all CueMark
- [\[IPRINT-779\]](#) - [TN20150548] Config generator does not populate TRCPath parameter in machine definition
- [\[IPRINT-791\]](#) - [TN20150400] Remove licensed feature KVMCompatibilty

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
i600mmi.exe	<b>2.10.1.0</b>	<b>10-12-2015</b>
pbx661controller.exe	<b>3.7.2.0</b>	<b>07-01-2016</b>
cddjobfile.dll	3.0.3.0	01-21-2015
printdataprovder_icontroller.dll	<b>1.4.3.0</b>	<b>16-12-2015</b>
printdataprovder_jobfile.dll	4.7.1.0	09-01-2015

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
configupdate.exe	1.1.4.1	06-17-2015
lpkBackup.exe	<b>1.0.5.0</b>	<b>01-06-2016</b>
i-dtpnetlibrary.dll	1.1.7.0	11-12-2014
impikafiberopticboard.dll	4.0.0.0	01-21-2015

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 21 of 89

cpnetlibrary.dll	5.1.0.0	01-21-2015
virtualkeyboard.dll	1.0.0.5	06-09-2014
virtualkeypad.dll	1.0.0.3	05-28-2015
vst_matti.dll	1.0.1.0	06-12-2015
serialportcom.dll	1.0.9.0	11-12-2014
iLog	1.0.0.0	03-26-2015
<b>i600configuration.dll</b>	<b>1.4.1.0</b>	<b>01-06-2016</b>
signaturetools.exe	1.0.0.3	03-26-2015
skinx.dll	1.0.0.7	02-05-2015
languageresource.dll	1.0.0.0	11-12-2014
mfcguiext.dll	1.0.0.2	11-12-2014
sqlite3.dll	-	11-12-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	11-12-2014
dbghelp.dll	6.12.2.633	11-12-2014
mxio.dll	2.7.0.0	11-12-2014
paexec.exe	1.25.0.0	11-12-2014
xcmd.exe	1.0.0.1	11-12-2014
xcrashhandler.dll	1.0.0.1	11-12-2014
xcrashreport.exe	1.0.0.2	11-12-2014
ipkwidget.dll	2.0.0.0	10-13-2015
qtcore4.dll	4.8.1.0	07-04-2014
qtgui4.dll	4.8.1.0	07-04-2014
qtxml4.dll	4.8.1.0	07-04-2014

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
DMDB Firmware	5.00.100 <b>6.3 5.4</b>	<b>01-07-2015</b>

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 22 of 89

## VERSION: 2.10.0.0

Release date: 12 October 2015

### NEW FEATURE /IMPROVEMENT

- [\[IPRINT-574\]](#) - VHQ support in IPDS
- [\[IPRINT-651\]](#) - 40 KHz manage different speed based on drop sizes, resolution and printing mode
- [\[IPRINT-652\]](#) - 40 KHz license based feature
- [\[IPRINT-653\]](#) - 40 KHz Improved Drop Flying Time Compensation

### BUG

- [\[IPRINT-724\]](#) - Some MMI displayed text are not presents in language file for translation

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
i600mmi.exe	<b>2.10.0.0</b>	<b>10-12-2015</b>
pbx661controller.exe	<b>3.6.0.0</b>	<b>10-12-2015</b>
cddjobfile.dll	3.0.3.0	01-21-2015
printdataprovder_icontroller.dll	<b>1.4.1.0</b>	<b>10-12-2015</b>
printdataprovder_jobfile.dll	4.7.1.0	09-01-2015

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
configupdate.exe	1.1.4.1	06-17-2015
lpkBackup.exe	1.0.4.2	06-16-2015
i-dtpnetlibrary.dll	1.1.7.0	11-12-2014
impikafiberopticboard.dll	4.0.0.0	01-21-2015
cpnetlibrary.dll	5.1.0.0	01-21-2015
virtualkeyboard.dll	1.0.0.5	06-09-2014
virtualkeypad.dll	1.0.0.3	05-28-2015
vst_matti.dll	1.0.1.0	06-12-2015
serialportcom.dll	1.0.9.0	11-12-2014
iLog	1.0.0.0	03-26-2015
<b>i600configuration.dll</b>	<b>1.4.0.0</b>	<b>10-09-2015</b>
signaturetools.exe	1.0.0.3	03-26-2015
skinx.dll	1.0.0.7	02-05-2015
languageresource.dll	1.0.0.0	11-12-2014
mfcguiext.dll	1.0.0.2	11-12-2014
sqlite3.dll	-	11-12-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	11-12-2014
dbgghelp.dll	6.12.2.633	11-12-2014
mxio.dll	2.7.0.0	11-12-2014

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 23 of 89

paexec.exe	1.25.0.0	11-12-2014
xcmd.exe	1.0.0.1	11-12-2014
xcrashhandler.dll	1.0.0.1	11-12-2014
xcrashreport.exe	1.0.0.2	11-12-2014
ipkwidget.dll	2.0.0.0	10-13-2015
qtcore4.dll	4.8.1.0	07-04-2014
qtgui4.dll	4.8.1.0	07-04-2014
qtxml4.dll	4.8.1.0	07-04-2014

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
DMDB Firmware	5.00.002 <b>6.2 5.3</b>	09-26-2014

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 24 of 89

## VERSION: 2.9.8.0

**Warning: the following item should impact FFPS controller! [IPRINT-737]**

Release date: 13 October 2015

### NEW FEATURE /IMPROVEMENT

- [\[IPRINT-720\]](#) - Camera system communication timeout configurable
- [\[IPRINT-721\]](#) - [TN20150361] Enlarge TRC and snapshot selection window

### BUG

- [\[IPRINT-727\]](#) - Automatic backup don't restore MMI shortcuts in start folder
- [\[IPRINT-730\]](#) - Snapshots and Job name with special characters like ' are not saved in productin log database.
- [\[IPRINT-731\]](#) - [TN20150149, 20150174] Missing and incorrect entries in Production logs.
- [\[IPRINT-732\]](#) - In Save Information file Data Provider name is not displayed
- [\[IPRINT-733\]](#) - ICC Profiles created the 26th cannot be loaded in MMI
- [\[IPRINT-737\]](#) - [TN20150218, 20150356, 20150421] IPDS Controller stays locked in Stopping state.
- [\[IPRINT-739\]](#) - Adjust the temporisation values for procedure "emptying head"
- [\[IPRINT-741\]](#) - [TN20150442] I600MMI application crash when changing snapshot
- [\[IPRINT-742\]](#) - Add an error message in the Ui when SetSimplexDuplexConfiguration fail on encoder box during gotoStartedState
- [\[IPRINT-743\]](#) - [TN20150334] Some jobs are not exported by automatic export feature when changing snapshot
- [\[IPRINT-744\]](#) - MMI Crash when editing a MediaSize parameter
- [\[IPRINT-746\]](#) - [TN20150446] Missing Qt dlls in IpkBackup deployment
- [\[IPRINT-773\]](#) - [TN20150535] IpkBackup is not correctly deployed on existing system

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
i600mmi.exe	<b>2.9.8.0</b>	<b>10-13-2015</b>
pbx661controller.exe	<b>3.5.6.0</b>	<b>10-13-2015</b>
cddjobfile.dll	3.0.3.0	01-21-2015
printdataprovder_icontroller.dll	<b>1.4.2.0</b>	<b>10-12-2015</b>
printdataprovder_jobfile.dll	4.7.1.0	09-02-2015

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
configupdate.exe	1.1.4.1	06-17-2015



	<h1>Technical Note</h1>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 25 of 89

lpkBackup.exe	1.0.4.2	06-16-2015
i-dtpnetlibrary.dll	1.1.7.0	11-12-2014
impikafiberboard.dll	4.0.0.0	01-21-2015
cpnetlibrary.dll	5.1.0.0	01-21-2015
virtualkeyboard.dll	1.0.0.5	06-09-2014
virtualkeypad.dll	1.0.0.3	05-28-2015
vst_matti.dll	1.0.1.0	06-12-2015
serialportcom.dll	1.0.9.0	11-12-2014
iLog	1.0.0.0	03-26-2015
<b>i600configuration.dll</b>	<b>1.4.0.0</b>	<b>10-13-2015</b>
signaturetools.exe	1.0.0.3	03-26-2015
skinx.dll	1.0.0.7	02-05-2015
languageresource.dll	1.0.0.0	11-12-2014
mfcguiext.dll	1.0.0.2	11-12-2014
sqlite3.dll	-	11-12-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	11-12-2014
dbgghelp.dll	6.12.2.633	11-12-2014
mxio.dll	2.7.0.0	11-12-2014
paexec.exe	1.25.0.0	11-12-2014
xcmd.exe	1.0.0.1	11-12-2014
xcrashhandler.dll	1.0.0.1	11-12-2014
xcrashreport.exe	1.0.0.2	11-12-2014
ipkwidgit.dll	2.0.0.0	10-13-2015
qtcore4.dll	4.8.1.0	07-04-2014
qtgui4.dll	4.8.1.0	07-04-2014
qtxml4.dll	4.8.1.0	07-04-2014

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
DMDB Firmware	5.00.002 6.2 5.3	09-26-2014

	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 26 of 89

## VERSION: 2.9.7.0

Release date: 14 august 2015

## BUG

[[IPRINT-725](#)] - [TN2015038] Start button disabled in operator mode if lineHoleCounter is used, in FFPS or LocalJob mode

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
configupdate.exe	1.1.4.1	06-17-2015
lpkBackup.exe	1.0.4.2	06-16-2015
i-dtpnetlibrary.dll	1.1.7.0	11-12-2014
impikafiberopticboard.dll	4.0.0.0	01-21-2015
cpnetlibrary.dll	5.1.0.0	01-21-2015
virtualkeyboard.dll	1.0.0.5	06-09-2014
virtualkeypad.dll	1.0.0.3	05-28-2015
vst_matti.dll	1.0.1.0	06-12-2015
serialportcom.dll	1.0.9.0	11-12-2014
iLog	1.0.0.0	03-26-2015
i600configuration.dll	1.3.0.0	03-23-2015
signaturetools.exe	1.0.0.3	03-26-2015
skinx.dll	1.0.0.7	02-05-2015
languageresource.dll	1.0.0.0	11-12-2014
mfcguiext.dll	1.0.0.2	11-12-2014
sqlite3.dll	-	11-12-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	11-12-2014
dbghelp.dll	6.12.2.633	11-12-2014
mxio.dll	2.7.0.0	11-12-2014
paexec.exe	1.25.0.0	11-12-2014
xcmd.exe	1.0.0.1	11-12-2014
xcrashhandler.dll	1.0.0.1	11-12-2014
xcrashreport.exe	1.0.0.2	11-12-2014

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
configupdate.exe	1.1.4.1	06-17-2015
lpkBackup.exe	1.0.4.2	06-16-2015
i-dtpnetlibrary.dll	1.1.7.0	11-12-2014
impikafiberopticboard.dll	4.0.0.0	01-21-2015
cpnetlibrary.dll	5.1.0.0	01-21-2015
virtualkeyboard.dll	1.0.0.5	06-09-2014
virtualkeypad.dll	1.0.0.3	05-28-2015
vst_matti.dll	1.0.1.0	06-12-2015
serialportcom.dll	1.0.9.0	11-12-2014

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 27 of 89

iLog	1.0.0.0	03-26-2015
i600configuration.dll	1.3.0.0	03-23-2015
signaturetools.exe	1.0.0.3	03-26-2015
skinx.dll	1.0.0.7	02-05-2015
languageresource.dll	1.0.0.0	11-12-2014
mfcguiext.dll	1.0.0.2	11-12-2014
sqlite3.dll	-	11-12-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	11-12-2014
dbghelp.dll	6.12.2.633	11-12-2014
mxio.dll	2.7.0.0	11-12-2014
paexec.exe	1.25.0.0	11-12-2014
xcmd.exe	1.0.0.1	11-12-2014
xcrashhandler.dll	1.0.0.1	11-12-2014
xcrashreport.exe	1.0.0.2	11-12-2014

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
DMDB Firmware	5.00.002 6.2 5.3	09-26-2014

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 28 of 89

## VERSION: 2.9.6.0

Release date: 27 july 2015

### BUG

- [\[IPRINT-716\]](#) - [TN6343\_XeroxChoregie\_France : N°Ticket20150280 [Sev.3] - degassing error] Degassing Error 1000: sometimes the pump doesn't reach the asked pressure
- [\[IPRINT-718\]](#) - Hide PBX Warning message : Jetter Module Expired
- [\[IPRINT-719\]](#) - Add counter unit : Custom page

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
i600mmi.exe	<b>2.9.6.0</b>	<b>07-20-2015</b>
pbx661controller.exe	<b>3.5.5.0</b>	<b>07-20-2015</b>
cddjobfile.dll	3.0.3.0	01-21-2015
printdataprovider_jcontroller.dll	1.4.0.0	11-28-2014
printdataprovider_jobfile.dll	4.7.1.0	11-12-2014

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
configupdate.exe	1.1.4.1	06-17-2015
lpkBackup.exe	1.0.4.2	06-16-2015
i-dtpnetlibrary.dll	1.1.7.0	11-12-2014
impikafiberopticboard.dll	4.0.0.0	01-21-2015
cpnetlibrary.dll	5.1.0.0	01-21-2015
virtualkeyboard.dll	1.0.0.5	06-09-2014
virtualkeypad.dll	1.0.0.3	05-28-2015
vst_matti.dll	1.0.1.0	06-12-2015
serialportcom.dll	1.0.9.0	11-12-2014
iLog	1.0.0.0	03-26-2015
i600configuration.dll	1.3.0.0	03-23-2015
signaturetools.exe	1.0.0.3	03-26-2015
skinx.dll	1.0.0.7	02-05-2015
languageresource.dll	1.0.0.0	11-12-2014
mfcguiext.dll	1.0.0.2	11-12-2014
sqlite3.dll	-	11-12-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	11-12-2014
dbghelp.dll	6.12.2.633	11-12-2014
mxio.dll	2.7.0.0	11-12-2014
paexec.exe	1.25.0.0	11-12-2014
xcmd.exe	1.0.0.1	11-12-2014
xcrashhandler.dll	1.0.0.1	11-12-2014
xcrashreport.exe	1.0.0.2	11-12-2014

	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 29 of 89

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
DMDB Firmware	5.00.002 6.2 5.3	09-26-2014

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 30 of 89

## VERSION: 2.9.5.0

Release date: 09 july 2015

### BUG

- [\[IPRINT-717\]](#) - Windows XP incompatibility

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
i600mmi.exe	<b>2.9.5.0</b>	<b>07-09-2015</b>
pbx661controller.exe	<b>3.5.4.0</b>	<b>07-09-2015</b>
cddjobfile.dll	3.0.3.0	01-21-2015
printdataprovider_icontroller.dll	1.4.0.0	11-28-2014
printdataprovider_jobfile.dll	4.7.1.0	11-12-2014

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
configupdate.exe	1.1.4.1	06-17-2015
lpkBackup.exe	1.0.4.2	06-16-2015
i-dtpnetlibrary.dll	1.1.7.0	11-12-2014
impikafiberopticboard.dll	4.0.0.0	01-21-2015
cpnetlibrary.dll	5.1.0.0	01-21-2015
virtualkeyboard.dll	1.0.0.5	06-09-2014
virtualkeypad.dll	1.0.0.3	05-28-2015
vst_matti.dll	1.0.1.0	06-12-2015
serialportcom.dll	1.0.9.0	11-12-2014
iLog	1.0.0.0	03-26-2015
i600configuration.dll	1.3.0.0	03-23-2015
signaturetools.exe	1.0.0.3	03-26-2015
skinx.dll	1.0.0.7	02-05-2015
languageresource.dll	1.0.0.0	11-12-2014
mfcguiext.dll	1.0.0.2	11-12-2014
sqlite3.dll	-	11-12-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	11-12-2014
dbghelp.dll	6.12.2.633	11-12-2014
mxio.dll	2.7.0.0	11-12-2014
paexec.exe	1.25.0.0	11-12-2014
xcmd.exe	1.0.0.1	11-12-2014
xcrashhandler.dll	1.0.0.1	11-12-2014
xcrashreport.exe	1.0.0.2	11-12-2014

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
DMDB Firmware	5.00.002 6.2 5.3	09-26-2014

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 31 of 89

## VERSION: 2.9.4.0

Release date: 15 june 2015

### BUG

- [\[IPRINT-698\]](#) - ConfigUpdate: Enforce the correct value for "RemotelCCProfilesAbsolutePath" for FFPS Data Provider
- [\[IPRINT-711\]](#) - Speed is limited to 10m/min if status bit TOP\_COVER\_LATCHED is enabled
- [\[IPRINT-712\]](#) - Snapshot can be named with invalid character for windows
- [\[IPRINT-713\]](#) - ConfigUpdate : File name with special characters can't be open

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
i600mmi.exe	<b>2.9.4.0</b>	<b>06-17-2015</b>
pbx661controller.exe	<b>3.5.3.2</b>	<b>06-12-2015</b>
cddjobfile.dll	3.0.3.0	01-21-2015
printdataprovder_jcontroller.dll	1.4.0.0	11-28-2014
printdataprovder_jobfile.dll	4.7.1.0	11-12-2014

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
configupdate.exe	<b>1.1.4.1</b>	<b>06-17-2015</b>
lpkBackup.exe	<b>1.0.4.2</b>	<b>06-16-2015</b>
i-dtpnetlibrary.dll	1.1.7.0	11-12-2014
impikafiberopticboard.dll	4.0.0.0	01-21-2015
cpnetlibrary.dll	5.1.0.0	01-21-2015
virtualkeyboard.dll	<b>1.0.0.5</b>	<b>06-09-2014</b>
virtualkeypad.dll	1.0.0.3	05-28-2015
vst_matti.dll	<b>1.0.1.0</b>	<b>06-12-2015</b>
serialportcom.dll	1.0.9.0	11-12-2014
iLog	1.0.0.0	03-26-2015
i600configuration.dll	1.3.0.0	03-23-2015
signaturetools.exe	1.0.0.3	03-26-2015
skinx.dll	1.0.0.7	02-05-2015
languageresource.dll	1.0.0.0	11-12-2014
mfcguiext.dll	1.0.0.2	11-12-2014
sqlite3.dll	-	11-12-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	11-12-2014
dbghelp.dll	6.12.2.633	11-12-2014
mxio.dll	2.7.0.0	11-12-2014
paexec.exe	1.25.0.0	11-12-2014

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 32 of 89

xcmd.exe	1.0.0.1	11-12-2014
xcrashhandler.dll	1.0.0.1	11-12-2014
xcrashreport.exe	1.0.0.2	11-12-2014

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
DMDB Firmware	5.00.002 6.2 5.3	09-26-2014



	<b>Technical Note</b>	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 33 of 89

## VERSION: 2.9.3.0

Release date: 18 may 2015

### NEW FEATURE /IMPROVEMENT

- [\[IPRINT-463\]](#) - Display EPSIB version in traces

### BUG

- [\[IPRINT-666\]](#) - IPDS file versions are not displayed
- [\[IPRINT-692\]](#) - Speed limitation is not correctly updated when switching from HighSpeed to VHQ mode
- [\[IPRINT-694\]](#) - IpkBackup: Perform a complete cleaning of temporary files before backup
- [\[IPRINT-695\]](#) - IpkBackup: Hide progress bar on MMI PC
- [\[IPRINT-696\]](#) - ConfigUpdate: Update IP addresses for newer interface to FFPS
- [\[IPRINT-697\]](#) - ConfigUpdate: Enable pattern printing mode for iController and FFPS

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
<b>i600mmi.exe</b>	<b>2.9.3.0</b>	<b>05-18-2015</b>
<b>pbx661controller.exe</b>	<b>3.5.3.0</b>	<b>05-18-2015</b>
cddjobfile.dll	3.0.3.0	01-21-2015
printdatapvider_icontroller.dll	1.4.0.0	11-28-2014
printdatapvider_jobfile.dll	4.7.1.0	11-12-2014

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
<b>configupdate.exe</b>	<b>1.1.3.0</b>	<b>05-18-2015</b>
<b>lpkBackup.exe</b>	<b>1.0.4.0</b>	<b>05-18-2015</b>
i-dtpnetlibrary.dll	1.1.7.0	11-12-2014
impikafiberboard.dll	4.0.0.0	01-21-2015
cpnetlibrary.dll	5.1.0.0	01-21-2015
virtualkeyboard.dll	1.0.0.5	11-12-2014
virtualkeypad.dll	1.0.0.3	11-12-2014
vst_matti.dll	1.0.0.7	03-23-2014
serialportcom.dll	1.0.9.0	11-12-2014
iLog	1.0.0.0	03-26-2015
i600configuration.dll	1.3.0.0	03-23-2015
signaturetools.exe	1.0.0.3	03-26-2015
skinx.dll	1.0.0.7	02-05-2015
languageresource.dll	1.0.0.0	11-12-2014
mfcguiext.dll	1.0.0.2	11-12-2014
sqlite3.dll	-	11-12-2014

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 34 of 89

pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	11-12-2014
dbgghelp.dll	6.12.2.633	11-12-2014
mxio.dll	2.7.0.0	11-12-2014
paexec.exe	1.25.0.0	11-12-2014
xcmd.exe	1.0.0.1	11-12-2014
xcrashhandler.dll	1.0.0.1	11-12-2014
xcrashreport.exe	1.0.0.2	11-12-2014

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
DMDB Firmware	5.00.002 <b>6.2 5.3</b>	09-26-2014

	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 35 of 89

## VERSION: 2.9.2.0

Release date: 28 apr 2015

### NEW FEATURE /IMPROVEMENT

- [\[IPRINT-680\]](#) - ConfigUpdate : Activate TRC Feature in FFPS
- [\[IPRINT-690\]](#) - Replace MMI command prompt by splashscreen with a wait timer at startup

### BUG

- [\[IPRINT-683\]](#) - Languages Front and Back swapped
- [\[IPRINT-684\]](#) - Translation: update French translation for "Shutdown printer\nPrinter only"
- [\[IPRINT-685\]](#) - [TN20150188] FlushLine using thickness User's Defined doesn't work with other languages then english
- [\[IPRINT-686\]](#) - UI\_DIRECTORY field in Configuration.ini must end by a '/'
- [\[IPRINT-689\]](#) - Display the choosen counter unit on the main screen
- [\[IPRINT-691\]](#) - update dialog name in the popup selector of PrintDataProvider display on the MainScreen
- [\[IPRINT-666\]](#) - IPDS file versions are not displayed
- [\[IPRINT-678\]](#) - AutoCheck Error is not displayed when "Custom Overlap" is disabled and "Cue Sensor" is activated on Back side.
- [\[IPRINT-679\]](#) - AutoCheck Error is not displayed when a cue mark position is invalid and some cue marks overlap on Back side.
- [\[IPRINT-681\]](#) - ProductionLog still export logs when autoexport feature is disabled
- [\[IPRINT-682\]](#) - In AutoExport GUI screen, Controls stay editable if AutoExport is not checked
- [\[IPRINT-687\]](#) - Display the selected unit for printed counter on the main screen
- [\[IPRINT-688\]](#) - PDP Popup selector on the main screen don't have the good title

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
i600mmi.exe	<b>2.9.2.0</b>	<b>04-28-2015</b>
pbx661controller.exe	<b>3.5.2.0</b>	<b>04-28-2015</b>
cddjobfile.dll	3.0.3.0	01-21-2015
printdatapvider_icontroller.dll	1.4.0.0	11-28-2014
printdatapvider_jobfile.dll	4.7.1.0	11-12-2014

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
configupdate.exe	<b>1.1.3.0</b>	<b>04-28-2015</b>
i-dtpnetlibrary.dll	1.1.7.0	11-12-2014

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 36 of 89

impikafiberopticboard.dll	4.0.0.0	01-21-2015
cpnetlibrary.dll	5.1.0.0	01-21-2015
virtualkeyboard.dll	1.0.0.5	11-12-2014
virtualkeypad.dll	1.0.0.3	11-12-2014
vst_matti.dll	1.0.0.7	03-23-2014
serialportcom.dll	1.0.9.0	11-12-2014
iLog	1.0.0.0	03-26-2015
i600configuration.dll	1.3.0.0	03-23-2015
signaturetools.exe	1.0.0.3	03-26-2015
skinx.dll	1.0.0.7	02-05-2015
languageresource.dll	1.0.0.0	11-12-2014
mfcguiext.dll	1.0.0.2	11-12-2014
sqlite3.dll	-	11-12-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	11-12-2014
dbghelp.dll	6.12.2.633	11-12-2014
mxio.dll	2.7.0.0	11-12-2014
paexec.exe	1.25.0.0	11-12-2014
xcmd.exe	1.0.0.1	11-12-2014
xcrashhandler.dll	1.0.0.1	11-12-2014
xcrashreport.exe	1.0.0.2	11-12-2014

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
DMDB Firmware	5.00.002 6.2 5.3	09-26-2014

 A Xerox Company	<h1>Technical Note</h1>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<h2>Suivi de version iPrint &amp; iPress</h2>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 37 of 89

### VERSION: 2.9.1.0

Release date: 03 apr 2015

### NEW FEATURE /IMPROVEMENT

- [\[IPRINT-482\]](#) - Create UDP/IP communication test program for the new WebGuide
- [\[IPRINT-483\]](#) - Integrate the new WebGuide to the MMI
- [\[IPRINT-485\]](#) - Modification of slanting code to perform the reverse printing
- [\[IPRINT-633\]](#) - Rebranding: Add splash screen at startup
- [\[IPRINT-634\]](#) - Rebranding: New about screen background
- [\[IPRINT-635\]](#) - Rebranding: Remove Impika Logo from title bar.
- [\[IPRINT-636\]](#) - Rebranding: Display new branding colors in main mimic
- [\[IPRINT-372\]](#) - VST Impika Continuous Feed Dynamic Library
- [\[IPRINT-415\]](#) - eXtreme: CWS Purge process modification
- [\[IPRINT-418\]](#) - eXtreme: New transport communication
- [\[IPRINT-419\]](#) - eXtreme: New transport communication Test program
- [\[IPRINT-422\]](#) - eXtreme: Ethernet-MTPB Protocol Implementation and Test Program
- [\[IPRINT-426\]](#) - eXtreme: Main Screen modification for TED11
- [\[IPRINT-602\]](#) - ConfigUpdate: Add FFPS specific Configuration strings and corrections to the Machine Definition xml
- [\[IPRINT-628\]](#) - Backup MMI configuration on all computers
- [\[IPRINT-649\]](#) - [TN20140650] Chose the counter unit displayed on the main screen
- [\[IPRINT-650\]](#) - Share the TRC Profiles folder.

### BUG

- [\[IPRINT-632\]](#) - Automatic filling don't check waste tank state
- [\[IPRINT-646\]](#) - Odd and EVEN label are reversed in Override Drop Size panel.
- [\[IPRINT-648\]](#) - [TN20150014] Autocheck: if the front cue mark is inside the Job, error "Back cue sensor is activated without front cue mark" should not be displayed
- [\[IPRINT-656\]](#) - PBX cannot start if IP 192.168.11.xxx is not connected to a network.
- [\[IPRINT-657\]](#) - Maintenance Screen: Flash operation deactivates the start button
- [\[IPRINT-671\]](#) - New loaded snapshot marked as modified when printing mode is changed
- [\[IPRINT-672\]](#) - [TN20150114] Ink leakage in the printer due to Meniscus blown fuse
- [\[IPRINT-674\]](#) - AutoCheck LineHoleCounter : Remove the auto check when the data provider is local job
- [\[IPRINT-675\]](#) - PrintLayoutDlg : Control display are not based on the good feature.
- [\[IPRINT-667\]](#) - Error "Line Hole Counter is activated without Pin Feed Emulation" is visible in LocalJob mode
- [\[IPRINT-668\]](#) - [TN20150065] deconnection host IPDS

	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 38 of 89

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
<b>i600mmi.exe</b>	<b>2.9.1.0</b>	<b>03-27-2015</b>
<b>pbx661controller.exe</b>	<b>3.5.1.0</b>	<b>03-27-2015</b>
cddjobfile.dll	3.0.3.0	01-21-2015
printdatapvider_icontroller.dll	1.4.0.0	11-28-2014
printdatapvider_jobfile.dll	4.7.1.0	11-12-2014

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
<b>configupdate.exe</b>	<b>1.1.2.0</b>	<b>03-26-2015</b>
i-dtpnetlibrary.dll	1.1.7.0	11-12-2014
impikafiberboard.dll	4.0.0.0	01-21-2015
<b>cpnetlibrary.dll</b>	<b>5.1.0.0</b>	<b>01-21-2015</b>
virtualkeyboard.dll	1.0.0.5	11-12-2014
virtualkeypad.dll	1.0.0.3	11-12-2014
vst_matti.dll	1.0.0.7	03-23-2014
serialportcom.dll	1.0.9.0	11-12-2014
iLog	1.0.0.0	03-26-2015
i600configuration.dll	1.3.0.0	03-23-2015
signaturetools.exe	1.0.0.3	03-26-2015
skinx.dll	1.0.0.7	02-05-2015
languageresource.dll	1.0.0.0	11-12-2014
mfcguiext.dll	1.0.0.2	11-12-2014
sqlite3.dll	-	11-12-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	11-12-2014
dbghelp.dll	6.12.2.633	11-12-2014
mxio.dll	2.7.0.0	11-12-2014
paexec.exe	1.25.0.0	11-12-2014
xcmd.exe	1.0.0.1	11-12-2014
xcrashhandler.dll	1.0.0.1	11-12-2014
xcrashreport.exe	1.0.0.2	11-12-2014

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
DMDB Firmware	5.00.002 6.2 5.3	09-26-2014

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 39 of 89

## VERSION: 2.8.7.0

Release date: 25 mar 2015

### BUG

- [\[IPRINT-669\]](#) - [TN20150065] deconnection host IPDS

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
i600mmi.exe	<b>2.8.7.0</b>	<b>03-25-2015</b>
pbx661controller.exe	<b>3.4.4.0</b>	<b>03-25-2015</b>
cddjobfile.dll	3.0.3.0	11-07-2014
printdataprovider_icontroller.dll	1.4.0.0	11-28-2014
printdataprovider_jobfile.dll	4.7.1.0	09-19-2014

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
configupdate.exe	1.1.1.0	03-16-2015
i-dtpnetlibrary.dll	1.1.7.0	09-19-2014
impikafiberopticboard.dll	4.0.0.0	11-07-2014
cpnetlibrary.dll	5.1.0.0	02-12-2015
virtualkeyboard.dll	1.0.0.5	09-19-2014
virtualkeypad.dll	1.0.0.3	09-19-2014
vst_matti.dll	1.0.0.7	12-10-2014
vst_xl.dll	1.0.0.5	12-10-2014
serialportcom.dll	1.0.9.0	09-19-2014
iLog	1.0.0.0	12-10-2014
i600configuration.dll	1.3.0.0	12-10-2014
signaturetools.exe	1.0.0.3	12-10-2014
skinx.dll	1.0.0.7	09-19-2014
languageresource.dll	1.0.0.0	09-19-2014
mfcguiext.dll	1.0.0.2	09-19-2014
sqlite3.dll	-	09-19-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	09-19-2014
dbgghelp.dll	6.12.2.633	09-19-2014
mxio.dll	2.7.0.0	09-19-2014
paexec.exe	1.25.0.0	09-19-2014
xcmd.exe	1.0.0.1	09-19-2014
xcrashhandler.dll	1.0.0.1	09-19-2014
xcrashreport.exe	1.0.0.2	09-19-2014

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
DMDB Firmware	5.00.002 6.2 5.3	09-26-2014

	<b>Technical Note</b>	Reference: 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 40 of 89

## VERSION: 2.8.7.0

Release date: 25 mar 2015

### BUG

- [\[IPRINT-669\]](#) – Host IPDS disconnected

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
<b>i600mmi.exe</b>	<b>2.8.7.0</b>	<b>03-25-2015</b>
<b>pbx661controller.exe</b>	<b>3.4.4.0</b>	<b>03-25-2015</b>
cddjobfile.dll	3.0.3.0	11-07-2014
printdatapvider_icontroller.dll	1.4.0.0	11-28-2014
printdatapvider_jobfile.dll	4.7.1.0	09-19-2014

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
configupdate.exe	1.1.1.0	03-16-2015
i-dtpnetlibrary.dll	1.1.7.0	09-19-2014
impikafiberboard.dll	4.0.0.0	11-07-2014
cpnetlibrary.dll	5.1.0.0	02-12-2015
virtualkeyboard.dll	1.0.0.5	09-19-2014
virtualkeypad.dll	1.0.0.3	09-19-2014
vst_matti.dll	1.0.0.7	12-10-2014
vst_xl.dll	1.0.0.5	12-10-2014
serialportcom.dll	1.0.9.0	09-19-2014
iLog	1.0.0.0	12-10-2014
i600configuration.dll	1.3.0.0	12-10-2014
signaturetools.exe	1.0.0.3	12-10-2014
skinx.dll	1.0.0.7	09-19-2014
languageresource.dll	1.0.0.0	09-19-2014
mfcguiext.dll	1.0.0.2	09-19-2014
sqlite3.dll	-	09-19-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	09-19-2014
dbghelp.dll	6.12.2.633	09-19-2014
mxio.dll	2.7.0.0	09-19-2014
paexec.exe	1.25.0.0	09-19-2014
xcmd.exe	1.0.0.1	09-19-2014
xcrashhandler.dll	1.0.0.1	09-19-2014
xcrashreport.exe	1.0.0.2	09-19-2014

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
DMDB Firmware	5.00.002 6.2 5.3	09-26-2014



	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 41 of 89

## VERSION: 2.8.6.0

Release date: 18 mar 2015

### BUG

- [\[IPRINT-673\]](#) - PBX doesn't support half inch extra width when EmulatePinFeedPrinter is activated

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
<b>i600mmi.exe</b>	<b>2.8.6.0</b>	<b>03-18-2015</b>
<b>pbx661controller.exe</b>	<b>3.4.3.0</b>	<b>03-18-2015</b>
cddjobfile.dll	3.0.3.0	11-07-2014
printdataprovder_icontroller.dll	1.4.0.0	11-28-2014
printdataprovder_jobfile.dll	4.7.1.0	09-19-2014

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
<b>configupdate.exe</b>	<b>1.1.1.0</b>	<b>03-16-2015</b>
i-dtpnetlibrary.dll	1.1.7.0	09-19-2014
impikafiberboard.dll	4.0.0.0	11-07-2014
<b>cpnetlibrary.dll</b>	<b>5.1.0.0</b>	<b>02-12-2015</b>
virtualkeyboard.dll	1.0.0.5	09-19-2014
virtualkeypad.dll	1.0.0.3	09-19-2014
vst_matti.dll	1.0.0.7	12-10-2014
vst_xl.dll	1.0.0.5	12-10-2014
serialportcom.dll	1.0.9.0	09-19-2014
iLog	1.0.0.0	12-10-2014
i600configuration.dll	1.3.0.0	12-10-2014
signaturetools.exe	1.0.0.3	12-10-2014
skinx.dll	1.0.0.7	09-19-2014
languageresource.dll	1.0.0.0	09-19-2014
mfcguiext.dll	1.0.0.2	09-19-2014
sqlite3.dll	-	09-19-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	09-19-2014
dbgghelp.dll	6.12.2.633	09-19-2014
mxio.dll	2.7.0.0	09-19-2014
paexec.exe	1.25.0.0	09-19-2014
xcmd.exe	1.0.0.1	09-19-2014
xcrashhandler.dll	1.0.0.1	09-19-2014
xcrashreport.exe	1.0.0.2	09-19-2014

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
DMDB Firmware	5.00.002 6.2 5.3	09-26-2014

 A Xerox Company	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 42 of 89

## VERSION: 2.8.5.0

Release date: 16 feb 2015

**Warning: this version requires a DMDB firmware Update!**

### **BUG**

- [\[IPRINT-664\]](#) - Emulate Pin Feed Paper option crop the image in 1/2 inch of the hole area
- [\[IPRINT-665\]](#) - UpdateMachineDefinition.bat improved to update all MachineDefinition files and associated Snapshots.

	<b>Technical Note</b>	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 43 of 89

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
<b>i600mmi.exe</b>	<b>2.8.5.0</b>	<b>02-16-2015</b>
<b>pbx661controller.exe</b>	<b>3.4.2.0</b>	<b>02-16-2015</b>
cddjobfile.dll	3.0.3.0	11-07-2014
printdataprovder_icontroller.dll	1.4.0.0	11-28-2014
printdataprovder_jobfile.dll	4.7.1.0	09-19-2014

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
configupdate.exe	1.1.0.0	12-10-2014
i-dtpnetlibrary.dll	1.1.7.0	09-19-2014
impikafiberopticboard.dll	4.0.0.0	11-07-2014
cpnetlibrary.dll	4.0.1.0	09-19-2014
virtualkeyboard.dll	1.0.0.5	09-19-2014
virtualkeypad.dll	1.0.0.3	09-19-2014
vst_matti.dll	1.0.0.7	12-10-2014
vst_xl.dll	1.0.0.5	12-10-2014
serialportcom.dll	1.0.9.0	09-19-2014
iLog	1.0.0.0	12-10-2014
i600configuration.dll	1.3.0.0	12-10-2014
signaturetools.exe	1.0.0.3	12-10-2014
skinx.dll	1.0.0.7	09-19-2014
languageresource.dll	1.0.0.0	09-19-2014
mfcguiext.dll	1.0.0.2	09-19-2014
sqlite3.dll	-	09-19-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	09-19-2014
dbgghelp.dll	6.12.2.633	09-19-2014
mxio.dll	2.7.0.0	09-19-2014
paexec.exe	1.25.0.0	09-19-2014
xcmd.exe	1.0.0.1	09-19-2014
xcrashhandler.dll	1.0.0.1	09-19-2014
xcrashreport.exe	1.0.0.2	09-19-2014

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
<b>DMDB Firmware</b>	<b>5.00.002 6.2 5.3</b>	<b>09-26-2014</b>

 A Xerox Company	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 44 of 89

## VERSION: 2.8.4.0

Release date: 06 feb 2015

**Warning: this version requires a DMDB firmware Update!**

### **BUG**

- [\[IPRINT-661\]](#) - ConfigUpdate : Auto creation of missing iEngine in configuration to reach 12 printheads
- [\[IPRINT-662\]](#) - ConfigUpdate : Update IPDS Enabled state in Snapshots according to MachineDefinition
- [\[IPRINT-663\]](#) - Acknowledge error button doesn't work with configuration with non-continuous printheads position

 A Xerox Company	<h1>Technical Note</h1>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<h2>Suivi de version iPrint &amp; iPress</h2>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 45 of 89

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
i600mmi.exe	<b>2.8.4.0</b>	<b>02-05-2015</b>
pbx661controller.exe	3.4.1.0	12-23-2014
cddjobfile.dll	3.0.3.0	11-07-2014
printdatapvider_icontroller.dll	1.4.0.0	11-28-2014
printdatapvider_jobfile.dll	4.7.1.0	09-19-2014

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
configupdate.exe	1.1.0.0	12-10-2014
i-dtpnetlibrary.dll	1.1.7.0	09-19-2014
impikafiberopticboard.dll	4.0.0.0	11-07-2014
cpnetlibrary.dll	4.0.1.0	09-19-2014
virtualkeyboard.dll	1.0.0.5	09-19-2014
virtualkeypad.dll	1.0.0.3	09-19-2014
vst_matti.dll	1.0.0.7	12-10-2014
vst_xl.dll	1.0.0.5	12-10-2014
serialportcom.dll	1.0.9.0	09-19-2014
iLog	1.0.0.0	12-10-2014
i600configuration.dll	1.3.0.0	12-10-2014
signaturetools.exe	1.0.0.3	12-10-2014
skinx.dll	1.0.0.7	09-19-2014
languageresource.dll	1.0.0.0	09-19-2014
mfcguiext.dll	1.0.0.2	09-19-2014
sqlite3.dll	-	09-19-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	09-19-2014
dbgghelp.dll	6.12.2.633	09-19-2014
mxio.dll	2.7.0.0	09-19-2014
paexec.exe	1.25.0.0	09-19-2014
xcmd.exe	1.0.0.1	09-19-2014
xcrashhandler.dll	1.0.0.1	09-19-2014
xcrashreport.exe	1.0.0.2	09-19-2014

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
<b>DMDB Firmware</b>	<b>5.00.002 6.2 5.3</b>	<b>09-26-2014</b>

 A Xerox Company	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 46 of 89

## VERSION: 2.8.3.0

Release date: 19 dec 2014

**Warning: this version requires a DMDB firmware Update!**

### BUG

- [\[IPRINT-587\]](#) - [TN20140651] Flush lines are printed outside of the media.
- [\[IPRINT-643\]](#) - Windows XP compatibility: load license button don't display the file search window.
- [\[IPRINT-644\]](#) - Windows XP compatibility: Production log and About screens are not displayed correctly.

	<h1>Technical Note</h1>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<h2>Suivi de version iPrint &amp; iPress</h2>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 47 of 89

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
<b>i600mmi.exe</b>	<b>2.8.3.0</b>	<b>12-18-2014</b>
<b>pbx661controller.exe</b>	<b>3.4.1.0</b>	<b>12-08-2014</b>
cddjobfile.dll	3.0.3.0	11-07-2014
<b>printdataprotider_icontroller.dll</b>	<b>1.4.0.0</b>	<b>11-28-2014</b>
printdataprotider_jobfile.dll	4.7.1.0	09-19-2014

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
configupdate.exe	1.1.0.0	12-10-2014
i-dtpnetlibrary.dll	1.1.7.0	09-19-2014
impikafiberopticboard.dll	4.0.0.0	11-07-2014
cpnetlibrary.dll	4.0.1.0	09-19-2014
virtualkeyboard.dll	1.0.0.5	09-19-2014
virtualkeypad.dll	1.0.0.3	09-19-2014
vst_matti.dll	1.0.0.7	12-10-2014
vst_xl.dll	1.0.0.5	12-10-2014
serialportcom.dll	1.0.9.0	09-19-2014
iLog	1.0.0.0	12-10-2014
i600configuration.dll	1.3.0.0	12-10-2014
signaturetools.exe	1.0.0.3	12-10-2014
skinx.dll	1.0.0.7	09-19-2014
languageresource.dll	1.0.0.0	09-19-2014
mfcguiext.dll	1.0.0.2	09-19-2014
sqlite3.dll	-	09-19-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	09-19-2014
dbgghelp.dll	6.12.2.633	09-19-2014
mxio.dll	2.7.0.0	09-19-2014
paexec.exe	1.25.0.0	09-19-2014
xcmd.exe	1.0.0.1	09-19-2014
xcrashhandler.dll	1.0.0.1	09-19-2014
xcrashreport.exe	1.0.0.2	09-19-2014

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
<b>DMDB Firmware</b>	<b>5.00.002 6.2 5.3</b>	<b>09-26-2014</b>

 A Xerox Company	<h1>Technical Note</h1>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<h2>Suivi de version iPrint &amp; iPress</h2>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 48 of 89

### VERSION: 2.8.2.0

Release date: 10 dec 2014

**Warning: this version requires a DMDB firmware Update!**

### BUG

- [\[IPRINT-614\]](#) - [TN20140591] Production Logs is disabled by the AutoExport checkbox
- [\[IPRINT-616\]](#) - Features expired are still activated
- [\[IPRINT-617\]](#) - [TN20140579] IPDS Job names are not saved in the production log database
- [\[IPRINT-627\]](#) - [TN20140482] Consumption counters are different with or without flushlines and cuemarks
- [\[IPRINT-629\]](#) - Windows XP compatibility lost



	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 49 of 89

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
<b>i600mmi.exe</b>	<b>2.8.2.0</b>	<b>12-08-2014</b>
<b>pbx661controller.exe</b>	<b>3.4.1.0</b>	<b>12-08-2014</b>
cddjobfile.dll	3.0.3.0	11-07-2014
<b>printdatapvider_icontroller.dll</b>	<b>1.4.0.0</b>	<b>11-28-2014</b>
printdatapvider_jobfile.dll	4.7.1.0	09-19-2014

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
configupdate.exe	1.1.0.0	12-10-2014
i-dtpnetlibrary.dll	1.1.7.0	09-19-2014
impikafiberopticboard.dll	4.0.0.0	11-07-2014
cpnetlibrary.dll	4.0.1.0	09-19-2014
virtualkeyboard.dll	1.0.0.5	09-19-2014
virtualkeypad.dll	1.0.0.3	09-19-2014
vst_matti.dll	1.0.0.7	12-10-2014
vst_xl.dll	1.0.0.5	12-10-2014
serialportcom.dll	1.0.9.0	09-19-2014
iLog	1.0.0.0	12-10-2014
i600configuration.dll	1.3.0.0	12-10-2014
signaturetools.exe	1.0.0.3	12-10-2014
skinx.dll	1.0.0.7	09-19-2014
languageresource.dll	1.0.0.0	09-19-2014
mfcguiext.dll	1.0.0.2	09-19-2014
sqlite3.dll	-	09-19-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	09-19-2014
dbgghelp.dll	6.12.2.633	09-19-2014
mxio.dll	2.7.0.0	09-19-2014
paexec.exe	1.25.0.0	09-19-2014
xcmd.exe	1.0.0.1	09-19-2014
xcrashhandler.dll	1.0.0.1	09-19-2014
xcrashreport.exe	1.0.0.2	09-19-2014

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
<b>DMDB Firmware</b>	<b>5.00.002 6.2 5.3</b>	<b>09-26-2014</b>

	<h1>Technical Note</h1>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<h2>Suivi de version iPrint &amp; iPress</h2>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 50 of 89

## VERSION: 2.8.1.0

Release date: 19 nov 2014

**Warning: this version requires a DMDB firmware Update!**

### NEW FEATURE /IMPROVEMENT

- [\[IPRINT-574\]](#) – VHQ support in IPDS
- TRC curve loading in IPDS
- [\[IPRINT-563\]](#) - Optional Degassing Module support
- [\[IPRINT-564\]](#) - [TN20140277] "Registration" is now available for Setup Operator
- [\[IPRINT-579\]](#) - Disable AutoFilling in Service operator
- [\[IPRINT-580\]](#) - Autocheck: Display a warning if Line Hole Counter is selected without Pin Feed Emulation.

### BUG

- [\[IPRINT-559\]](#) - In the dryer screen, the second dryer Maximum Temperature limitation is not disabled
- [\[IPRINT-577\]](#) - The TRC dialog don't display a TRC file if it contains \_C before the color letter
- [\[IPRINT-582\]](#) - PDP/CDD "Configuration" parameters were processed as for "Local Job" mode before passing them to the other PDP/CDDs
- [\[IPRINT-553\]](#) - Test ID: #01-0002: Check the media height compared to the Printlayout (disabled) - Check if autocheck detect the Media Length is smaller than the defined Print Layout
- [\[IPRINT-589\]](#) - PaExec to PsExec regression, PBX start and kill not working anymore
- [\[IPRINT-591\]](#) - [TN20140570] IPDS file version are not displayed
- [\[IPRINT-596\]](#) - ConfigUpdate: Add ScreeningTreshold default values
- [\[IPRINT-603\]](#) - [TN20140382] Main printer mimic: Head n°8 don't change color to orange during a purge operation
- [\[IPRINT-605\]](#) - [TN20140571] Sheet Grouping Delay field is overlapped in VHQ printing mode
- [\[IPRINT-608\]](#) - [TN20140573] Printer resolution is not correctly sent to PDP
- [\[IPRINT-609\]](#) - [TN20140574] ProductionLogs are not saved in the correct location
- [\[IPRINT-610\]](#) - [TN20140575] The current PDP is not updated on MainScreen when it's modified by snapshot loading

	<h1>Technical Note</h1>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<h2>Suivi de version iPrint &amp; iPress</h2>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 51 of 89

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
<b>i600mmi.exe</b>	<b>2.8.1.0</b>	<b>11-19-2014</b>
<b>pbx661controller.exe</b>	<b>3.4.0.0</b>	<b>11-13-2014</b>
cddjobfile.dll	3.0.3.0	11-07-2014
<b>printdataprotider_icontroller.dll</b>	<b>1.3.0.0</b>	<b>11-07-2014</b>
printdataprotider_jobfile.dll	4.7.1.0	10-23-2014

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
configupdate.exe	1.1.0.0	11-13-2014
i-dtpnetlibrary.dll	1.1.7.0	10-23-2014
impikafiberopticboard.dll	4.0.0.0	11-07-2014
cpnetlibrary.dll	4.0.1.0	10-23-2014
virtualkeyboard.dll	1.0.0.5	10-23-2014
virtualkeypad.dll	1.0.0.3	10-23-2014
vst_matti.dll	1.0.0.7	11-13-2014
vst_xl.dll	1.0.0.5	11-13-2014
serialportcom.dll	1.0.9.0	10-23-2014
iLog	1.0.0.0	11-13-2014
i600configuration.dll	1.3.0.0	11-13-2014
signaturetools.exe	1.0.0.3	11-13-2014
skinx.dll	1.0.0.7	10-23-2014
languageresource.dll	1.0.0.0	10-23-2014
mfcguiext.dll	1.0.0.2	10-23-2014
sqlite3.dll	-	10-23-2014
pcan_usb.dll	2.0.4.0	11-07-2014
adsapi32.dll	1.5.16.1	10-23-2014
dbgghelp.dll	6.12.2.633	10-23-2014
mxio.dll	2.7.0.0	10-23-2014
paexec.exe	1.25.0.0	10-23-2014
xcmd.exe	1.0.0.1	10-23-2014
xcrashhandler.dll	1.0.0.1	10-23-2014
xcrashreport.exe	1.0.0.2	10-23-2014

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
<b>DMDB Firmware</b>	<b>5.00.002 6.2 5.3</b>	<b>09-26-2014</b>

 A Xerox Company	<h1>Technical Note</h1>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<h2>Suivi de version iPrint &amp; iPress</h2>	<b>Version :</b> 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 52 of 89

## VERSION: 2.7.0.0

Release date: 12 sept 2014

### NEW FEATURE/ IMPROVEMENT

- [\[IPRINT-480\]](#) - Licensing: implement Xerox outbound licensing strategy for all iPrint configurations.
- [\[IPRINT-478\]](#) - [TN20140175] IPDS: Add Pinfeed emulation parameter (Pro BTP)
- [\[IPRINT-510\]](#) - Add remote servicing LogMeIn link on MMI trace screen.
- [\[IPRINT-414\]](#) - Change Language From MMI
- [\[IPRINT-417\]](#) – New Maintenance Screen to check and upload WaveForm and Firmware on MMI
- [\[IPRINT-465\]](#) - Add sharing the 2 ICC Profiles folder over network
- [\[IPRINT-513\]](#) - Remove temporary licenses before printer shipment
- [\[IPRINT-363\]](#) - ProductionLog : Provide automatic periodic log file creation
- [\[IPRINT-106\]](#) - Run local job mode Only, When IPDS initialisation Failed
- [\[IPRINT-204\]](#) - Use Panasonic Module serial numbers as rank data file signature
- [\[IPRINT-253\]](#) - Add loaded waveform name to sign Rank data file in addition to the PCC linehead modules ID
- [\[IPRINT-254\]](#) - Alert operator when rank data file signature detects a difference with the current configuration
- [\[IPRINT-356\]](#) - Add message to Err&Warn screen when connection is lost to a device
- [\[IPRINT-402\]](#) - Autocheck : a front mark is needed if printer configured to synchronize Back printing on CUE.
- [\[IPRINT-403\]](#) - Autocheck : Print layout height mustn't be greater than media height
- [\[IPRINT-404\]](#) - Autocheck : In maintenance or Service operator block start if paper length exceed the hardware limit
- [\[IPRINT-443\]](#) - ProductionLog : Improve graphic display speed
- [\[IPRINT-461\]](#) - Configuration: Add a user parameter to configure the Waiting time before starting printer in IPDS.
- [\[IPRINT-467\]](#) - [TN20130309] Auto compute pattern submitted distance
- [\[IPRINT-515\]](#) - Add HostID in saved information Parameters
- [\[IPRINT-524\]](#) - Licensing: Display the expiration message at least 30 days ahead of actual expiration

### BUG

- [\[IPRINT-15\]](#) - Impossible to reconnect IPDS controller from MMI when first IPDS initialisation Failed
- [\[IPRINT-352\]](#) - [TN20130174] Color Spacing error when Cue mark is moved in the middle of the page

 A Xerox Company	<h1>Technical Note</h1>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<h2>Suivi de version iPrint &amp; iPress</h2>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 53 of 89

- [\[IPRINT-454\]](#) - When a PBX is in error Waste Tank is Full MMI can still launch a purge on other PBX
- [\[IPRINT-459\]](#) - Autocheck : Block start button not updated if Back button is used on PrintLayout Screen.
- [\[IPRINT-469\]](#) - [TN20140117] In CSMaintenanceMode AutoPark timer is still active for Operator and Setup Operator
- [\[IPRINT-470\]](#) - [TN20140153] Media pin feed paper length is limited to 1000 mm
- [\[IPRINT-471\]](#) - ProductionLog screen not accessible the 31th
- [\[IPRINT-481\]](#) - [TN20140260] Users can't load curves and profiles with special characters
- [\[IPRINT-511\]](#) - Error when opening a compressed bitmap file from a local job.
- [\[IPRINT-514\]](#) - In the automated pattern dialog, the quantity edit box sometimes displays 1.
- [\[IPRINT-525\]](#) - [TN20140363] DropSize of iEngines in the "default" snapshot are not those of the MachineDefinition
- [\[IPRINT-531\]](#) - Internal Matching system: on Compact configuration, Head 3 is not checked for predictive control
- [\[IPRINT-533\]](#) - Disable PDP change on UI while Main Printer or PDP initialization is in progress
- [\[IPRINT-534\]](#) - Do not show PDP debug messages on the UI (ErrWarn screen)
- [\[IPRINT-548\]](#) - PrintDataProvider Job File: MediaLength in millimeter and PutSheets to send is miscomputed for square resolutions
- [\[IPRINT-523\]](#) - Trace creation should take \*.xml files from the PBX "Trace\" folder

	<b>Technical Note</b>	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 54 of 89

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
<b>i600mmi.exe</b>	<b>2.7.0.0</b>	<b>09-12-2014</b>
<b>pbx661controller.exe</b>	<b>3.3.14.0</b>	<b>09-12-2014</b>
cddjobfile.dll	3.0.3.0	07-03-2014
<b>printdatapvider_icontroller.dll</b>	<b>1.2.0.0</b>	<b>09-04-2014</b>
<b>printdatapvider_jobfile.dll</b>	<b>4.7.1.0</b>	<b>09-04-2014</b>

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
<b>configupdate.exe</b>	<b>1.1.0.0</b>	<b>09-12-2014</b>
i-dtpnetlibrary.dll	1.1.7.0	06-17-2014
impikafiberopticboard.dll	4.0.0.0	07-03-2014
cpnetlibrary.dll	4.0.1.0	06-17-2014
virtualkeyboard.dll	1.0.0.5	06-17-2014
virtualkeypad.dll	1.0.0.3	06-17-2014
vst_matti.dll	1.0.0.7	09-12-2014
vst_xl.dll	1.0.0.5	09-12-2014
serialportcom.dll	1.0.9.0	06-17-2014
<b>iLog</b>	<b>1.0.0.0</b>	<b>09-12-2014</b>
<b>i600configuration.dll</b>	<b>1.3.0.0</b>	<b>09-12-2014</b>
<b>signaturetools.exe</b>	<b>1.0.0.3</b>	<b>09-09-2014</b>
skinx.dll	1.0.0.7	06-17-2014
languageresource.dll	1.0.0.0	06-17-2014
mfcguiext.dll	1.0.0.2	06-17-2014
sqlite3.dll	-	06-17-2014
pcan_usb.dll	2.0.4.0	07-03-2014
adsapi32.dll	1.5.16.1	06-17-2014
dbgghelp.dll	6.12.2.633	06-17-2014
mxio.dll	2.7.0.0	06-17-2014
paexec.exe	1.25.0.0	06-17-2014
xcmd.exe	1.0.0.1	06-17-2014
xcrashhandler.dll	1.0.0.1	06-17-2014
xcrashreport.exe	1.0.0.2	06-17-2014

 A Xerox Company	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 55 of 89

## VERSION: 2.5.3.0

Release date: 18 juin 2014

### BUG

- [\[IPRINT-438\]](#) - IPDS need to be activated in PBX config file (PBX661ControllerHW.ini) to make the IPDS work
- [\[IPRINT-473\]](#) - License error messages are not display at startup
- [\[IPRINT-474\]](#) - The PDP Controller don't check the ParameterID to send modified values

### NEW FEATURE

- [\[IPRINT-453\]](#) - Dynamic configuration of displayed fields based on selected PDP
- [\[IPRINT-472\]](#) - XLM Outbound Licensing
- [\[IPRINT-441\]](#) - PDPJobFile : Upgrade to Meet PDPv2 requirements
- [\[IPRINT-442\]](#) - Use standard wrapper class for PrintDataProvider v2 in MMI

### TASK

- [\[IPRINT-475\]](#) - Replace PsExec by PaExec due to licensing issues

	<b>Technical Note</b>	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 56 of 89

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
<b>i600mmi.exe</b>	<b>2.5.3.0</b>	<b>06-17-2014</b>
<b>pbx661controller.exe</b>	<b>3.3.12.0</b>	<b>03-20-2014</b>
cddjobfile.dll	3.0.3.0	09-20-2013
<b>printdatapvider_icontroller.dll</b>	<b>1.1.0.0</b>	<b>06-17-2014</b>
<b>printdatapvider_jobfile.dll</b>	<b>4.5.0.0</b>	<b>06-17-2014</b>

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
<b>configupdate.exe</b>	<b>1.0.0.2</b>	<b>06-17-2014</b>
i-dtpnetlibrary.dll	1.1.7.0	10-02-2013
impikafiberopticboard.dll	4.0.0.0	09-20-2011
cpnetlibrary.dll	4.0.1.0	05-13-2014
tracecreationtools.exe	1.0.0.6	Removed
virtualkeyboard.dll	1.0.0.5	10-02-2013
virtualkeypad.dll	1.0.0.3	10-02-2013
<b>vst_matti.dll</b>	<b>1.0.0.7</b>	<b>01-28-2014</b>
<b>vst_xl.dll</b>	<b>1.0.0.5</b>	<b>01-28-2014</b>
serialportcom.dll	1.0.9.0	08-31-2011
<b>i600configuration.dll</b>	<b>1.2.1.0</b>	<b>06-17-2014</b>
signaturetools.exe	1.0.0.2	01-28-2014
skinx.dll	1.0.0.7	10-02-2013
languageresource.dll	1.0.0.0	10-02-2013
mfcguiext.dll	1.0.0.2	10-02-2013
sqlite3.dll	-	11-27-2013
pcan_usb.dll	2.0.4.0	09-20-2013
adsapi32.dll	1.5.16.1	11-15-2011
dbgghelp.dll	6.12.2.633	02-16-2012
mxio.dll	2.7.0.0	11-15-2011
psexec.exe	1.98.0.0	Removed
paexec.exe	1.25.0.0	05-16-2014
xcmd.exe	1.0.0.1	11-27-2013
xcrashhandler.dll	1.0.0.1	11-15-2011
xcrashreport.exe	1.0.0.2	11-15-2011



	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 57 of 89

## VERSION: 2.4.3.0

Release date: 2 jun 2014

### NEW FEATURE

- [\[IPRINT-476\]](#) - [TN20140161] RankData: Option in PBX to reload rank data and waveform at every machine start

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
i600mmi.exe	<b>2.4.3.0</b>	<b>05-27-2014</b>
pbx661controller.exe	<b>3.3.13.0</b>	<b>05-26-2014</b>
cddjobfile.dll	3.0.3.0	09-20-2013

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
configupdate.exe	1.0.0.1	01-28-2014
i-dtpnetlibrary.dll	1.1.7.0	10-02-2013
impikafiberopticboard.dll	4.0.0.0	09-20-2011
cpnetlibrary.dll	4.0.1.0	10-02-2013
tracecreationtools.exe	1.0.0.6	Removed
virtualkeyboard.dll	1.0.0.5	10-02-2013
virtualkeypad.dll	1.0.0.3	10-02-2013
vst_matti.dll	1.0.0.6	01-28-2014
vst_xl.dll	1.0.0.4	01-28-2014
serialportcom.dll	1.0.9.0	08-31-2011
i600configuration.dll	1.2.0.0	01-28-2014
signaturetools.exe	1.0.0.2	01-28-2014
skinx.dll	1.0.0.7	10-02-2013
languageresource.dll	1.0.0.0	10-02-2013
mfcguiext.dll	1.0.0.2	10-02-2013
sqlite3.dll	-	11-27-2013
pcan_usb.dll	2.0.4.0	09-20-2013
adsapi32.dll	1.5.16.1	11-15-2011
dbghelp.dll	6.12.2.633	02-16-2012
mxio.dll	2.7.0.0	11-15-2011
psexec.exe	1.98.0.0	11-27-2013
xcmd.exe	1.0.0.1	11-27-2013
xcrashhandler.dll	1.0.0.1	11-15-2011
xcrashreport.exe	1.0.0.2	11-15-2011

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 58 of 89

## VERSION: 2.4.2.0

Release date: 21 feb. 2014

### BUG

- [\[IPRINT-455\]](#) - [TN20140066] Impossible to drive old transport base, communication protocol incompatibility
- [\[IPRINT-456\]](#) - [TN20140072] PrintHeads temperature information display odd/even inverted on PrintHead screen
- [\[IPRINT-457\]](#) - Restore Windows Xp compatibility
- [\[IPRINT-458\]](#) - Restore '-i' option to import old counters

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
i600mmi.exe	<b>2.4.2.0</b>	<b>02-21-2014</b>
pbx661controller.exe	3.3.11.0	01-28-2014
cddjobfile.dll	3.0.3.0	09-20-2013

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
configupdate.exe	1.0.0.1	01-28-2014
i-dtpnetlibrary.dll	1.1.7.0	10-02-2013
impikafiberopticboard.dll	4.0.0.0	09-20-2011
cpnetlibrary.dll	4.0.1.0	10-02-2013
tracecreationtools.exe	1.0.0.6	Removed
virtualkeyboard.dll	1.0.0.5	10-02-2013
virtualkeypad.dll	1.0.0.3	10-02-2013
vst_matti.dll	1.0.0.6	01-28-2014
vst_xl.dll	1.0.0.4	01-28-2014
serialportcom.dll	1.0.9.0	08-31-2011
i600configuration.dll	1.2.0.0	01-28-2014
signaturetools.exe	1.0.0.2	01-28-2014
skinx.dll	1.0.0.7	10-02-2013
languageresource.dll	1.0.0.0	10-02-2013
mfcguiext.dll	1.0.0.2	10-02-2013
sqlite3.dll	-	11-27-2013
pcan_usb.dll	2.0.4.0	09-20-2013
adsapi32.dll	1.5.16.1	11-15-2011
dbghelp.dll	6.12.2.633	02-16-2012
mxio.dll	2.7.0.0	11-15-2011
psexec.exe	1.98.0.0	11-27-2013
xcmd.exe	1.0.0.1	11-27-2013
xcrashhandler.dll	1.0.0.1	11-15-2011
xcrashreport.exe	1.0.0.2	11-15-2011

 A Xerox Company	<h1>Technical Note</h1>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<h2>Suivi de version iPrint &amp; iPress</h2>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 59 of 89

## VERSION: 2.4.1.0

Release date: 28 jan. 2014

### BUG

- [\[IPRINT-425\]](#) - Switching from overridden media offset to standard media offset was not working.
- [\[IPRINT-444\]](#) - AutoCheck: Back Cue mark position where incorrectly computed if media offsets are overridden
- [\[IPRINT-413\]](#) - Save counters only save the screenshot. The csv file and binary file are not exported in the compressed package.
- [\[IPRINT-412\]](#) - Automated pattern usage lead to an MMI crash if only one page is setup in the first pattern
- [\[IPRINT-429\]](#) - [TN20130196] FlushLines bad positionning on Back
- [\[IPRINT-430\]](#) - Autocheck : print width and printable area not correctly computed in SED
- [\[IPRINT-432\]](#) - At MMI startup current SnapShot is always marked as modified
- [\[IPRINT-433\]](#) - Several Media screens don't display 2 drop sizes in VHQ mode
- [\[IPRINT-434\]](#) - When switching from VHQ mode to HighSpeed mode, 1bpp configuration is not sent to IPDS
- [\[IPRINT-435\]](#) - MMI GUI do not display the three first digit of version
- [\[IPRINT-440\]](#) - [TN20130405] DeviceLink in RGB and GreyScale are impossible to configure
- [\[IPRINT-445\]](#) - ProductionLog was not saved in case of mechanical error
- [\[IPRINT-447\]](#) - ICC profiles are not send to IPDS when the current drops size has changed
- [\[IPRINT-448\]](#) - Camera Language: Change "Datamatrix" to "verification code"
- [\[IPRINT-449\]](#) - Camera error incorrectly displayed
- [\[IPRINT-451\]](#) - Print engine state is not sent to the Camera System (SetEngineState() not called, START protocol command not sent)
- [\[IPRINT-450\]](#) - [TN20140028] PBX Crash when draw flushlines and CueMarks positions are outside the media limit

### IMPROVEMENT

- [\[IPRINT-271\]](#) - Trace creation process rewrite to increase reliability
- [\[IPRINT-428\]](#) - Production Log: Improved export speed
- [\[IPRINT-446\]](#) - Gathering Information (printer modules versions and serial numbers) and export in a CSV file

### NEW FEATURE

- [\[IPRINT-437\]](#) - IPDS: KVM Format Compatibility for transparency

	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 60 of 89

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
<b>i600mmi.exe</b>	<b>2.4.1.0</b>	<b>01-28-2014</b>
<b>pbx661controller.exe</b>	<b>3.3.11.0</b>	<b>01-28-2014</b>
cddjobfile.dll	3.0.3.0	09-20-2013

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
<b>configupdate.exe</b>	<b>1.0.0.1</b>	<b>01-28-2014</b>
i-dtpnetlibrary.dll	1.1.7.0	10-02-2013
impikafiberboard.dll	4.0.0.0	09-20-2011
cpnetlibrary.dll	4.0.1.0	10-02-2013
tracecreationtools.exe	1.0.0.6	<b>Removed</b>
virtualkeyboard.dll	1.0.0.5	10-02-2013
virtualkeypad.dll	1.0.0.3	10-02-2013
vst_matti.dll	1.0.0.6	01-28-2014
vst_xl.dll	1.0.0.4	01-28-2014
serialportcom.dll	1.0.9.0	08-31-2011
<b>i600configuration.dll</b>	<b>1.2.0.0</b>	<b>01-28-2014</b>
signaturetools.exe	1.0.0.2	01-28-2014
skinx.dll	1.0.0.7	10-02-2013
languageresource.dll	1.0.0.0	10-02-2013
mfcguiext.dll	1.0.0.2	10-02-2013
sqlite3.dll	-	11-27-2013
pcan_usb.dll	2.0.4.0	09-20-2013
adsapi32.dll	1.5.16.1	11-15-2011
<b>dbghelp.dll</b>	<b>6.12.2.633</b>	<b>02-16-2012</b>
mxio.dll	2.7.0.0	11-15-2011
psexec.exe	1.98.0.0	11-27-2013
xcmd.exe	1.0.0.1	11-27-2013
xcrashhandler.dll	1.0.0.1	11-15-2011
xcrashreport.exe	1.0.0.2	11-15-2011

 A Xerox Company	<h1>Technical Note</h1>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<h2>Suivi de version iPrint &amp; iPress</h2>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 61 of 89

## VERSION: 2.4.0.0

Release date: 27 sept. 2013

**Warning: this version requires a DMDB firmware Update!**

### BUG

- [\[IPRINT-309\]](#) - ProductionLog: The job informations are not saved in the production log database untill the printer is back to ready state
- [\[IPRINT-339\]](#) - [TN20130060] Pattern is cropped to PrintLayout Size
- [\[IPRINT-351\]](#) - Draw flushLine on verso checkBox is Visible in a Recto-only configuration
- [\[IPRINT-383\]](#) - Possible to override an read only snapshot
- [\[IPRINT-389\]](#) - [TN20130297] Device Link still used after being disabled in the CMR Screen
- [\[IPRINT-391\]](#) - [TN20130295] When changing ICCProfile, sometime the Media Save button is not available
- [\[IPRINT-394\]](#) - In dryer Screen, basic and advanced subscreen are not updated when user level change
- [\[IPRINT-405\]](#) - [TN20130320] Electrical Shutdown operation is not shutting down the IPDS Controller nodes
- [\[IPRINT-406\]](#) - Electrical Shutdown operation is not shutting down the cabinet PC if PBX is not running
- [\[IPRINT-350\]](#) - Production Log: export problem in case of job failure
- [\[IPRINT-407\]](#) - ProductionLog: Print session is not tracked correctly (GlobalStop and GlobalStart not called in the right location and time).
- [\[IPRINT-379\]](#) - Last top right pixel is cropped with the largest print layout
- [\[IPRINT-411\]](#) - [TN20130328] ProductionLog export problems (Xls, Html)

### IMPROVEMENT

- [\[IPRINT-97\]](#) - Cue Mark positioning relative to Media border
- [\[IPRINT-273\]](#) - Autocheck - control the maximum paper length according to hardware limit.
- [\[IPRINT-381\]](#) - Change displayed counter units to A4 surface, US letter Size surface and 12" length
- [\[IPRINT-386\]](#) - Enable Operator level Access for "Enter CWS maintenance Mode"
- [\[IPRINT-392\]](#) - In Media Screen when clearing front ICCProfile, the back linked ICC Profile is now deleted
- [\[IPRINT-393\]](#) - Update MachineDefinition\_RectoOnly.xml with UpdateMachineDefinition.bat script
- [\[IPRINT-397\]](#) - TED Recto Only Support: Report Simplex mode to Tagg Ipds PDP if no heads printing the back side
- [\[IPRINT-408\]](#) - ProductionLog: Add more error reason reporting when printer stops.

### NEW FEATURE

- [\[IPRINT-73\]](#) - Add support multiple CUE mark printing per side (Front & Back, with independent size and position)

	<h1>Technical Note</h1>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<h2>Suivi de version iPrint &amp; iPress</h2>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 62 of 89

- [\[IPRINT-395\]](#) - Multiple Cue Mark : Autocheck if cue mark don't overlap on synchronization mark (if active)
- [\[IPRINT-212\]](#) - VHQ - Add capability to switch to High Speed without restarting MMI
- [\[IPRINT-303\]](#) - VHQ - Add configuration for Drop Flying Time Compensation to adjust Small drop on Big Drop.
- [\[IPRINT-338\]](#) - Counters - Pixel count threshold per color plane
- [\[IPRINT-347\]](#) - Send new fiber mapping to DMDB

### **TASK**

- [\[IPRINT-382\]](#) – CxImage removed (licensing problems).

### **KNOWN BUG**

- Switching from overridden media offset to standard media offset is not working.  
Workaround: use only media offsets only or overridden offsets only.
- Save counters only save the screenshot. The csv file and binary file are not exported in the compressed package.
- Automated pattern usage lead to an MMI crash if only one page is setup in the first pattern.  
Workaround: use at least 2 pages for the first pattern
- Production Log export is very slow, and block the MMI. It can take several minutes and a dialog box "program not responding" can appear.  
Workaround: just wait and above all, do not close MMI during the export.

	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 63 of 89

Main files versions (file modified from the previous version <b>in bold</b> )		
File	Version	Date
<b>i600mmi.exe</b>	<b>2.4.0.0</b>	<b>09-27-2013</b>
<b>pbx661controller.exe</b>	<b>3.3.10.0</b>	<b>09-27-2013</b>
cddjobfile.dll	3.0.3.0	09-20-2013

Secondary files version (file modified from the previous version <b>in bold</b> )		
File	Version	Date
<b>configupdate.exe</b>	<b>1.0.0.1</b>	<b>09-25-2013</b>
i-dtppnetlibrary.dll	1.1.7.0	08-09-2012
impikafiberboard.dll	4.0.0.0	20-09-2011
cpnetlibrary.dll	4.0.1.0	10-19-2012
tracecreationtools.exe	1.0.0.6	07-18-2013
virtualkeyboard.dll	1.0.0.5	01-24-2013
virtualkeypad.dll	1.0.0.3	01-24-2013
vst_matti.dll	1.0.0.6	06-05-2013
vst_xl.dll	1.0.0.4	06-05-2013
serialportcom.dll	1.0.9.0	08-31-2011
<b>i600configuration.dll</b>	<b>1.1.0.0</b>	<b>06-05-2013</b>
signaturetools.exe	1.0.0.2	06-05-2013
skinx.dll	1.0.0.7	01-24-2013
languageresource.dll	1.0.0.0	01-24-2013
mfcguiext.dll	1.0.0.2	01-24-2013
sqlite3.dll	-	08-03-2012
pcan_usb.dll	2.0.4.0	10-14-2010
adsapi32.dll	1.5.16.1	03-27-2012
cximageu.dll		<b>removed</b>
dbghelp.dll	6.5.3.7	03-27-2012
mxio.dll	2.7.0.0	03-27-2012
psexec.exe	1.98.0.0	01-11-2012
xcmd.exe	1.0.0.1	07-20-2012
xcrashhandler.dll	1.0.0.1	03-27-2012
xcrashreport.exe	1.0.0.2	03-27-2012

Firmware (file modified from the previous version <b>in bold</b> ):		
Component	Version	Date
<b>DMDB Firmware</b>	<b>5.00.002 6.0 5.2</b>	<b>09-20-2013</b>

	<h1>Technical Note</h1>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<h2>Suivi de version iPrint &amp; iPress</h2>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 64 of 89

### VERSION: 2.3.0.12

Release date: 25 july. 2013

### BUG

- [\[IPRINT-377\]](#) - Screenshot taken for Print Counters archive contains an incomplete desktop image (no background, no text,...)

### IMPROVEMENT

- [\[IPRINT-378\]](#) - After saving Print counters automatically open an explorer window with the created file selected

Main files versions (file modified from the previous version **in bold**):

File	Version	Date
<b>i600mmi.exe</b>	<b>2.3.0.12</b>	<b>07-25-2013</b>
pbx661controller.exe	3.3.8.0	05-13-2013
cddjobfile.dll	3.0.3.0	10-17-2012

Secondary files version:

File	Version	Date
configupdate.exe	1.0.0.1	06-05-2013
i-dtptnetlibrary.dll	1.1.7.0	08-09-2012
impikafiberopticboard.dll	4.0.0.0	07-13-2011
cpnetlibrary.dll	4.0.1.0	10-19-2012
tracecreationtools.exe	1.0.0.6	07-18-2013
virtualkeyboard.dll	1.0.0.5	01-24-2013
virtualkeypad.dll	1.0.0.3	01-24-2013
vst_matti.dll	1.0.0.6	06-05-2013
vst_xl.dll	1.0.0.4	06-05-2013
serialportcom.dll	1.0.9.0	08-31-2011
i600configuration.dll	1.0.0.6	06-05-2013
signaturetools.exe	1.0.0.2	06-05-2013
skinx.dll	1.0.0.7	01-24-2013
languageresource.dll	1.0.0.0	01-24-2013
mfcguiext.dll	1.0.0.2	01-24-2013
sqlite3.dll	-	08-03-2012
pcan_usb.dll	2.0.4.0	10-14-2010
adsapi32.dll	1.5.16.1	03-27-2012
cximageu.dll	7.0.2.0	01-24-2013
dbgghelp.dll	6.5.3.7	03-27-2012
mxio.dll	2.7.0.0	03-27-2012
psexec.exe	1.98.0.0	01-11-2012
xcmd.exe	1.0.0.1	07-20-2012
xcrashhandler.dll	1.0.0.1	03-27-2012
xcrashreport.exe	1.0.0.2	03-27-2012



	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 65 of 89

## VERSION: 2.3.1.11

Release date: 18 July 2013

### IMPROVEMENT

- [\[IPRINT-374\]](#) - Use semicolon as a separator in ProductionLog export
- [\[IPRINT-375\]](#) - Switch from compilation directive to command line argument based app test under simulation environment

Version des fichiers principaux

(en gras les fichiers modifiés par rapport à la version précédente) :

Fichiers	Version	Date
<b>i600mmi.exe</b>	<b>2.3.1.11</b>	<b>07-18-2013</b>
pbx661controller.exe	3.3.8.0	05-13-2013
cddjobfile.dll	3.0.3.0	10-17-2012

- Version des fichiers annexes :

Fichiers	Version	Date
configupdate.exe	1.0.0.1	06-05-2013
i-dtpnetlibrary.dll	1.1.7.0	08-09-2012
impikafiberopticboard.dll	4.0.0.0	07-13-2011
cpnetlibrary.dll	4.0.1.0	10-19-2012
<b>tracecreationtools.exe</b>	<b>1.0.0.6</b>	<b>07-18-2013</b>
virtualkeyboard.dll	1.0.0.5	01-24-2013
virtualkeypad.dll	1.0.0.3	01-24-2013
vst_matti.dll	1.0.0.6	06-05-2013
vst_xl.dll	1.0.0.4	06-05-2013
serialportcom.dll	1.0.9.0	08-31-2011
i600configuration.dll	1.0.0.6	06-05-2013
signaturetools.exe	1.0.0.2	06-05-2013
skinx.dll	1.0.0.7	01-24-2013
languageresource.dll	1.0.0.0	01-24-2013
mfcguiext.dll	1.0.0.2	01-24-2013
sqlite3.dll	-	08-03-2012
pcan_usb.dll	2.0.4.0	10-14-2010
adsapi32.dll	1.5.16.1	03-27-2012
cximageu.dll	7.0.2.0	01-24-2013
dbghelp.dll	6.5.3.7	03-27-2012
mxio.dll	2.7.0.0	03-27-2012
psexec.exe	1.98.0.0	01-11-2012
xcmd.exe	1.0.0.1	07-20-2012
xcrashhandler.dll	1.0.0.1	03-27-2012
xcrashreport.exe	1.0.0.2	03-27-2012

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 66 of 89

## VERSION: 2.3.0.11

Release date: 17 July 2013

### BUG

- [\[IPRINT-366\]](#) - [TN20130254] MMI crashes when shutdown button pressed on the Computers screen
- [\[IPRINT-320\]](#) - [TN20130143] "LHC on the Transport NEEDS RESET !" message never displayed in the "ToDo/Info" panel
- [\[IPRINT-275\]](#) - IDTP command GET\_PBX661\_HEAD\_COUNTERS support broken in I600MMI when XL support was added
- [\[IPRINT-362\]](#) - ProductionLog: CDataBase::AddColumn() not all paths returning a value
- [\[IPRINT-373\]](#) - MMI sometimes crashes on exit in CHashTable<...>::Clear() in m\_oTable.clear()

### IMPROVEMENT

- [\[IPRINT-367\]](#) - CWMIService class corrections/rewrite
- [\[IPRINT-368\]](#) - Improve handling credential conflict in CConnect::Connection
- [\[IPRINT-369\]](#) - EPSIB Input/Output change notification is too noisy (each bit is logged separately)
- [\[IPRINT-370\]](#) - Add ThreadID to the traced INFO in CMainPrinter class
- [\[IPRINT-371\]](#) - Trace errors as ERROR in CMainPrinter

Version des fichiers principaux

(en gras les fichiers modifiés par rapport à la version précédente) :

Fichiers	Version	Date
<b>i600mmi.exe</b>	<b>2.3.0.11</b>	<b>07-17-2013</b>
pbx661controller.exe	3.3.8.0	05-13-2013
cddjobfile.dll	3.0.3.0	10-17-2012

- Version des fichiers annexes :

Fichiers	Version	Date
configupdate.exe	1.0.0.1	06-05-2013
i-dtpnetlibrary.dll	1.1.7.0	08-09-2012
impikafiberopticboard.dll	4.0.0.0	07-13-2011
cpnetlibrary.dll	4.0.1.0	10-19-2012
<b>tracecreationtools.exe</b>	<b>1.0.0.5</b>	<b>07-17-2013</b>
virtualkeyboard.dll	1.0.0.5	01-24-2013
virtualkeypad.dll	1.0.0.3	01-24-2013
vst_matti.dll	1.0.0.6	06-05-2013
vst_xl.dll	1.0.0.4	06-05-2013
serialportcom.dll	1.0.9.0	08-31-2011
i600configuration.dll	1.0.0.6	06-05-2013
signaturetools.exe	1.0.0.2	06-05-2013
skinx.dll	1.0.0.7	01-24-2013
languageresource.dll	1.0.0.0	01-24-2013
mfcguiext.dll	1.0.0.2	01-24-2013

 <b>Impika</b> A Xerox Company	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 67 of 89

sqlite3.dll	-	08-03-2012
pcan_usb.dll	2.0.4.0	10-14-2010
adsapi32.dll	1.5.16.1	03-27-2012
cximageu.dll	7.0.2.0	01-24-2013
dbghelp.dll	6.5.3.7	03-27-2012
mxio.dll	2.7.0.0	03-27-2012
psexec.exe	1.98.0.0	01-11-2012
xcmd.exe	1.0.0.1	07-20-2012
xcrashhandler.dll	1.0.0.1	03-27-2012
xcrashreport.exe	1.0.0.2	03-27-2012

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 68 of 89

## VERSION 2.3.0.10

RELEASE DATE: 5 Juin. 2013

### BOGUE

- Safety speed limitation not working on Compact
- [TN20130148] ProductionLog export corrections
- I/O Initialisation with EPSIB encoder Box

Version des fichiers principaux

(en gras les fichiers modifiés par rapport à la version précédente) :

Fichiers	Version	Date
<b>i600mmi.exe</b>	<b>2.3.0.10</b>	<b>06-05-2013</b>
pbx661controller.exe	3.3.8.0	05-13-2013
cddjobfile.dll	3.0.3.0	10-17-2012

- Version des fichiers annexes :

Fichiers	Version	Date
<b>configupdate.exe</b>	<b>1.0.0.1</b>	<b>06-05-2013</b>
i-dtppnetlibrary.dll	1.1.7.0	08-09-2012
impikafiberboard.dll	4.0.0.0	07-13-2011
cpnetlibrary.dll	4.0.1.0	10-19-2012
<b>tracecreationtools.exe</b>	<b>1.0.0.4</b>	<b>06-05-2013</b>
virtualkeyboard.dll	1.0.0.5	01-24-2013
virtualkeypad.dll	1.0.0.3	01-24-2013
<b>vst_matti.dll</b>	<b>1.0.0.6</b>	<b>06-05-2013</b>
<b>vst_xl.dll</b>	<b>1.0.0.4</b>	<b>06-05-2013</b>
serialportcom.dll	1.0.9.0	08-31-2011
<b>i600configuration.dll</b>	<b>1.0.0.6</b>	<b>06-05-2013</b>
<b>signaturetools.exe</b>	<b>1.0.0.2</b>	<b>06-05-2013</b>
skinx.dll	1.0.0.7	01-24-2013
languageresource.dll	1.0.0.0	01-24-2013
mfcguiext.dll	1.0.0.2	01-24-2013
sqlite3.dll	-	08-03-2012
pcan_usb.dll	2.0.4.0	10-14-2010
adsapi32.dll	1.5.16.1	03-27-2012
cximageu.dll	7.0.2.0	01-24-2013
dbghelp.dll	6.5.3.7	03-27-2012
mxio.dll	2.7.0.0	03-27-2012
psexec.exe	1.98.0.0	01-11-2012
xcmd.exe	1.0.0.1	07-20-2012
xcrashhandler.dll	1.0.0.1	03-27-2012
xcrashreport.exe	1.0.0.2	03-27-2012

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 69 of 89

## VERSION 2.3.0.9

RELEASE DATE: 23 mai. 2013

### BOGUE

- [\[IPRINT-336\]](#) - [TN20130201] PVS and the standard Camera conflict lead to no camera icon on the Main screen
- [\[IPRINT-337\]](#) - [TN20130201] Electrical signals based camera connection handling conflicts with COM based camera handling, leading to camera error

Version des fichiers principaux

(**en gras** les fichiers modifiés par rapport à la version précédente) :

Fichiers	Version	Date
<b>i600mmi.exe</b>	<b>2.3.0.9</b>	<b>05-13-2013</b>
pbx661controller.exe	3.3.8.0	05-13-2013
cddjobfile.dll	3.0.3.0	10-17-2012

- Version des fichiers annexes :

Fichiers	Version	Date
i-dtpnetlibrary.dll	1.1.7.0	08-09-2012
impikafiberboard.dll	4.0.0.0	07-13-2011
cpnetlibrary.dll	4.0.1.0	10-19-2012
tracecreationtools.exe	1.0.0.4	05-13-2013
virtualkeyboard.dll	1.0.0.5	01-24-2013
virtualkeypad.dll	1.0.0.3	01-24-2013
vst_matti.dll	1.0.0.6	05-13-2013
vst_xl.dll	1.0.0.4	05-13-2013
serialportcom.dll	1.0.9.0	08-31-2011
<b>i600configuration.dll</b>	<b>1.0.0.6</b>	<b>05-13-2013</b>
<b>signaturetools.exe</b>	<b>1.0.0.2</b>	<b>05-13-2013</b>
skinx.dll	1.0.0.7	01-24-2013
languageresource.dll	1.0.0.0	01-24-2013
mfcguiext.dll	1.0.0.2	01-24-2013
sqlite3.dll	-	08-03-2012
pcan_usb.dll	2.0.4.0	10-14-2010
adsapi32.dll	1.5.16.1	03-27-2012
cximageu.dll	7.0.2.0	01-24-2013
dbghelp.dll	6.5.3.7	03-27-2012
mxio.dll	2.7.0.0	03-27-2012
psexec.exe	1.98.0.0	01-11-2012
xcmd.exe	1.0.0.1	07-20-2012
xcrashhandler.dll	1.0.0.1	03-27-2012
xcrashreport.exe	1.0.0.2	03-27-2012

 A Xerox Company	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 70 of 89

## VERSION 2.3.0.8

RELEASE DATE: 13 mai. 2013

### **BOGUE**

- Ink consumption decrease if flush line are inserted
- Migrate bugfix for camera button handling on the main screen from 'XL\_v2.3.0.6\_Modif' branch r1504 (v2.3.1.6)
- MMI main trace file in use cannot be open for reading, so the file will not be saved in the trace package

### **AMÉLIORATION**

- Modify End of Purge Sequence with CWS (HD Ink sedimentation Problem)
- Modify Park Sequence to include a periodic Filling (HD Ink sedimentation problem)
- Remove OA pump driving
- Display the Waveform Table Header in the PBX

	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 71 of 89

Version des fichiers principaux

(**en gras** les fichiers modifiés par rapport à la version précédente) :

Fichiers	Version	Date
<b>i600mmi.exe</b>	<b>2.3.0.8</b>	<b>05-13-2013</b>
<b>pbx661controller.exe</b>	<b>3.3.8.0</b>	<b>05-13-2013</b>
cddjobfile.dll	3.0.3.0	10-17-2012

- Version des fichiers annexes :

Fichiers	Version	Date
i-dtpnetlibrary.dll	1.1.7.0	08-09-2012
impikafiberboard.dll	4.0.0.0	07-13-2011
cpnetlibrary.dll	4.0.1.0	10-19-2012
<b>tracecreationtools.exe</b>	<b>1.0.0.4</b>	<b>05-13-2013</b>
virtualkeyboard.dll	1.0.0.5	01-24-2013
virtualkeypad.dll	1.0.0.3	01-24-2013
<b>vst_matti.dll</b>	<b>1.0.0.6</b>	<b>05-13-2013</b>
<b>vst_xl.dll</b>	<b>1.0.0.4</b>	<b>05-13-2013</b>
serialportcom.dll	1.0.9.0	08-31-2011
<b>i600configuration.dll</b>	<b>1.0.0.6</b>	<b>05-13-2013</b>
<b>signaturetools.exe</b>	<b>1.0.0.2</b>	<b>05-13-2013</b>
skinx.dll	1.0.0.7	01-24-2013
languageresource.dll	1.0.0.0	01-24-2013
mfcguiext.dll	1.0.0.2	01-24-2013
sqlite3.dll	-	08-03-2012
pcan_usb.dll	2.0.4.0	10-14-2010
adsapi32.dll	1.5.16.1	03-27-2012
cximageu.dll	7.0.2.0	01-24-2013
dbghelp.dll	6.5.3.7	03-27-2012
mxio.dll	2.7.0.0	03-27-2012
psexec.exe	1.98.0.0	01-11-2012
xcmd.exe	1.0.0.1	07-20-2012
xcrashhandler.dll	1.0.0.1	03-27-2012
xcrashreport.exe	1.0.0.2	03-27-2012

 A Xerox Company	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 72 of 89

## VERSION 2.3.0.7

RELEASE DATE: 2 avr. 2013

### BOGUE

- Dryer1Status & Dryer2Status Status Bits00 is On even when the printer is Stopped
- "Save infos" generate incorrect values in the file VersionsAndInformation.xml
- Add forbidden character for the snapshot, printlayout and media naming
- Overridden offset are not correctly used in autocheck parameters computation.
- Ensure IMS is enabled when SheetManagement starts!
- Parallelized Machine Configuration dispatching to the Print Head Controllers
- TraceCreationTools: Created package is not copied to the MMI PC when MMI is running on a cabinet PC
- Trace : Copy to clipboard button is not working
- Fixed and Stacked distance are not updated
- InErrorProcessing IPDS tolerance feature is not working

### AMÉLIORATION

- MIGRATE PVS branch features to XL branch: IMS Tracing & max log file size
- MIGRATE trunk features to XL branch: IMS related improvements (Enable/Disable & Logging changes)
- Check if Profile and DeviceLink are correctly used.
- Coder accuracy enhancement in 1200DPI
- Migrate "Display the sum of local job and Ipds specific Print Counters" feature from PVS\_Support branch

### NOUVELLE FONCTIONNALITÉ

- New Mechanical Advanced screen's functionality (load cell, speed, temperature feedback for service only)
- Load Cell feedback on the mechanical screen (LED VU-meter style)
- Add Support for DeviceLink
- Production Log (Job history)

### TACHE

- Compiled with Visual Studio 2010.



	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 73 of 89

Version des fichiers principaux

(**en gras** les fichiers modifiés par rapport à la version précédente) :

Fichiers	Version	Date
<b>i600mmi.exe</b>	<b>2.3.0.7</b>	<b>04-02-2013</b>
pbx661controller.exe	3.3.7.0	10-08-2012
cddjobfile.dll	3.0.3.0	10-17-2012

- Version des fichiers annexes :

Fichiers	Version	Date
i-dtpnetlibrary.dll	1.1.7.0	08-09-2012
impikafiberopticboard.dll	4.0.0.0	07-13-2011
<b>cpnetlibrary.dll</b>	<b>4.0.1.0</b>	<b>10-19-2012</b>
<b>tracecreationtools.exe</b>	<b>1.0.0.2</b>	<b>04-02-2013</b>
<b>virtualkeyboard.dll</b>	<b>1.0.0.5</b>	<b>01-24-2013</b>
<b>virtualkeypad.dll</b>	<b>1.0.0.3</b>	<b>01-24-2013</b>
<b>vst_matti.dll</b>	<b>1.0.0.4</b>	<b>04-02-2013</b>
<b>vst_xl.dll</b>	<b>1.0.0.2</b>	<b>04-02-2013</b>
serialportcom.dll	1.0.9.0	08-31-2011
<b>i600configuration.dll</b>	<b>1.0.0.4</b>	<b>04-02-2013</b>
<b>signaturetools.exe</b>	<b>1.0.0.2</b>	<b>04-02-2013</b>
<b>skinx.dll</b>	<b>1.0.0.7</b>	<b>01-24-2013</b>
<b>languageresource.dll</b>	<b>1.0.0.0</b>	<b>01-24-2013</b>
<b>mfcguiext.dll</b>	<b>1.0.0.2</b>	<b>01-24-2013</b>
sqlite3.dll	-	08-03-2012
pcan_usb.dll	2.0.4.0	10-14-2010
adsapi32.dll	1.5.16.1	03-27-2012
<b>cximageu.dll</b>	<b>7.0.2.0</b>	<b>01-24-2013</b>
dbghelp.dll	6.5.3.7	03-27-2012
mxio.dll	2.7.0.0	03-27-2012
psexec.exe	1.98.0.0	01-11-2012
<b>xcmd.exe</b>	<b>1.0.0.1</b>	<b>07-20-2012</b>
xcrashhandler.dll	1.0.0.1	03-27-2012
xcrashreport.exe	1.0.0.2	03-27-2012

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 74 of 89

## VERSION 2.3.4.6

RELEASE DATE: 15 avr. 2013

### BOGUE

- [TN20130139] Rabobank: Impossible to disconnect camera
- Migrate support for Tagg Ipds Controller's IN\_ERROR\_PROCESSING mode
- Rabobank: I600MMI crashes on start with the existing I600Configuration.dll
- MIGRATED bugfix for TraceCreationTools "detect if trace gathering is running on MMI PC" from 'XL' branch r1443 (v2.3.0.7)
- MIGRATED bugfixes from trunk r1157 (v2.1.0.37): ErrAck button was not enabled when camera errors were returned through the COM port.

Version des fichiers principaux

(**en gras** les fichiers modifiés par rapport à la version précédente) :

Fichiers	Version	Date
<b>i600mmi.exe</b>	<b>2.3.4.6</b>	<b>15-12-2013</b>
pbx661controller.exe	3.3.7.0	10-08-2012
cddjobfile.dll	3.0.3.0	10-17-2012

- Version des fichiers annexes :

Fichiers	Version	Date
i-dtpnetlibrary.dll	1.1.7.0	08-09-2012
impikafiberopticboard.dll	4.0.0.0	07-13-2011
cpnetlibrary.dll	4.0.0.0	08-09-2012
<b>tracecreationtools.exe</b>	<b>1.0.0.3</b>	<b>04-12-2013</b>
virtualkeyboard.dll	1.0.0.5	03-27-2012
virtualkeypad.dll	1.0.0.3	08-06-2012
<b>vst_matti.dll</b>	<b>1.0.0.5</b>	<b>04-12-2013</b>
<b>vst_xl.dll</b>	<b>1.0.0.3</b>	<b>04-12-2013</b>
serialportcom.dll	1.0.9.0	08-31-2011
<b>i600configuration.dll</b>	<b>1.0.0.5</b>	<b>04-12-2013</b>
signaturetools.exe	1.0.0.2	11-21-2012
skinx.dll	1.0.0.6	03-27-2012
languageresource.dll	1.0.0.0	03-27-2012
mfcguiext.dll	1.0.0.1	03-27-2012
sqlite3.dll	-	08-03-2012
pcan_usb.dll	2.0.4.0	10-14-2010
adsapi32.dll	1.5.16.1	03-27-2012
cximageu.dll	5.9.9.3	03-27-2012
dbghelp.dll	6.5.3.7	03-27-2012
mxio.dll	2.7.0.0	03-27-2012
psexec.exe	1.98.0.0	01-11-2012
xcmd.exe	1.0.0.1	05-22-2012
xcrashhandler.dll	1.0.0.1	03-27-2012

 A Xerox Company	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 75 of 89

xcrashreport.exe	1.0.0.2	03-27-2012
------------------	---------	------------

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 76 of 89

## VERSION 2.3.0.6

### BOGUE

- CLog class can block the calling thread while writing to disk
- MMI doesn't start if LineHoleCounter configuration is not present
- PrintHead Temperature Warning message is always display when ConfigurationTypeEx is not in XL mode

Version des fichiers principaux

(**en gras** les fichiers modifiés par rapport à la version précédente) :

Fichiers	Version	Date
i600mmi.exe	2.3.0.6	11-22-2012
pbx661controller.exe	3.3.7.0	10-08-2012
cddjobfile.dll	3.0.3.0	10-17-2012

- Version des fichiers annexes :

Fichiers	Version	Date
i-dtpnetlibrary.dll	1.1.7.0	08-09-2012
impikafiberopticboard.dll	4.0.0.0	07-13-2011
cpnetlibrary.dll	4.0.0.0	08-09-2012
tracecreationtools.exe	1.0.0.1	11-21-2012
virtualkeyboard.dll	1.0.0.5	03-27-2012
virtualkeypad.dll	1.0.0.3	08-06-2012
vst_matti.dll	1.0.0.4	11-21-2012
vst_xl.dll	1.0.0.2	11-21-2012
serialportcom.dll	1.0.9.0	08-31-2011
i600configuration.dll	1.0.0.4	11-21-2012
signaturetools.exe	1.0.0.2	11-21-2012
skinx.dll	1.0.0.6	03-27-2012
languageresource.dll	1.0.0.0	03-27-2012
mfcguiext.dll	1.0.0.1	03-27-2012
sqlite3.dll	-	08-03-2012
pcan_usb.dll	2.0.4.0	10-14-2010
adsapi32.dll	1.5.16.1	03-27-2012
cximageu.dll	5.9.9.3	03-27-2012
dbgghelp.dll	6.5.3.7	03-27-2012
mxio.dll	2.7.0.0	03-27-2012
psexec.exe	1.98.0.0	01-11-2012
xcmd.exe	1.0.0.1	05-22-2012
xcrashhandler.dll	1.0.0.1	03-27-2012
xcrashreport.exe	1.0.0.2	03-27-2012

 A Xerox Company	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 77 of 89

 A Xerox Company	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 78 of 89

## VERSION 2.3.0.5

### BOGUE

- Active keyboard shortcut when associated button is disabled
- Maintenance Mode message bit not displayed
- Not Installed component is not load in MachineDefinition, but some dialog try to set default values in component so SnapShot is always modified
- Exception when i start Log
- When 1 tank use with 2 PrintHead is empty, First corresponding PrintHead is blinking but not the Second
- Incorrect page cropping when pattern printing mode is selected
- Error on IDTP-COM retry procedure
- Main screen's Ink containers display and action on Ink containers is not working correctly on COMPACT printers

### AMÉLIORATION

- Auto Park: After "START" pressed the heads are uncapped, and during the purge the "need to cap" message is displayed in the ToDo/Info panel
- Right Media Offset for Verso (ISETO)
- Hide (or disable) Duplex Layout choice from Printing Mode screen if Local Job printing mode
- Add counters export in the trace package
- Add support for Line Hole Counting in EPSIB Board
- Add retry for CAN bus communication

### TÂCHE

- Update mechanical default constructor values
- Dryer #2 parameters was not used with Compact
- Update language file FR for the new Dryer Screen
- GUI Controls adjustment for French traduction display in WorkWnd\_TechnicalAreaDlg
- Enable Ink consumption display in Log screen by default
- Do not save some MachineDefinition specific Ipds parameters to SnapShot, Remove not used parameter
- Enable CutterSynchronisation printing function as a standard configuration
- On Printer AutomatedPatternPrinting, Adjust Loop checkbox width for French translation
- Incorrect Rank data displayed when related rank file doesn't exist (for all drop sizes) and dialog box simplification
- SnapShot is modified each time AutomatedPatternPrintingDialog is display with no configuration
- Ignore missing nodes and parameters in MachineDefinition while loading new features
- During initialising GetlEngine is call without check iEngine existence
- MenuBar keyboard shortcut are still active when buttons are disabled
- Crash of the TraceCreationTools

 A Xerox Company	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 79 of 89

- Clean all trace/log files when the TraceCreationTools is finished
- Dryer #2 Fresh air blower is hide but only exhaust must be
- Dryers controls were not disabled when UserLevel is Operator
- Adjust DryerAdvancedDlg controls geometry to display entire label in french
- Dryers parameters send with the command are not correct
- Add error in the TodoInfo when the LHC Max error arrives

	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 80 of 89

## VERSION 2.3.0.4

### BOGUE

- Incorrect Rank data displayed when entering into Head Parameter windows
- Very slow memory leak in standby mode
- VST\_Matti plugin is leaking memory

### NOUVELLE FONCTIONNALITÉ

- Add support for sheetlet rotation (requested by DataOne)

### TÂCHE

- Migrated BugFix "Internal Matching System was not handling delayed sheet status correctly in all cases" from the Release branch
- Migrate IMS related bug fixes IPRINT-112, IPRINT-117.



 A Xerox Company	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 81 of 89

## VERSION 2.3.0.3

### BOGUE

- Pixel to metric unit conversion must consider the resolution change
- On the main screen the Page Left Offset is rounded instead of showing decimals

### AMÉLIORATION

- Automatic Parameter Validation - Check overlap and control setting when printing pre-printed papers
- Remove or disable IPDS node START button once pressed
- RA121742 - Software/Paramétrage Max de la taille de la "Window secure printing" en fonction de la résolution choisie
- RA121743 - Software/Prise en compte de la position en Y>0 de la marque pour le calcul distance verso Cue Sensor-Tête
- Simplify IR Dryers settings and controls for operator (Set only one Paper Temperature for drying whatever the speed)
- Reduce the long waiting time between the START button press and the first put sheet reception
- Synchronize cabinet PC's clocks and PVS PC's clocks with the MMI PC's clock
- Add PrintLayout Page cropping inside the PBX in Job Mode
- Limit the allowed max input value to the head width for the Page Width on the Print Layout screen
- Connection Screen: For Ipds rows change the 'Device Connection State' column's background color to match the real background
- Simplify the Trace Screen and it's usage
- Include all the files from PVS in the Versions.txt file in case of Log/Trace/Info packages
- Log and Trace Package creation OPTIMIZATION

### NOUVELLE FONCTIONNALITÉ

- Parameter values validation with Todo/Info panel display if parameters are not correct + disable the start button.
- Information gathering & save + Information screen
- Extend AutoPark to allow parking even when stopped
- Add signature based protection to the MachineDefinition.xml as a security against modification
- Configurable feature support for Cutter Sync, APP, Flush Line
- Ink Consumption Logging at Stop (in the Log window)
- Add 'About' screen with the license details for the source code and libraries used
- Add support for the new IPDS parameters required for 2bpp screening

### TÂCHE

- Improve Rank data file loading and setting
- Waveform loaded twice when the drop size is changed

 A Xerox Company	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 82 of 89

- Remove the Pin feed emulation
- Replace LZO by LZ4 everywhere
- Add support for Message coming from PBX

 A Xerox Company	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 83 of 89

## VERSION 2.2.0.17

Release date: 22 mars 2013

### BOGUE

- [TN201130016] Handle PVS Disabled state correctly

### AMÉLIORATION

- MIGRATE some features/bugfixes from trunk and XL branch

	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 84 of 89

## VERSION 2.1.0.43

### TÂCHE

- Add sheet rotation support
- Enabled Start button when UserLevel is upper than Maintenance operator even if AutoCheckParameters is in error state

Version des fichiers principaux

(**en gras** les fichiers modifiés par rapport à la version précédente) :

Fichiers	Version	Date
<b>i600mmi.exe</b>	<b>2.1.0.43</b>	<b>11-21-2012</b>
pbx661controller.exe	3.2.32.0	11-08-2012
cddjobfile.dll	3.0.3.0	10-17-2012

Version des fichiers annexes :

Fichiers	Version	Date
i-dtpnetlibrary.dll	1.1.5.0	10-17-2012
impikafiberboard.dll	4.0.0.0	10-17-2012
pcan_usb.dll	2.0.4.0	10-17-2012
serialportcom.dll	1.0.9.0	10-17-2012
adsapi32.dll	1.5.16.1	11-15-2011
cpnetlibrary.dll	2.0.0.1	11-15-2011
cximageu.dll	5.9.9.3	11-15-2011
dbgghelp.dll	6.12.2.633	02-16-2012
i-dtpnetlibrary.dll	1.1.6.0	02-03-2012
languageresource.dll	1.0.0.0	11-15-2011
mfcguiext.dll	1.0.0.1	11-15-2011
mxio.dll	2.7.0.0	11-15-2011

	Technical Note	Reference: 2013-1964 .TN00.A0
Project(s)/Product(s): iPrint – iPress	Suivi de version iPrint & iPress	Version : 1.0
Date: 2018-11-0505	Written by: Impika R&D dpt. (Philippe BARBERIO)	Page 85 of 89

## VERSION 2.1.0.42

### BOGUE

- Value used by sheet management to track the "last printed coder stamp" is never reset, causing "end of job" issues in speed regulation

Version des fichiers principaux

(**en gras** les fichiers modifiés par rapport à la version précédente) :

Fichiers	Version	Date
<b>i600mmi.exe</b>	<b>2.1.0.42</b>	<b>11-05-2012</b>
<b>pbx661controller.exe</b>	<b>3.2.32.0</b>	<b>11-08-2012</b>
cddjobfile.dll	3.0.3.0	10-17-2012

Version des fichiers annexes :

Fichiers	Version	Date
i-dtpnetlibrary.dll	1.1.5.0	10-17-2012
impikafiberopticboard.dll	4.0.0.0	10-17-2012
pcan_usb.dll	2.0.4.0	10-17-2012
serialportcom.dll	1.0.9.0	10-17-2012
adsapi32.dll	1.5.16.1	11-15-2011
cpnetlibrary.dll	2.0.0.1	11-15-2011
cximageu.dll	5.9.9.3	11-15-2011
dbghelp.dll	6.12.2.633	02-16-2012
i-dtpnetlibrary.dll	1.1.6.0	02-03-2012
languageresource.dll	1.0.0.0	11-15-2011
mfcguiext.dll	1.0.0.1	11-15-2011
mxio.dll	2.7.0.0	11-15-2011

	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 86 of 89

## VERSION 2.1.0.41

### BOGUE

- VST\_Matti plugin is leaking memory
- Incorrect page cropping when pattern printing mode is selected
- Error on IDTP-COM retry procedure

### AMÉLIORATION

- Add counters export in the trace package
- Add retry for CAN bus communication

Version des fichiers principaux :

Fichiers	Version	Date
i600mmi.exe	2.1.0.41	10-16-2012
pbx661controller.exe	3.2.31.0	10-17-2012
cddjobfile.dll	3.0.3.0	10-17-2012

Version des fichiers annexes :

Fichiers	Version	Date
i-dtpnetlibrary.dll	1.1.5.0	10-17-2012
impikafiberopticboard.dll	4.0.0.0	10-17-2012
pcan_usb.dll	2.0.4.0	10-17-2012
serialportcom.dll	1.0.9.0	10-17-2012
adsapi32.dll	1.5.16.1	11-15-2011
cpnetlibrary.dll	2.0.0.1	11-15-2011
cximageu.dll	5.9.9.3	11-15-2011
dbghelp.dll	6.12.2.633	02-16-2012
i-dtpnetlibrary.dll	1.1.6.0	02-03-2012
languageresource.dll	1.0.0.0	11-15-2011
mfcguiext.dll	1.0.0.1	11-15-2011
mxio.dll	2.7.0.0	11-15-2011
psexec.exe	1.98.0.0	02-03-2012
serialportcom.dll	1.0.9.0	11-15-2011
skinx.dll	1.0.0.6	02-03-2012
virtualkeyboard.dll	1.0.0.5	11-15-2011
virtualkeypad.dll	1.0.0.3	11-15-2011
xcrashhandler.dll	1.0.0.1	11-15-2011
xcrashreport.exe	1.0.0.2	11-15-2011

	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	<b>Version :</b> 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	<b>Page</b> 87 of 89

## **VERSION 2.1.0.40**

### **BOGUE**

- PrintUnitList.BuildList was called during printing when accessing Printing Mode/Registration/Tach and Cue screens messing up the Internal Matching System

## **VERSION 2.1.0.39**

### **BOGUE**

- Internal Matching System was not handling delayed sheet status correctly in all cases

## **VERSION 2.1.0.38**

### **BOGUE**

- On the main screen the Page Left Offset is rounded instead of showing decimals

### **AMÉLIORATION**

- Add PrintLayout Page cropping inside the PBX in Job Mode
- Limit the allowed max input value to the head width for the Page Width on the Print Layout screen
- Limit input for Overlap Distance edit control to 0 .. 2000 mm interval

### **NOUVELLE FONCTIONNALITÉ**

- Migrate Parameters Validation feature from v2.3.0.3 and test the new feature

## **VERSION 2.1.0.37**

### **BOGUE**

- AckErr button is not enabled when camera errors are returned over the COM port

 A Xerox Company	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 88 of 89

## **VERSION 2.1.0.36**

### **BOGUE**

- Printing is not starting when one job with non loop copies is used in LocalJob mode.
- Internal Matching system correction in SED mode

## **VERSION 2.1.0.35**

### **BOGUE**

- Pixel to metric unit conversion must consider the resolution change
- Auto Park not working when printing is started

## **VERSION 2.1.0.34**

### **BOGUE**

- Reversed text label in Printer screen\Tach&Cue tab: "Reference Cue to XX Cue Distance" (front <-> back)
- Fix ToDo/Info panel message length for Buffer Tank Refilling messages (they are too long)
- Color channel ink consumption counting and reporting issues

### **AMÉLIORATION**

- RA121743 - Software/Prise en compte de la position en Y>0 de la marque pour le calcul distance verso Cue Sensor-Tête
- Change label text from "Density" to "Paper weight" on Media screen\General tab
- Change all 'recto' to 'front' and all 'verso' to 'back' in the UI and English language file

### **NOUVELLE FONCTIONNALITÉ**

- Ink Consumption Logging at Stop (in the Log window)
- Add feature "Secure printing window value input limit (VKP)"
- Add feature "AutoPark support even when stopped"



	<b>Technical Note</b>	<b>Reference:</b> 2013-1964 .TN00.A0
<b>Project(s)/Product(s):</b> iPrint – iPress	<b>Suivi de version iPrint &amp; iPress</b>	Version : 1.0
<b>Date:</b> 2018-11-0505	<b>Written by:</b> Impika R&D dpt. (Philippe BARBERIO)	Page 89 of 89

### VERSION 2.1.0.33

#### BOGUE

- Added FastStop triggering to Speed Regulation if printing, there is no more data and the PutSheets queue is not on hold.
- Modified Sheet Management to hold put sheets if the data to print in the reference head is less than what is required to print for the PutSheet submitted timeout period.

### VERSION 2.1.0.32

#### BOGUE

- IMS is enabled each time when Sheet Management is initialized or started.

#### AMÉLIORATION

- Added extra log for Internal Matching System Enable/Disable changes.

### VERSION 2.1.0.31

#### BOGUE

- Line Hole Counter rounding fix, in order to match with Matti rounding method.
- BugFix: Create Ipds Trace bug was fixed. Now Start and Stop Trace should work correctly.

#### AMÉLIORATION

- The Event log is not cleared anymore on trace clean up nor on Start Trace.

### VERSION 2.1.0.30

#### AMÉLIORATION

- Added support for new extended information received from Tagg Ipds Controller: IN\_ERROR\_PROCESSING. When in this state, the regulation speed will be limited. The speed limit is also configurable from the MachineDefinition.xml.  
Added new <IpdsController> parameters to MachineDefinition.xml:  
InErrorProcessing\_ExtInfosSupported (Default: false),  
InErrorProcessing\_SpeedLimitInMetersPerMinute (Default: 10).