

Kit Installation Instructions

XOG SPAR Team

Product(s):	DocuColor 240/250 Integrated Fiery Color Server v1.2	Date:	March 09
Title:	1-ZIFBX Installation Instructions	Page:	1 of 1

Purpose

This software kit provides a version 1.2 software update in response to a DocuColor 240/250 Integrated Fiery Color Server v1.2 SPAR. Refer to the included customer letter for more information.

In the event of a version 1.2 system reinstall this software should be reapplied.

Kit Contents

Qty.	Description
1	Kit Installation Instructions
1	Customer Letter
1	Patch 1-ZIFBX.ps

Prerequisites

- Previous working knowledge with the DocuColor 240/250 Integrated Fiery Color Server v1.2.
- The DocuColor 240/250 Integrated Fiery Color Server v1.2 server must be at version 1.2 prior to performing this install. This software is supplemental to the 1.2 launch software.
- The following patches must be loaded prior to installing this patch. They are available via System Updates or www.xerox.com.
 - 1-XVE1A
 - 1-YNNOJ
 - 1-ZZJED
 - 1-116UK9

Installation Instructions

Note: This patch is Exclusive which means it must be installed independently and the server rebooted/restarted once. After which, other patches can be applied to the server.

1. Import the patch file **1-ZIFBX.ps** with Command Workstation to the **Direct** queue.
2. You must wait at least 60 seconds after importing the patch file before rebooting the system. This will ensure the patch file is completely processed.
3. From Command Workstation, select **Server > Reboot Server**. The Fiery will reboot.
4. Wait until the Fiery has come to idle and print out the configuration page.
5. Verify the **Update Info** section. It should contain the patch number 1-ZIFBX.