

Release Note

General information	
Issue ID Number	1-ZXMPH
Product Name	Fiery Network Controller for WorkCentre 7300 Series v1.0 SP1 EFIGSBPD
Issue Date	November 20, 2008

Files included in this release	
File name	File size
1-ZXMPH.exe	491 KB
1-ZXMPH_relnotes.doc	49 KB

Issue(s) addressed with this release

- **Landscape documents in InDesign CS3/Intel Mac 10.5x are printing rotated after first page**

Steps to reproduce

1. Create multipage landscape document from InDesign on Intel Mac 10.5.x.
2. Select File > Print.
3. Printer > Select the Fiery.
4. Select Page Setup.
5. Format For > Select Fiery.
6. Paper Size: A3
7. Select OK.
8. Select Setup in left hand column in the Print Window.
9. Paper Size: A3SEF
10. Select Print.

Results: Observe that Page 1 will print fine. Pages 2 & 3 will print rotated as if it was portrait.

Prerequisite(s)

- None

Installation instructions

1. Execute **1-ZXMPH.exe** and follow the instructions in the Fiery Patch Downloader
2. Notes about the Fiery Patch Downloader
 - a. Login must be **admin**. This is fixed and cannot be modified.
 - b. Password is the Fiery administrator login password
 - c. Hostname can be either the IP address or the Fiery server name.
3. After the patch is downloaded, and when prompted by Fiery Patch Downloader, choose **Reboot**.

4. When the Fiery has come to Idle, verify the Update Info section in the configuration page.
5. It should contain the patch number **1-ZXMPH**.

Note 1: When executing **1-ZXMPH.exe** manually, if you choose **Restart later** when prompted by the Fiery Patch Downloader, please make sure you manually restart the server for changes to take effect. In some cases, the patch will require a Restart Fiery, and a Reboot. Restart or Reboot server from the Server menu in Command Workstation. If Command Workstation is not available the Fiery can be rebooted by pushing and holding down the Soft power button until it shuts Off. Push the Soft power button again to turn On.

Note 2: This patch is not Exclusive which means that it can be applied to the server along with other patches concurrently and only one server restart/reboot is sufficient for all patches to take effect on the system.

Known Issues

- None