








Xerox® Phaser® 6140/6500

250-Sheet Feeder • Chargeur 250 feuilles • Alimentatore da 250 fogli • 250-Blatt-Zuführung • Alimentador de 250 hojas
 Alimentador para 250 folhas • Invoerlade voor 250 vel • Arkmatare för 250 ark • 250-arks mater • 250-arksfremfører
 250 arkin syöttölaite • Устройство подачи на 250 листов • Podavač na 250 listů • Podajnik 250 stronicowy • 250 lapos adagoló
 250-Sayfa Besleyici • Τροφοδότης 250 φύλλων

See the instructional video at
www.xerox.com/office/6140docs
www.xerox.com/office/6500docs



Enable Driver

Activer le pilote

Abilita driver

Treiber aktivieren

Activar controlador

Ativar o Driver

Driver inschakelen

Aktivera drivrutin

Aktiver driver

Aktivering af driver

Ota ajuri käyttööön

Включить драйвер

Povolte ovladač

Włącz sterownik

Illesztőprogram engedélyezése

Sürücüyü Etkinleştir

Ενεργοποίηση οδηγού

