

# EXP250 v1.1/1.01 for DocuColor 240/250



Xerox Corporation  
800 Phillips Road  
Webster, NY 14580

June 2008

Dear Xerox DocuColor 240/250 customer:

Your DocuColor EXP250 v1.1/1.01 system can now be upgraded with the **1-SS6CZ** software kit.

**NOTE:** *This software may be installed by the customer.*

**PREREQUISITE:** *RoHS systems must be at version 1.1 prior to installing this software.*

**PREREQUISITE:** *Non-RoHS systems must be at version 1.01 prior to installing this software.*

We tested this updated software release specifically for the System Problem Action Requests (SPARs) noted below. If your SPAR number is not listed, we are providing you this software either because you reported a problem that resembles one of the listed fixes or because our testing has shown that this software should resolve your problem. If this software does not resolve your problem, please contact the hotline and provide a detailed job scenario and sample job(s) for further investigation, testing, and resolution.

This software kit contains fixes for the following SPARs:

SPAR Release		SPAR #	Description
<b>1-SS6CZ</b>	1.	550197962	When inserting a special page in the job, the output on the finisher is incorrect.

**NOTE:** *Not all child SPARs will be listed in this letter.*