

# Kit Installation Instructions

PSG SPAR Team

Product(s):	EXP250 v1.1/1.01 for DC240/250	Date:	06/25/08
Title:	Patch 1-SS6CZ Installation instructions	Page:	1 of 1

## Purpose

This software kit provides an EXP250 v1.1/1.01 software update in response to an EXP250 SPAR. Refer to the included customer letter for more information.

In the event of an EXP250 v1.1/1.01 system reinstall this software should be reapplied.

## Kit Contents

Qty.	Description
1	Kit Installation Instructions
1	Customer Letter
1	1-SS6CZ.zip

## Prerequisites

- Previous working knowledge with the EXP250.
- RoHS EXP250 systems must be at version 1.1 prior to performing this install. This software is supplemental to the v1.1 launch software.
- Non-RoHS EXP250 systems must be at version 1.01 prior to performing this install. This software is supplemental to the v1.01 launch software.

## Installation Instructions

### Install the EXP250 1-SS6CZ patch:

- \_\_\_ 1. Copy the 1-SS6CZ.zip file to a PC
  - \_\_\_ a. Unzip the file
  - \_\_\_ b. Open the 1-SS6CZ folder
- \_\_\_ 2. Install the 1-SS6CZ patch
  - \_\_\_ a. Double click on the 1-SS6CZ.exe file
  - \_\_\_ b. At the Fiery Patch Download window, click [Next]
  - \_\_\_ c. At the License Agreement window, click [Accept]
  - \_\_\_ d. At the Fiery Logon window, type the Fiery administrator login password in the Password field

**NOTE:** Do NOT change the User field; that value must be admin.

- \_\_\_ e. In the Hostname field, type in the IP address or hostname of the EX260 and select [Connect]
- \_\_\_ f. At the Server Information window, select [Download]. The patch will be downloaded and installed
- \_\_\_ g. At the Processing window, select [Next], wait for approximately one (1) minute
- \_\_\_ h. On the final window, select [Reboot], then select [Finish]

**NOTE:** The patch will not be installed until the EXP250 is rebooted.

- \_\_\_ 3. Verify that the patch is installed and wrap-up
  - \_\_\_ a. Once the Fiery status says "Idle," select [Server: Print Pages] from the CWS menu and print a configuration page.
  - \_\_\_ b. On the "System Update Log" sheet of the configuration pages, ensure that the patch 1-SS6CZ is listed
  - \_\_\_ c. At the PC, delete the 1-SS6CZ.zip file and the 1-SS6CZ folder.

**NOTE:** When executing **1-SS6CZ.exe**, if you choose **Restart later** when prompted by the Fiery Patch Downloader, please make sure you manually reboot the server for changes to take effect.

**NOTE:** This patch is not Exclusive which means that it can be applied to the server along with other patches concurrently and only one server reboot/restart is sufficient for all patches to take effect on the system.