

RELEASE NOTES

General information	
Issue ID Number	1-GTOYT
Product Name	Fiery EX12 v. 2.0 SP2
Issue Date	November 11, 2004

Files included in this release	
File name	File size
1-GTOYT.ps	9.95 Megabytes
relnotes.pdf	

Issue description
Composite Patch for EX12 v. 2.0 SP2, consists of fixes for: 1-G9PWP Blue Text Printing Purple 1-CY7Z9 Part of background missing when printing from InDesign

Steps to reproduce
N.A.

Resolution type:	Closed - Patch
-------------------------	-----------------------

Resolution
1-GTOYT.ps

Important notes
To install this patch, download this file to the Direct Queue using Fiery Downloader or use the import function of CWS 4.x to import it. After the file has finished processing, please wait at least 60 seconds, then reboot the server from the Fiery LCD. When the Fiery has come to idle, print out the configuration page to confirm that the patch file has been received. The Update Info section should reflect the patch number: "1-GTOYT".