

File Name: 1-RAPF5.ps

File Size: 11.59 KB

Date Posted: 8/21/2007

Criticality: Recommended

Description: Patch to adjust the system clock for the new 2007 Daylight Savings Time schedule.

ID: 1-RKXV1

Installation Order: 14

Notes:

1. Download/Import the patch file 1-RAPF5.ps with Command Workstation to the Direct queue.
2. You must wait at least 60 seconds after the patch file downloaded/imported before rebooting the system. This will ensure the patch file is completely processed.
3. From either Command Workstation or the Fiery LCD, select Shut Down and then Reboot System
4. Wait until the Fiery has come to idle and print out the configuration page.
5. Verify the Update Info section. It should contain the patch number 1-RAPF5.

Note: This patch is not Exclusive which means that it can be applied to the server along with other patches concurrently and only one server reboot/restart is sufficient for all patches to take effect on the system.