

Release Note

General information	
Issue ID Number	1-JHPDF
Product Name	Fiery X12e v. 1.0
Issue Date	June 28, 2005

Files included in this release	
File name	File size
1-JHPDF.ps	9.88 Megabytes
releaseNote_1-JHPDF.pdf	44 Kilobytes

Issue(s) addressed with this release

Text and box with same color print differently

Steps to reproduce

Client: Win 2000, Application: PowerPoint 2000

1. Open new PowerPoint file
2. Color a box with new color (R=124, G=136, B=149)
3. Type text with same new color as created in Step 2.
4. Print the file to the X12e v1.0 and notice the colors are different.

Installation instructions

1. Download/Import the patch file "1-JHPDF.ps" with Command Workstation to the "Direct" queue.
2. You must wait at least 60 seconds after the patch file downloaded/imported before rebooting the system. This will ensure the patch file is completely processed.
3. The system must be rebooted twice for the patch to be effective.
4. Please select "Shut Down" and then "Reboot System" on the Fiery LCD. When the Fiery has come to "Idle", repeat the steps to reboot the system a second time.
5. Please wait until the Fiery has come to idle after the second reboot to print out the configuration page.

Verify the Update Info section. It should contain the patch number "1-JHPDF".

Prerequisite(s)

None.

Known Issues

None.