VERSION 2.1 DATE JUNE 2020

Xerox® AltaLink® C80XX & B80XX Series Multifunction Printers Embedded Web Server Software Upgrade Installation Instructions 100, 101, or 103 versions

Upgrading Software for Xerox® ConnectKey® Technology



Xerox[®] AltaLink[®] C80XX & B80XX Series Upgrade Instructions

Using Embedded Web Server

This document details the software upgrade instructions to support the Xerox[®] AltaLink[®] X80xx Multifunction Printer. The upgrade process can be performed on Xerox[®] AltaLink[®] Multifunction Printers built on ConnectKey® Technology that currently run software versions **100.xxx.xxxxxxx** or **101.xxx.xxxxx or 103.xxx.xxxxxx**. Note: To access administrative settings and to perform the software upgrade procedures, you must have system administrator access privileges.

Print a Configuration Report and Identify Software Version

To view the IP address of your printer, print a Configuration Report. Ensure that you print and keep a copy of the Configuration Report for reference until after the firmware update has been completed.

- 1. At the printer control panel, touch the **Home** button.
- 2. Touch Device > Information Pages.
- 3. Touch Configuration Report, then touch Print.
- 4. On the printed configuration report, check the system software version under the **Software Version** section.

	Information Pages	;		×	
Configuration Report			Print		
Billing Summary			_		

Upgrade Procedures

Software Upgrade Utility	To upgrade your device, we recommend that you use the Xerox [®] ConnectKey [®]
(Recommended)	Technology Software Upgrade Utility. This utility enables you to upgrade your device by
	running through our quick and easy-to-use tool interface. To use the recommended
	automatic upgrade process, follow the instructions provided.
Embedded Web Server	If you experience problems with the Software Upgrade Utility, you can upgrade the
Software Upgrade	software manually using the Embedded Web Server on the device.

This process updates devices running software versions 100, 101 or 103 to a later version of software for Xerox[®] ConnectKey[®] Technology.

Requirements

- 1. Verify the current software version installed on your device. For instructions, refer to Print a Configuration Report and Identify Software Version. If the software version number does not start with 100 or 101 or 103, then the wrong device is being used.
- 2. Ensure that the printer is configured and connected to the network.
- 3. Ensure that you have the IP address of the Xerox[®] AltaLink[®] device and can connect to it successfully. To locate the IP address, refer to Print a Configuration Report and Identify Software Version.
- 4. Ensure that HTTP is enabled on your Xerox[®] AltaLink[®] device. For details, refer to the HTTP on the configuration page under **Protocols > HTTP** or *System Administrator Guide* for your device on www.xerox.com/office/support.

Notes: The zip file contains the Software Upgrade Utility instructions, Embedded Web Server Software Upgrade Instructions, ckupgrade-xxxxxxxx.jar, dlm upgrade file, any associated Web apps to install, and the software manifest file. Do not modify the structure or format of the zip file.

Downloading the Package for Upgrade

To upgrade the device software from 100, 101 or 103 to a later version manually, use the following instructions.

- 1. At your computer, download the Upgrade Software:
 - a. Locate the software and download to your desktop.
 - b. Double-Click on the downloaded Xerox®_AltaLink®_X80x0_Software_Upgrade_zip file and extract all content to the desktop. This should create a new directory on the desktop with the same name as the downloaded zip file.
 - c. Open the directory and double click down to find Xerox®_AltaLink®_x80xx_Software_Upgrade_.zip file. Double-Click this zip file, enter the DLM directory and then enter the AltaLink_X80xx directory.
 - d. Highlight the **453170v2.dlm** file and the **AltaLink_X80xx_system-sw# ENG_MOD.DLM** file. Extract the 2 files to the already created directory on the desktop.

Creating the Clone File (Optional)

- 1. At your computer, open a Web browser, then type the IP Address of your Xerox[®] AltaLink[®] printer using the format http://xxx.xxx.xxx.
- 2. From the top menu click **Properties**. If you receive a security warning, click to continue. If the printer is locked, a login screen appears.

Note: The default system administrator login user name is **admin** and the default password is either **1111** or the machine serial number (please note that the password is case sensitive).

- 3. Type the login details for the system administrator. The Configuration Overview page appears.
- 4. In the left-navigation pane, click **General Setup > Cloning.**
- 5. To clone all features, click the **Create/ Install File** button.



6. Select Create a file Button.

Image: Configuration Files Image: Configuration Files Type File Name/Version Status Type File Name/Version Status Type File Name/Version Status Schware Upgrade 10.001.008.27400 No software upgrade Schware Upgrade 10.001.008.27400 No software upgrade	xerox 🍞	Xerox®AltaLink®C8035						
Exercit Fleet Orchestrator Building for the memory Strategies are the "-Constraint" '-Constraint"	<u>.</u>	<u>_</u>	Prote Same Address Data				<u>.</u>	
Revenue de la constance de la	Search			Fleet Orchestrator				
Configuration Files Called / Im Type File Name/Version Status Instati ar File Instati ar File <td>Net Constraints Configuration Overview Configuration Report Configuration Report - Consent State - Consent State - Consent State - Consenting - Appe - Speciestly - Speciestly</td> <td colspan="6">Arco Configured Configured using 1 file.</td>	Net Constraints Configuration Overview Configuration Report Configuration Report - Consent State - Consent State - Consent State - Consenting - Appe - Speciestly - Speciestly	Arco Configured Configured using 1 file.						
Type File Name/Version Status Institut is File. Institut is File. Institut is File. Institution is consume typesate. Add on file. Add on file. Add on file. Constitution is Consume typesate. Add on file. Constitution is Consume typesate. Constitution is Constypesate. Constypesate. Constitu			Create / Install File					
Software Upgrade 101.001.008.27400 No software upgrade file installed. Add On the Add On the Software Upgrade file installed. Add On the Company of the Share Configuration Files Common Company of the Software Upgrade file installed.		Туре	File Name/Vers	Install a	File			
Share Configuration Files Create a File Create a Close or Add On fi Current decise settings.		Software Upgrade	101.001.008.274	00 No softw	No software upgrade file installed.			
current device settings.		Share Configuration Files Create a File Create a Call of the of create						
File Sharing allows connected devices to receive configuration files in order to apply and maintain device settings across multiple devices. Loann m Configure File Sharing		File Sharing allows connected devices to receive configuration files in order to apply and maintain device settings across multiple devices. Learn more Configure File Sharing with the start arguing and the start arguing the star						

7. Scroll to bottom of page and select **Create** button.

xerox 🍞	Xerox [®] AltaLink [®] C8035					🔒 admin-Logout			
nee.		R ive		Address Book		C Support			
Search	Download This File								
Floot Orchestrator Configuration Overview Description		Configuration Settings							
Configuration Report - Concentration - Logan Payments Accounting - Logan Payments Accounting - Second Payments Accounting			Select: All groups selected	Hide Setting	J S				
	Apps	Copy (Details Print Settings (I Server Fax (De) Workflow Scann Workflows (Det)) Details) tails) ning (<u>Details</u>) ails)	 D Card Copy (Details) Email (Details) Internet Fax (Details) Scan To Destination (Details) One-Touch (Details) 	<u>lls</u>)				
	General Settings	 Administration (Feature Installal Paper Managen Internationalizat Web Services () 	(D <u>etails)</u> tion nent (<u>Details)</u> tion <u>Details</u>)	 Security (<u>Details</u>) Job Management (<u>Details.</u>) Remote Services (<u>Details.</u>) Energy Saver 	u) u)				
	Connectivity	Connectivity Set	ttings <u>(Details</u>)						
	Access & Accounting	Accounting (Del Customer Logo	talls)	Authentication & Authoriza Configuration (Details) Device Address Book (Details)	tion alis)				
						Cancel Create			

Note: When the clone process completes, the following page appears.



8. Click the **cloning.dlm** hyperlink and save the .dlm file to your local hard drive.

Enabling Software Upgrades

- 1. At your computer, open a Web browser, then type the IP Address of your Xerox[®] AltaLink[®] printer using the format http://xxx.xxx.xxx.
- 2. From the top menu click **Properties**. If you receive a security warning, click to continue. If the printer is locked, a login screen appears.

Note: The default system administrator login user name is **admin** and the default password is either **1111** or the machine serial number (please note that the password is case sensitive).

- 3. Type the login details for the system administrator. The Configuration Overview page appears.
- 4. In the left-navigation pane, click **Security > Installation Policies**.
- 5. For Software Upgrade, enable the check box for Allow Software Upgrades, then scroll down and click Apply.
- 6. To install weblets, enable the check box for Allow Weblet Installation.

xerox 🄊	Xerox [®] AltaLinK [®] C8055				admin-Logout
Home Jobs	Print	Scan	Address Book	Properties	Support
Search	EE / Installation Pol	icies			*
Configuration Overview Description *General Setup E.Connectivity Login/ Permissions/ Accounting *Apps *Security Password Policies Installation Policies Installation Policies Secure pilot	Installation Backup & Restore Allow Backup Fil Cloning Only encrypted cl	Policies e Restore ione files can be inst	alled	•	Take me there
Authentication (Login) Flogg Flogg Flogg Flogg IP Fitching IP Fitching IP Face USB Port Security Imago Crewent Security PostScript © Passwords Hide User Name' Software Verification Test	Software Upgrade	Ipgrades			Take me there
	Remote Software Do	ownload	•		Take me there
	Weblet	tallation			Take me there
	Fleet Management T	ips			Apply

Installing the Software

If upgrading from any release 100, 101 or 103, 2 files will need to be loaded (1 at a time).

- 1. Return to the Software Upgrade page, from the left-navigation pane, click General Setup > Software Upgrade.
- 2. Install the pre-upgrade patch for your device:
 - a. Click **Create/Install File then click Install a File.** Make sure **Software Upgrade File** radio button is selected. Scroll to the bottom and **Select Chose File**. Locate the **453170v2.dlm** file that was saved to the directory on the desktop. Select the file, then click Open.
 - b. Click Install. A file submission message appears. Click OK.
 - c. Let the 1st software installation complete. Please note, if this file is not loaded prior to loading the software file the upgrade will fail.
- 3. After the first file is installed, return to Software Upgrade page, from the left-navigation pane, click **General Setup >** Software Upgrade.
 - a. Click **Create/Install File then click Install a File.** Make sure **Software Upgrade File** radio button is selected. Scroll to the bottom and **Select Chose File**. Locate the **AltaLink_X80xx_system-sw# ENG_MOD.DLM** file saved to the directory on the desktop.
 - b. Select the AltaLink_X80xx_system-sw# ENG_MOD.DLM file, then click Open.
 - c. Click Install. A file submission message appears. Click OK.
 - d. Let the 2nd software installation complete. Please note, if this file is not loaded prior to loading the software file the upgrade will fail.

4. If the upgrade is successful, continue with instructions. If the upgrade fails and a failed upgrade report is generated, navigate to the Appendix for instructions on how to recover.

Reapplying the Clone File (Optional)

- 1. At your computer, open a Web browser, then type the IP Address of your Xerox[®] AltaLink[®] printer using the format http://xxx.xxx.xxx.
- 2. From the top menu click **Properties**. If you receive a security warning, click to continue. If the printer is locked, a login screen appears.

Note: The default system administrator login user name is **admin** and the default password is either **1111** or the machine serial number (please note that the password is case sensitive).

- 3. Type the login details for the system administrator. The Configuration Overview page appears.
- 4. In the left-navigation pane, click General Setup > Cloning.
- 5. Select Install file



6. Select Clone file



7. Select Choose file and select the previously saved file from your hard drive

xerox ()	Xerox® AltaLink® C8035						
<u>e</u>		<u>_</u>	a	The second secon	2 Address Ecck	₽espectars	<u>.</u>
Search	Instal Configuration File						
RecEntered to the second secon	Software Lippacke File Image states of the dense. - Great for classing device reframements, capabilities, and to address security concerns. - Great for classing device reframements, capabilities, and to address security concerns. - Great for classing device reframements, capabilities, and to address security concerns. - Great for classing device reframements, capabilities, and to address security concerns. - Great for classing device reframe of great set in the state regreate the set. - Great for classing device reframe device. - Great for classing for an order device. without coverviting entiting ages. - Address for a braining "Great set brains of the lower set brain device.						
	Details						
	Last Attempt LDRPC800039v1.dlm						
	Last Attempt Status -						
	Installation Policy Allowed (Coty encrypted clone files can be installed). Print Submission: Allowed						
	Additional Options						
	File To Install Choose File No file choose						
	Close Indat						

8. Select Install



9. Click OK.



Note: The Embedded Web Server is unavailable during cloning installation. When the cloning process completes, the device restarts automatically.



10. To verify that the clone file installed successfully, refresh the browser.



Congratulations! You have upgraded the software on your Xerox® AltaLink® device for Xerox® ConnectKey® Technology successfully!

Appendix: Failed Software Upgrade

This section details the process to follow if the software upgrade fails. If any of the following Printed Error Reports are generated, proceed to the instructions below.

- Printed Error Report showing "Launch Release Missing"
- Printed Error Report showing "Launch Release Corrupted"
- Printed Error Report showing "Launch Release Version Mismatch"
- 1. The Launch DLM Recovery Patch (LDRP) needs to be loaded on the device. The recovery patch is speed specific so use the following table to determine which patch to load:

Device	Recovery Patch	Link
C8030/35	LDRPC803035v1.dlm	LDRPC803035v1
C8045/55	LDRPC804555v1.dlm	LDRPC804555v1
C8070	LDRPC8070v1.dlm	LDRPC8070v1
B8045/55/65/75/90	LDRPB804590v1.dlm	LDRPB804590v1

- 2. Follow the appropriate Link above. Click Accept to download the zip file to the desktop.
- 3. Double-Click the downloaded file and unzip to the desktop.
- 4. The identified patch needs to be loaded via EWS.
 - a. At your computer, open a Web browser, then type the IP Address of your Xerox[®] AltaLink[®] printer using the format http://xxx.xxx.xxx.
 - b. From the top menu click **Properties**. If you receive a security warning, click to continue. If the printer is locked, a login screen appears.
 - c. Note: The default system administrator login user name is **admin** and the default password is either **1111** or the machine serial number (please note that the password is case sensitive).
 - d. Type the login details for the system administrator. The Configuration Overview page appears.
 - e. From the left-navigation pane, click **General Setup > Software Upgrade**.
 - Click **Browse**, then locate the LDRPx80xxV1.dlm file that was unzipped to the desktop.
 - Select the located file, then click **Open.**
 - Click Install Software. A file submission message appears. Click OK.

Note: While the file is transferring, do not navigate from the transfer page until the file completes.

- 5. Once completed, reboot the device.
- 6. Try Software Upgrade again. The pre-install patch 453170v2.dlm does not need to be loaded again.

If instead during the upgrade the EWS screen provided an error notification saying the software file in invalid, please check the following:

- 1. Print a Configuration Sheet and check the Device Software.
- Next check the Network Controller software version under Software Version. If the listed version for the Network Controller is not appended with 453170v2.dlm, the required patch was not loaded. Please navigate to Section "Installing Software" and follow the upgrade procedure under the section <u>If upgrading from a release that begins with</u> <u>100.xxx.xxx.xxxxx</u>: