

XEROX®

XEROX 6204
Wide Format Copier/Printer
Version 1.1.03 Release Notes

February, 2006

Table of Contents

1	Trademark Acknowledgements	3
2	Release Content	4
3	Updates in this release	5
3.1	New Release Features	5
3.2	Customer Issues Resolved	5
4	Installation	6
4.1	Embedded Controller firmware	6
4.2	Windows Driver Installation	6
4.3	PostScript Driver Installation	6
4.4	BT-PlotAssistant Installation	6
4.5	Wide Format Scan Service Installation	6
5	Known Issues	7

1 Trademark Acknowledgements

XEROX®, The Document Company, and the identifying product names and numbers herein are trademarks of XEROX CORPORATION. All other product names mentioned herein are trademarks of their respective companies. All rights reserved.

Windows, Windows® 2000, Windows® XP Pro are registered trademarks of Microsoft Corporation.

AutoCAD is a registered trademark of AutoDesk, Inc.

HDI is an acronym for Heidi Device Interface. Heidi is a registered trademark of AutoDesk, Inc.

WinZip is a registered trademark of Nico Mak Computing, Inc.

2 Release Content

The following components are new in this release:

- Xerox 6204 embedded controller version 1.1.03
- Windows 2000/XP GDI driver v3.2.0 (English)
- BT-PlotAssistant version 3.4.01(English, French, Italian, German, Spanish and Portuguese)
- Wide Format Scan Service version 1.0.2.1 (English)
- Network TWAIN driver version 1.0.2.1 (English)
- PostScript driver version 1.0.0 (English) & version 0.0.1 (French, Italian, German, Spanish and Portuguese)
- HDI drivers for AutoCAD 2002, 2004/2005 and 2006 v3.2.0 (English)

3 Updates in this release

3.1 New Release Features

This is the initial launch release for the Xerox 6204 Wide Format.

3.2 Customer Issues Resolved

None.

4 Installation

4.1 Embedded Controller firmware

This SW can only be installed by a service technician.

4.2 Windows Driver Installation

For Windows 2000 and XP, please refer to chapter 1 of the Xerox 6030/6050/6204 Wide Format Windows Driver User Guide for detailed installation instructions. These instructions are on the documentation CD that arrived with the product or available on www.Xerox.com under Support & Drivers.

4.3 PostScript Driver Installation

Refer to the Xerox 6204 PostScript Driver Installation Guide for detailed installation instructions. These instructions are on the documentation CD that arrived with the product or available on www.Xerox.com under Support & Drivers.

4.4 BT-PlotAssistant Installation

Refer to chapter 2 of the Xerox 6030/6050/6204 Wide Format BT Plot Assistant User Guide for detailed installation instructions. These instructions are on the documentation CD that arrived with the product or available on www.Xerox.com under Support & Drivers.

4.5 Wide Format Scan Service Installation

Refer to chapter 1 of the Xerox 6204 Wide Format Scan Service User Guide for detailed installation instructions. These instructions are on the documentation CD that arrived with the product or available on www.Xerox.com under Support & Drivers.

5 Known Issues

Online Help availability:

The online help features of the clients and drivers are not yet available.

Printing with the PostScript Driver:

- If a media source (example: Roll 1) is specified, the auto rotate and auto scaling features are disabled.
- Automatic roll switching is not enabled.
- PostScript Custom Page Sizes must be defined as Short Edge First.

Print Services on Web:

Internet Explorer version 6.0 is required. Print Service on Web pages may not be displayed as expected with other internet browsers.

Prepared by:
Xerox Corporation
800 Phillips Road
Building 139-64A
Webster, New York 14580-9791
USA

©XEROX Inc. 2006. All rights reserved.

Printed in the United States of America

02/2006