

# Fiery Patch Release Notes

## General information

Defect ID number	1-19SQ4A
Product name	Fiery Network Controller for WorkCentre 7500 Series v1.0
Release date	1/11/2011

## Files included in this release

File name	File size
1-19SQ4A	21 KB

## Issue(s) addressed with this release

Receive error when trying to enable logging on the Fiery Controller. Logging is for troubleshooting purposes only.

## Steps to reproduce the Issue(s)

When enabling logging on the Fiery Controller through http, it doesn't enable the log, rather gives an error.

Error:

**Warning:** fopen(../persist/log.enable) [function.fopen]: failed to open stream: Permission denied in /scsi0/httpd/htdocs/lexlog.php on line 23 can't open file"

---

## Before installing "1-19SQ4A.ps"

- 1 This patch is exclusive, it must be installed by itself, and the server must be rebooted or restarted once. After that, other patches can be applied to the server.
- 2 Prerequisites listed below must be installed before applying "1-19SQ4A.ps" patch:
  - 1-18GCJ1Note: Print Configuration Sheet to check if patch has been installed.  
Note: If patch is not installed it can be found at <http://www.support.xerox.com/> or Fiery System Updates.
- 3 If known issues are listed below, read before installing 1-19SQ4A.ps patch:
  - None.





- 4 Do NOT install any of the following patch(es) after installing the **1-19SQ4A.ps** patch. If you are required to install any of the patch(es) below, do so before installing the **1-19SQ4A.ps** patch:

- None.

---

## Patch installation instruction

- 1 Make sure that the Fiery is Idle.
- 2 Import the patch file **1-19SQ4A.ps** using Command Workstation to the Direct queue. Or use Fiery WebTools by going to the Docs tab to Import to the Direct queue.
- 3 You must wait until the file finishes processing. Please refer to CWS or WebTools to ensure the patch file is completely processed.
- 4 From Command WorkStation, choose Server → Reboot Server, or from the WC75xx UI select the Fiery Button → Restart Server → login as operator → Reboot System.
- 5 Wait until the Fiery comes to Idle - If startup page is enabled on the Fiery Controller, the startup page will print.
- 6 Print a configuration page to verify that the **Update Info** section contains the Patch ID: **1-19SQ4A**.