



# Fiery Patch Release Notes

## General information

Defect ID number	FIT212119
Product name	Xerox EX 570 Print Server Powered by Fiery
Release date	5 May 2014

## Files included in this release

File name	File size	Checksum
EX570_v1.0_SP3.exe	9377240 bytes	1132916627

## Issue(s) addressed with this release

- **FIT212119: Service pack 3 for Xerox EX 570**
- FIT197739: Increase tab imageable area (A4/Letter) for improved Job Master support.
- FIT199332: Cannot set Fiery EX 570 to work on network switch mode.
- FIT203319: Incompatibility issue between the Configure application and JRE 1.7u51.
- FIT205303: Need 'Print on any side' option for booklet covers

## IMPORTANT

### Before installing EX570\_v1.0\_SP3.exe

- 1 Known issues listed below, read before installing **EX570\_v1.0\_SP3.exe** patch:
  - None.
- 2 The following prerequisite(s) must be installed in the order specified before applying the **EX570\_v1.0\_SP3.exe** patch:
  - SP1
  - SP2

#### Disclaimer

This hardware, software/patches, or technology may contain cryptographic functions as defined in Article 8 (ix) (h) because the cryptographic capability is not user-accessible, and are designed to have only one or more of the following cryptographic functionality(ies):

- 1 Functionality to execute copy-protected programs
- 2 Functionality to access to digital contents stored on copy-protected read-only media
- 3 Functionality to access to encrypted and memorized digital contents on a medium that will be sold to the public with the same content
- 4 Functionality for copying control of copyright protected audio/video data
- 5 Functionality to encrypt and/or decrypt to protect libraries, design attributes, or associated data for the design of semiconductor devices or integrated circuits



- 3 Do **NOT** install any of the following patch(es) after installing the **EX570\_v1.0\_SP3.exe** patch. If you must install any of the patch(es) below, do so before installing the **EX570\_v1.0\_SP3.exe** patch:
  - None.
- 4 This patch is exclusive, it must be installed by itself, and the server must be rebooted or restarted once. After that, other patches can be applied to the server.

### Patch installation instructions

- 1 Make sure that the Fiery printer controller reaches Idle.
- 2 Execute **EX570\_v1.0\_SP3.exe** and follow the instructions in the Fiery Patch Downloader.
- 3 Notes about the Fiery Patch Downloader
  - a. Logon must be admin. This is fixed and cannot be modified.
  - b. Password is the Fiery administrator login password.
  - c. Hostname can be the IP address or the Fiery server name.
- 4 After the patch is downloaded, and when prompted by the Fiery Patch Downloader, choose Reboot. *(If you choose to Restart later, make sure you manually reboot the server for the changes to take effect)*
- 5 Wait until the Fiery controller reaches Idle and print the Configuration page.
- 6 Verify that the **System Updates Log** section contains the patch number **SP3**.

#### Disclaimer

This hardware, software/patches, or technology may contain cryptographic functions as defined in Article 8 (ix) (h) because the cryptographic capability is not user-accessible, and are designed to have only one or more of the following cryptographic functionality(ies):

- 1 Functionality to execute copy-protected programs
- 2 Functionality to access to digital contents stored on copy-protected read-only media
- 3 Functionality to access to encrypted and memorized digital contents on a medium that will be sold to the public with the same content
- 4 Functionality for copying control of copyright protected audio/video data
- 5 Functionality to encrypt and/or decrypt to protect libraries, design attributes, or associated data for the design of semiconductor devices or integrated circuits