



Fiery Software Release Notes

General information

Defect ID number	1-1EC2TT
Product name	Fiery Color Server for Xerox DocuColor 242/252/260
Release date	15 March 2012

Files included in this release

File name	File size	Checksum
XC_EX260_v2_0R_OSX_Rel1.0.dmg	1.39 MB	955759868

Issue addressed with this release

- Updated drivers for Mac OS X 10.7 compatibility.

Steps to reproduce the Issue(s)

- 1 Attempt to install Fiery Network Controller for Fiery Color Server for Xerox DocuColor 242/252/260 driver on Mac OS X 10.7.

<Result> Unable to install Fiery Network Controller for Fiery Color Server for Xerox DocuColor 242/252/260 driver on Mac OS X 10.7.



CAUTION

Before installing the drivers

- 1 Addendum contains the crucial information regarding this release. Please make sure to review it before proceeding with the testing.

Mac driver installation instructions

OS10.7

- 1 Decompress XC_EX260_v2_0R_OSX_Rel1.0.dmg file on the desktop.
- 2 Select User Software folder and double click on the Fiery Driver installer.
- 3 Follow the instructions in the wizard and complete the installation.
- 4 Navigate through System Preference and install the printer.



Release Notes for the Fiery print driver 2.9.1 for Mac OS X Lion

The Mac OS X Lion driver installer package is distributed as a disk image (DMG) file, and is named **XC_EX260_v2_0R_OSX_Rel1.0.dmg**. Once the DMG file is downloaded and the disk image is mounted on the computer, the User Software package contains the following:

Fiery Driver Installer – directly installs the printer driver.

Fiery Software Uninstaller – uninstalls printer driver software. This was previously available with the Utilities and is now available as a part of the driver package.

OS versions supported: These printer drivers are supported on Mac OS X Lion.

Driver UI modifications:

This driver version provides a Mac OS X Lion compliant installer and is a PPD-only solution to enable printing from the driver with product specific options, but without customized user interface controls. Because the older Fiery Driver 2.9 plugin based architecture is not supported by Mac OS X Lion, the following plugins which included custom user interface controls are not included in this driver:

1. Printer Info plugin (PINFO)
2. Colorwise plugin (CW)
3. ImageShift plugin (IS)
4. Fiery Job Notes (FJN)
5. Center Margine (CM)

As a result, the following customized user interfaces will not be displayed in this driver:

1. Bidirectional information, including color profile and FreeForm master names, and consumable information
2. Image Shift
3. Job notes
4. Mixed Media
5. Specific range controls, such as Gutter, Scale, Center Margin and Pages Per Record.