

## *Corel Draw Landscape EX12 v2.0*

### **Problems Addressed:**

Unable to print Landscape documents from Corel Draw on Windows 2000 client. (Xerox SPAR # 001723586, 941697904, EFI Bug # 1-8BIIH)

### **Solution:**

This driver update consists of the following (19) files for Fiery EX12 v2.0 for Windows 2000 client only:

File Name	File Size	File Name	File Size
EF3X1011.bxe	100 KB	EF3X1011.psr	46.7 KB
EF3X1011.chm	115 KB	EF3X1011.uim	1.77 MB
EF3X1011.dll	80 KB	EF3X102E.cat	12.3 KB
EF3X1011.ext	520 KB	ehm10.dll	412 KB
EF3X1011.fin	1.12 MB	ehmbrg.dll	292 KB
EF3X1011.ini	74 B	ehmcore.dll	96 KB
EF3X1011.lan	1.78 MB	ehmecol.dll	152 KB
EF3X1011.oem	252 KB	ehmefi.dll	476 KB
EF3X1011.pge	4.14 KB	oemsetup.inf	2.08 KB
EF3X1011.ppd	127 KB		

### **Client Installation Instructions:**

It is necessary for the client system to delete the previously installed driver, and install new driver.

#### **Deleting Existing Driver Files:**

1. Go to *Start/ Settings/ Printers*.
2. Select the Fiery EX12 2.0 printer.
3. Go to *File / Delete*.
4. Go to *Start/ Find/ Files & Folders...*
5. Search for EF3X1011.\*.
6. Delete all files. They will be located in  
*C:\Winnt\system32\spool\drivers\w32x86\2* or *C:\Winnt\system32\spool\drivers\w32x86\3*
4. Empty Recycle Bin
5. Restart Computer

*Note:* If an error is received when deleting a file, reboot the computer and delete the files.

#### **Installing Driver:**

1. Go to *Start/ Settings/ Printers*.
2. Double click on *Add Printer*.
3. Follow the on screen instructions.

#### **Important Note:**

These drivers are not Microsoft WHQL compliant, and the Add Printer setup procedure will display a message concerning this. Please ignore the message and select "Yes" to successfully finish the installation.