

March 2009

Dear Xerox DocuColor 240/250 Integrated Fiery Color Server customer:

Your DocuColor 240/250 Integrated Fiery Color Server system can now be upgraded with the 1-ZIFBX software kit.

**NOTE:** *This patch may be installed by the customer following the enclosed Installation Instructions.*

**NOTE:** *Your system must be at version 1.2 prior to installing this software.*

We tested this updated software release specifically for the System Problem Action Requests (SPARs) noted below. If your SPAR number is not listed, we are providing you this software either because you reported a problem that resembles one of the listed fixes or because our testing has shown that this software should resolve your problem. If this software does not resolve your problem, please contact the hotline and provide a detailed job scenario and sample job(s) for further investigation, testing, and resolution.

This software kit contains fixes for the following SPARs:

| SPAR kit version | SPAR #       | Description  |
|------------------|--------------|--|
| 1-ZIFBX          | 1. 330419712 | Fiery v1.2 unable to match color that worked with v1.1 |

**NOTE:** *Not all child SPARs will be listed in this letter.*

**Prerequisites:** The following patches must be loaded prior to installing this patch. They are available via System Updates or [www.xerox.com](http://www.xerox.com).

- 1-XVE1A
- 1-YNN0J
- 1-ZZJED
- 1-116UK9